

Ships detained in Hong Kong by PSC Section in May 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	6604482	JI MEI	Panama	1965	9878	Passenger ship	Polski Rejestr Statkow (Polish Register of Shipping)	Polski Rejestr Statkow (Polish Register of Shipping); Lloyd's Register; China Classification Society	Island Ship Management Ltd	22/05/13	---	RADIO COMMUNICATIONS: satellite EPIRB 406MHz/1.6GHz/two EPIRBs not installed correctly; LIFE SAVING APPLIANCES: stowage and provision of liferafts/liferafts stowage, some weak links missing and some weak links not properly secured; POLLUTION PREVENTION - MARPOL ANNEX I/oil and oily mixtures from machinery spaces: generator room tank top, excessive oily water accumulated, generator case and floor oily and dirty, M/E room tanktop, excessive oily water accumulated, air condition room tanktop, excessive oily water accumulated, stern shaft room tanktop, excessive oily water accumulated; ISM/maintenance of the ship and equipment/referring to deficiencies item 1-53 of PSC inspection report, shipboard maintenance was not properly carried out, safety management system was not properly implemented; PROPULSION AND AUXILIARY MACHINERY: other (machinery)/MGO filter nearby no. 1 generator leaked and oil accumulated in the saveall; FIRE SAFETY: ventilation/steering gear room s'side ventilation cannot be closed; SAFETY OF NAVIGATION: voyage or passage plan/voyage to and from Xiamen not made berth to berth; LIFE SAVING APPLIANCES/maintenance of life saving appliances/LSA weekly inspection not including lifeboats
2	9092331	DONG PENG	Panama	1993	1064	General cargo/ multipurpose	Isthmus Bureau of Shipping, S.A.	Isthmus Bureau of Shipping, S.A.	East Harbour Navigation Co Ltd	31/05/13	03/06/13	POLLUTION PREVENTION - MARPOL ANNEX V: garbage management plan/garbage management plan not meet MARPOL requirement; WATER/WEATHERTIGHT CONDITIONS - COVERS(HATCHWAY-, PORTABLE-, TARPULINS, ETC.): numerous hatch cover cleat missed/damaged, no. 2 cargo hold starboard side holed; FIRE SAFETY: ready availability of fire fighting equipment/4 x fire hoses found leakage during test; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/oily water accumulated in e/r tank top about 15cm; SAFETY OF NAVIGATION: charts/BA chart 937 old edition; BA chart 3026 not updated

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.