

Ships detained in Hong Kong by PSC Section in November 2002

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Place of Detention	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8100820	UNI-OCEAN	Panama	1981	18337	container ship	American Bureau of Shipping	Evergreen Marine Corporation (Taiwan)	Hong Kong, China	04/11/02	05/11/02	FIRE FIGHTING MEASURES - defective fire nozzles, hoses and hydrants LIFESAVING APPLIANCES - Std. lifeboat lifting frame bolts seriously corroded, fire extinguisher missing, no lagging on exhaust pipe, landing platform detached, engine casing holed
2	8105478	NOOR	Qatar	1981	4644	oil tanker	International Naval Surveys Bureau	H.B.M. Shipping	Hong Kong, China	06/11/02		STABILITY, STRUCTURE AND RELATED EQUIPMENT - steering gear LIFESAVING APPLIANCE - lifeboats, lifebuoys, liferaft expired MARPOL - OWS, bilge full of oily water RADIOCOMMUNICATION - EPIRB, VHF radio, navetext not working, MF/HF radio SAFETY OF NAVIGATION - radar, revolution counter, engine telegraph, echo sounder not working, charts, tide tables, sailing directions, radio signals, lights, shapes and sound signals missing ALARM SIGNALS - fire alarm SOLAS RELATED DEFICIENCIES - operation of GMDSS equipment, communication between steering gear flat and ER or bridge
3	8902125	PANAMA	Liberia	1989	18000	container ship	Germanischer Lloyd	F.L.S.mbH + CO KG R.F. LAEISZ Gmbh	Hong Kong, China	21/11/02	22/11/02	ISM RELATED DEFICIENCIES - emergency preparedness. LIFESAVING APPLIANCES - line throwing appliance
4	8403064	WEI LI NO. 2	Taiwan, China	1984	2847	general cargo/multi-purpose ship	China Corporation Register of Shipping	Yeng Fu Marine Transportation Co.	Hong Kong, China	21/11/02	22/11/02	FIRE FIGHTING MEASURES - CO2 room ceiling and bulkhead A-60 insulation material more than 50% detached, emergency fire pump could only run for five minutes and stop by itself
5	8910419	KATSURAGI	Panama	1989	50437	container ship	Nippon Kaiji Kyokai	NYK Shipmanagement Pte LTD	Hong Kong, China	25/11/02	25/11/02	SOLAS RELEATED OPERATIONAL DEFICIENCIES - abandon ship drills RADIOCOMMUNICATIONS - satellite EPIRB 406MHz/1.6GHz, hydrostatic release on EPIRB expired
6	7354541	SEA FAN	Liberia	1973	16078	bulk carrier	Nippon Kaiji Kyokai	LIHAI INTERNATIONAL SHIPPING	Hong Kong, China	25/11/02	29/11/02	SAFETY OF NAVIGATION - gyro compass malfunction ISM RELATED DEFICIENCIES - programmes for emergency drills and exercises not available LIFESAVING APPLIANCES - #2 lifeboat sail mast foundation rotten and detached, #1 lifeboat transmission not working FIRE FIGHTING MEASURES - emergency fire pump not working
7	9220304	SINAR BANGKA	Panama	1999	12563	container ship	Bureau Veritas	MEI KAIUN CO. LTD.	Hong Kong, China	25/11/02	25/11/02	ISM RELATED DEFICIENCIES - master's responsibility and authority, maintenance of ship and equipment
8	9101481	COURIER	Antigua and Barbuda	1994	14969	container ship	Germanischer Lloyd	Reederer Gebr. Winter GMBH & Co. KG	Hong Kong, China	26/11/02	27/11/02	RADIOCOMMUNICATIONS - no records of weekly DSC test call to coastal station FIRE FIGHTING MEASURES - emergency fire pump is not readily available for operation
9	8518778	ORIENTAL PROFIT	Panama	1986	2838	general cargo/multi-purpose ship	China Corporation Register of Shipping	Oriental Profit Navigation S.A.	Hong Kong, China	28/11/02	29/11/02	SOLAS RELEATED OPERATIONAL DEFICIENCIES - abandon ship drills LIFESAVING APPLIANCES - lifeboats engine exhaust pipe, support frame bolts and nuts, sailmast support

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.