

## Ships detained in Hong Kong by PSC Section in December 2002

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7507241	KAMNIK	Singapore	1976	12117	general cargo/multi-purpose ship	Lloyd's Register of Shipping	Splsna Plovga Ltd.	02/12/02	03/12/02	RADIOCOMMUNICATIONS Satellite EPIRB 406 MHz/1.6 GHz - EPIRB self-test failed for more than six tests.
2	8601616	EASTERN CHALLENGER	Korea, Republic of	1985	3948	general cargo/multi-purpose ship	Korean Register of Shipping	Daebo Shipping Co. Ltd.	03/12/02	04/12/02	LIFESAVING APPLIANCES - Lifeboats , engine test failure and engine coupling serious wasted.
3	9143348	UNI-AHEAD	Panama	1997	14796	container ship	Nippon Kaiji Kyokai	Evergreen Marine Corporation (Taiwan) Ltd.	04/12/02	05/12/02	LIFESAVING APPLIANCES - Launching arrangements for rescue & life boats was not readily for operation; steering cannot be operated. CERTIFICATION AND WATCHKEEPING FOR SEAFARERS - C/O & 3/O did not have GMDSS flag endorsement; minimum safe manning document was not compiled
4	8113865	UNI-OBTAIN	Panama	1982	19698	container ship	American Bureau of Shipping	Evergreen Marine Corporation (Taiwan) Ltd.	04/12/02	05/12/02	SAFETY OF NAVIGATION - Charts were not updated. FIRE FIGHTING MEASURES - Fire hose seals were damaged. RADIOCOMMUNICATIONS - Reserve batteries eletrolytes density very low. STABILITY, STRUCTURE AND RELATED EQUIPMENT - Emergency lights were very dim; crew did not know where to switch on emergency lights on bridge deck. FIRE FIGHTING MEASURES - CO2 control pipe was broken. FIRE FIGHTING MEASURES - Seals for all fire hose nozzle was damaged.
5	8317344	SHINE HO	Taiwan, China	1984	10944	Other types of ship	China Corporation Register of	Ta Ho Maritime Corporation	05/12/02	05/12/02	MARPOL - ANNEX 1 - Oily water seperator shell plating found locally holed.
6	8323159	WORLDDLINE 3	Saint Vincent and the Grenadines	1983	4908	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	World Shine Shipping Ltd.	05/12/02	09/12/02	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS - C/E did not have flag endorsement. ISM RELATED DEFICIENCIES - Emergency drill was not carried out. RADIOCOMMUNICATIONS - DSC routine tests were not carried out. FIRE FIGHTING MEASURE - Fire hose was seriously leaked and no spare on board.
7	9260976	CRYSTAL WAY	Panama	2001	9004	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Eagle Maritime Co. Ltd.	09/12/02	10/12/02	SOLAS RELATED OPERATIONAL DEFICIENCIES - Stbd lifeboat was not lowered in water more than 3 months. ISM RELATED DEFICIENCIES - Identified emergency drills was not carried out as per plan, SMS did not provide adequate measure to ensure emergency preparedness on board.
8	9175597	CONVENIENCE CONTAINER	Singapore	1998	17652	container ship	American Bureau of Shipping	Kieng Hung Shipping Co.	10/12/02	11/12/02	ISM RELATED DEFICIENCIES - No maintenance plan for navigational equipment. RADIO COMMUNICATIONS - Radio equipment weekly tests were not carried out.
9	7703546	DINA	Liberia	1978	12929	general cargo/multi-purpose ship	Lloyd's Register of Shipping	Eastmark Associates Inc.	10/12/02	13/12/02	ISM RELATED DEFICIENCIES - Type of vessel on SMC deviated from Flag Register, no internal audit record was found on board. LIFESAVING APPLIANCES - 4 line throwing appliances expired in 10/99.
10	8322844	SUPERIOR	Panama	1984	5479	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Sekwang Shipping Co. Ltd.	10/12/02	13/12/02	LOAD LINES - Hatch cover locking devices were inoperable. LIFESAVING APPLIANCES - Stbd lifeboat engine exhaust pipe damaged, port lifebaot sail mast wasted. FIRE FIGHTING MEASURES - Emergency fire pump fuel pipe leaked. SOLAS RELATED OPERATIONAL DEFICIENCIES - Port lifeboat was not lowered to water more than 3 months. ISM RELATED DEFICIENCIES - SMS did not provide adequate measure to ensure emergency preparedness on board, major equipment & machinery was not maintained as per relevant rules and regulations.
11	7512698	MULTI EASY	Cambodia	1975	9744	Bulk carrier	Other	Rizhao Jinyang Shipping Co. Ltd.	12/12/02	18/12/02	RADIOCOMMUNICATIONS - MF/HF equipment was defective, reserve power was not functioning. LIFESAVING APPLIANCES - Port lifeboat was damaged. SAFETY OF NAVIGATION - Charts for intended voyage was not updated. FIRE FIGHTING MEASURES - Emergency fire was not operable, CO2 lines system for cargo hold was broken. ISM RELATED DEFICIENCIES - Major equipment & machinery was not maintained as per relevant rules and regulations.
12	8972302	RICH LAND 6	Cambodia	1991	1589	general cargo/multi-purpose ship	Cambodia Shipping Corporation	Zhoushan Putuo Fishery (Group) Shipping Co. Ltd.	12/12/02	20/12/02	RADIOCOMMUNICATIONS - Reserve power was not fuctioning, batteries in bad conditions, weekly test was not carried out. LIFESAVING APPLIANCES - Rescue boat engine was not functioning. ALARM SIGNALS - Fire alarm had faulty circuit. FIRE FIGHTING MEASURES - Skylight seals were damaged, short of BA air bottles. LOAD LINES - Seals for watertight doors were damaged. STABILITY, STRUCTURE AND RELATED EQUIPMENT - Emregency lights were not working. SAFETY OF NAVIGATION - Charts were not updated and sextant not found. ISM RELATED DEFICIENCIES - No drill plan and familiarization record for master was found.

13	8403325	STARLITE ELISA	Panama	1983	3150	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	WK Marine Services Co. Ltd.	12/12/02	14/12/02	SOLAS RELATED OPERATIONAL DEFICIENCIES - Port & Stbd lifeboats wer not lowered in water more than 3 months. ISM RELATED DEFICIENCIES - No emergency plan found on board. SAFETY OF NAVIGATION - Charts were not updated. LIFESAVING APPLIANCES - Stbd lifeboat engine defective. FIRE FIGHTING MEASURES - fire line isolating valves found stucked, emergency fire pump could not started.
14	8216801	GIGA WAVE	Malaysia	1983	7551	Ro-ro cargo	Nippon Kaiji Kyokai	Tera Marine SDN BHD	18/12/02	18/12/02	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS - Master & C/E flag endorsement expired. ISM RELATED DEFICIENCIES - Emergency drill was not carried out and drill plan was found. LIFESAVING APPLIANCES - Port lifeboat grab rails were heavily corroded.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.