

## Ships detained in Hong Kong by PSC Section in February 2004

| No | IMO Number | Ship Name     | Flag     | YOB  | GRT   | Ship Type                        | Class                                  | Ship Company                              | Date of Detention | Date of Release | Nature of Deficiencies (responsible RO, if any)  |
|----|------------|---------------|----------|------|-------|----------------------------------|--|---|-------------------|-----------------|--|
| 1  | 8713299    | GREAT MARINER | Cambodia | 1987 | 1894  | general cargo/multi-purpose ship | Global Marine Bureau Inc.              | Ever Maru Shipping S.A.                   | 02/02/04          | 02/02/04        | FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, ventilation, fire-dampers, valves, quick closing devices, means of control, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, LOAD LINES: ventilators, air pipes, casings   |
| 2  | 8808135    | SILVER ACE    | Belize   | 1988 | 1451  | general cargo/multi-purpose ship | Isthmus Bureau of Shipping             | Dalian Chun An Ship Management Co., Ltd.  | 02/02/04          | 06/02/04        | CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, RADIOCOMMUNICATIONS: reserve source of energy, LIFESAVING APPLIANCES: lifeboat inventory  |
| 3  | 9130523    | EVER APEX     | Panama   | 1996 | 14807 | container ship                   | Nippon Kaiji Kyokai                    | Evergreen Marine Corporation (Taiwan) Ltd | 03/02/04          | 03/02/04        | SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, RADIOCOMMUNICATIONS: VHF, EPIRB, FIRE FIGHTING MEASURES: fire fighting equipment and appliances   |
| 4  | 8912273    | ISABELA       | Panama   | 1989 | 5898  | general cargo/multi-purpose ship | Nippon Kaiji Kyokai                    | Bright Knight Management Incorporated     | 04/02/04          | 07/02/04        | ISM RELATED DEFICIENCIES: resources and personnel, LIFESAVING APPLIANCES: lifeboat inventory, Stbd. lifeboat engine failed starting, lifeboat inventory, lifeboat searchlight found not working, FIRE FIGHTING MEASURES: personal equipment, one EEBD in E/R found completely discharged, RADIOCOMMUNICATIONS: reserve source of energy, batteries for essential radio equipment found hydrometer testing passed red mark  |
| 5  | 7627302    | SAN WAI       | Panama   | 1976 | 5985  | general cargo/multi-purpose ship | China Corporation Register of Shipping | Unison Marine Corporation, Taiwan         | 05/02/04          | 06/02/04        | RADIOCOMMUNICATIONS: maintenance/duplication of equipment, MF/HF DSC radio not working, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, GMDSS officers not familiar with function test of all GMDSS equipt. & cancellation procedures of false GMDSS distress alert, manuals, instructions, etc., launching instruction not posted under emergency lighting, LOAD LINES: ventilators, air pipes, casings, funnel casing at nav. deck holed, ventilators, air pipes, casings, hand wheel for galley vent seized and electric cable conduit corroded & holed, manholes/flush scuttles, cargo hold manhatches in deck house bet. no. 2 & 3 holds without cleats to maintain weathertightness, ventilators, air pipes, casings, deckhouse vent casing bet. hold 2 & 3 holed, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, 2 emergency lighting P&S boat deck not working, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, poop deck aft hose box blocked by mooring ropes, readily availability of fire fighting equipment, operation procedures of CO <sub>2</sub> remote release device not familiar to responsible crew; glass inspection holes blanked, readily availability of fire fighting equipment, jet & spray nozzles for fire hose not properly located in E/R, WORKING SPACES (ILO 147): other (working spaces), acetylene/oxygen cylinders stored in crew accommodation, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, E/R bilge full of oily water, ISM RELATED DEFICIENCIES: resources and personnel, deficient item 9, 11 & 20, maintenance of the ship and equipment, deficient item 2, 6, 10, 12, 14, 15, 16, 18 & 19 |

|   |         |             |          |      |       |                                  |   |                                     |          |          |   |
|---|---------|-------------|----------|------|-------|----------------------------------|---|-------------------------------------|----------|----------|---|
| 6 | 8607438 | BUDI WAJA   | Bahamas  | 1986 | 18353 | container ship                   | Germanischer Lloyd                          | V Ships Limited                     | 05/02/04 | 05/02/04 | MARPOL - ANNEX I: oil filtering equipment, PROPULSION AND AUXILIARY MACHINERY: other (machinery), main air compressor discharge line (hp) relief valve lifting spindle was blocked by bolting arrangement   |
| 7 | 7617565 | SLAVAL-1    | Cambodia | 1976 | 4003  | general cargo/multi-purpose ship | Global Marine Bureau                        | Ka-trans Navigation Limited Ukraine | 08/02/04 | 14/02/04 | CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, master without Cambodia licence, SAFETY OF NAVIGATION: nautical publications, nautical publication for intended voyage generally missing, e.g. NP283(3)2, 282, 284, 286 (i.e. list of radio signal) & list of lights, RADIOCOMMUNICATIONS: maintenance/duplication of equipment, GMDSS officers fail to demonstrated tests to various GMDSS equipt function properly, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, procedures to cancel GMDSS false distress alert not familiar by GMDSS officers, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, CO <sub>2</sub> alarm switch for CO <sub>2</sub> remote control/release box not function, readily availability of fire fighting equipment, pressure to activate F.O. quick release device unreasonably low, ISM RELATED DEFICIENCIES: resources and personnel, responsible crew not know what will happen if CO <sub>2</sub> control box door was open, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, CO <sub>2</sub> system periodical service overdue (expired in 2001), LIFESAVING APPLIANCES: maintenance and inspection, periodical load test to survival craft launching appliances overdue, on board training and instructions, lifeboat not lowered to water and manoeuvred in every 3 months, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, engine room machinery generally oily and dirty, WORKING SPACES (ILO 147): other (working spaces), oxygen/acetylene cylinders stored in crew accommodation, ISM RELATED DEFICIENCIES: resources and personnel, item no. 1, 4, 5 & 7, maintenance of the ship and equipment, item no. 3, 4, 6, 7, 9, 10, 11, 12, 13, 14 & 16, emergency preparedness, item 16 |
| 8 | 8106599 | MERCURY III | Panama   | 1981 | 3016  | general cargo/multi-purpose ship | Panama Maritime Documentation Services Inc. | Musung Corporation                  | 09/02/04 | 10/02/04 | LIFESAVING APPLIANCES: lifeboats, lifeboat inventory, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, PROPULSION AND AUXILIARY MACHINERY: propulSION main engine, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills   |
| 9 | 8000525 | RIVA        | Panama   | 1981 | 67727 | bulk carrier                     | Lloyd's Register of Shipping                | Good Faith Shipping Co. S.A.        | 11/02/04 | 12/02/04 | FIRE FIGHTING MEASURES: fire pumps, unable to be started, chain clutch damaged, MARPOL - ANNEX I: oil filtering equipment, oily water separator pipes were either leak or damaged   |

|    |         |                 |                     |      |       |                                  |                             |   |          |          |  |
|----|---------|-----------------|---------------------|------|-------|----------------------------------|-----------------------------|---|----------|----------|--|
| 10 | 7420819 | FOOK ON         | Panama              | 1975 | 3168  | oil tanker                       | Panama Register Corp.       | Kam Bao Shipping (H.K.) Company Limited | 12/02/04 | 03/03/04 | ISM RELATED DEFICIENCIES: resources and personnel, maintenance of the ship and equipment, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, certificate for personnel on tankers, certificates for Master and officer, certificates for master and officer, STABILITY, STRUCTURE AND RELATED EQUIPMENT: pilot ladders, other (stability/structure), hull plate and frame distorted and weld detached, LIFESAVING APPLIANCES: lifeboat inventory, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, other (fire safety) E/R bulkhead holded for electric cable, jacketed piping system for high pressure fuel lines, MARPOL - ANNEX I: oil filtering equipment, OIL, CHEMICAL TANKERS AND GAS CARRIERS: spaces in cargo areas, LOAD LINES: ventilators, air pipes, casings |
| 11 | 9185401 | ARAMAC          | Liberia             | 1998 | 32322 | container ship                   | Germanischer Lloyd          | Reederei Hermann Wuff, Kollmar, Germany | 13/02/04 | 13/02/04 | LIFESAVING APPLIANCES: on board training and instructions, drill for actual lifeboat freefall launching overdue and without administration's permission for extension of such drill to 12 mths., CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, chief mate without liberian licenece   |
| 12 | 9004669 | AYUMAS SAMUDERA | Indonesia           | 1989 | 5552  | general cargo/multi-purpose ship | Nippon Kaiji Kyokai         | Pt. Gurita Lintas Samudera              | 16/02/04 | 16/02/04 | LIFESAVING APPLIANCES: lifeboat inventory, RADIOCOMMUNICATIONS: reserve source of energy   |
| 13 | 8321058 | MANDAKINI       | India               | 1985 | 28739 | bulk carrier                     | Indian Register of Shipping | Shipping Corporation of India Ltd       | 16/02/04 | 17/02/04 | RADIOCOMMUNICATIONS: MF/HF radio installation, LIFESAVING APPLIANCES: lifebuoys  |
| 14 | 8919001 | ALBERTA         | Cyprus              | 1991 | 21053 | container ship                   | Germanischer Lloyd          | Peter Dohle Schffahrts-KG               | 20/02/04 | 25/02/04 | CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, ventilation   |
| 15 | 9071480 | MARE ADRIATICUM | Antigua and Barbuda | 1993 | 9581  | container ship                   | Germanischer Lloyd          | Schlusel Reederei KG (GmbH & Co.)       | 20/02/04 | 20/02/04 | CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, RADIOCOMMUNICATIONS: MF/HF radio installation   |
| 16 | 9100530 | THAILINE 6      | Malaysia            | 1994 | 7633  | general cargo/multi-purpose ship | Nippon Kaiji Kyokai         | Shinline Sdn. Bhd.                      | 25/02/04 | 25/02/04 | FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control   |
| 17 | 9117777 | STAR ISLAND     | Panama              | 1994 | 6384  | container ship                   | Nippon Kaiji Kyokai         | Temm Maritime Co. Ltd                   | 26/02/04 | 26/02/04 | FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, LIFESAVING APPLIANCES: other (life-saving), EEBD in wheelhouse completely discharged   |

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.