Ships detained in Hong Kong by PSC Section in February 2005

| No | IMO Number | Ship Name | Flag | YOB | GRT | Ship Type | Class | Ship Company | Date of Detention | Date of Release | Nature of Deficiencies (responsible RO, if any) |
|----|---------------|------------------|--|------|-------|--------------------------------------|----------------------------------|---------------------------------------|----------------------|--------------------|---|
| 1 | 8405103 | TO SONG | Korea, Democratic People's Republic | 1984 | 1668 | general cargo/multi- purpose ship | Korean Classification Society | To song Shipping Co., Ltd. | 01/02/05 | 02/02/05 | ISM RELATED DEFICIENCIES: resources and personnel, SAFETY OF NAVIGATION: charts, nautical publications, lights, shapes, sound-signals, LIFESAVING APPLIANCES: lifeboat inventory, launching arrangements for survival craft, embarkation arrangements - survival craft, RADIOCOMMUNICATIONS: reserve source of energy, FIRE SAFETY MEASURES: personal equipment, fire-dampers |
| 2 | 9132404 | HAN JIN 3005 | Panama | 1995 | 2786 | general cargo/multi- purpose ship | Korean Register of Shipping | Hanjin Transportation Co., Ltd. | 01/02/05 | 02/02/05 | SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, SAFETY OF NAVIGATION: echo-sounding device, LIFESAVING APPLIANCES: lifebuoys, FIRE SAFETY MEASURES: readily availability of fire fighting equipment |
| 3 | 8121197 | GUANG DE | Saint Vincent and the Grenadines | 1981 | 3768 | general cargo/multi- purpose ship | Korean Register of Shipping | Anhui Marine Company Limited | 02/02/05 | 07/02/05 | LIFESAVING APPLIANCES: line throwing appliance, lifebuoys, lifeboat inventory, FIRE SAFETY MEASURES: fire-dampers, fire prevention, jacketed piping system for high pressure fuel lines, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, LOAD LINES: cargo and other hatchways, ventilators, air pipes, casings, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: access control to ship, ship security defects, there was no control to restricted areas (e.g. acc. doors, engine room doors etc. found open), security drills |
| 4 | 5413642 | GLENN BRAVEHEART | Panama | 1964 | 5690 | ro-ro cargo ship | Panama Register Corp | Glenn Marine Group (Asia) Pte Ltd. | 02/02/05 | 04/02/05 | ISM RELATED DEFICIENCIES: resources and personnel, RADIOCOMMUNICATIONS: reserve source of energy, other (radio), ITU publication not available, FIRE SAFETY MEASURES: fire-dampers |
| 5 | 8618449 | CMA CGM ENERGY | Marshall Islands | 1987 | 32630 | container ship | Registro Italiano Navale | Magnus Carriers Corp. | 15/02/05 | 16/02/05 | ISM RELATED DEFICIENCIES: resources and personnel, FIRE SAFETY MEASURES: jacketed piping system for high pressure fuel lines, fire prevention, readily availability of fire fighting equipment, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room |
| 6 | 9320790 | VICTORY | Viet Nam | 2002 | 2280 | general cargo/multi- purpose ship | Viet Nam Register of Shipping | Asia Shipping Joint Stock Company | 28/02/05 | 08/03/05 | ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: access control to ship, ISM RELATED DEFICIENCIES: resources and personnel, development of plans for shipboard operations, SAFETY OF NAVIGATION: charts, nautical publications, lights, shapes, sound-signals, RADIOCOMMUNICATIONS: other (radio), no ITU publication onboard, FIRE SAFETY MEASURES: fire-dampers, personal equipment, fire prevention |

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.