

Ships detained in Hong Kong by PSC Section in July 2006

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8304000	HUB BINTULU	Malaysia	1983	8234	container ship	Germanischer Lloyd	Hub Shipping Sdn. Bhd..	06/07/06	10/07/06	LIFESAVING APPLIANCES: lifeboats/stbd. lifeboat engine cannot start, FIRE SAFETY MEASURES: emergency fire pump/hard to start and pump pressure not built-up, fire prevention/main engine oil filters with excess oil, fire prevention/oil purifier room with excess oil, fire prevention/generators' filters with excess oil, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room/steering gear saveall with excess oil
2	8107608	CHANG SHUN DA 89	Panama	1982	1375	container ship	Panama Maritime Surveyors Bureau Inc	Guangzhou Sunny Ocean International Shipmanagement Co Ltd	10/07/06	26/07/06	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills/no log book for navigation & emergency drill since Jan 2006, MARPOL - ANNEX I: oil record book/no oil record book & garbage record book record, ISM RELATED DEFICIENCIES: documentation/no Panama official log book onboard, SAFETY OF NAVIGATION: nautical publications/all required publication not onboard (e.g. tide table, sailing direction, international code of signals, IAMSAR manual vo. III, ITU publications, etc.), voyage or passage plan/no voyage plan for last voyage, LIFESAVING APPLIANCES: stowage of rescue boats/all three liferafts not rigged properly, FIRE SAFETY MEASURES: fire-dampers/all fire dampers for engine room not working/close properly
3	9305702	MSC MADELEINE	Panama	2005	107551	container ship	Germanischer Lloyd	Mediterranean Shipping Co Srl	12/07/06	13/07/06	FIRE SAFETY MEASURES: emergency fire pump/the emergency fire pump not working

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.