

Ships detained in Hong Kong by PSC Section in August 2006

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9015773	DALIA ROJA	Panama	1991	8889	ro-ro cargo ship	Nippon Kaiji Kyokai	Janfield Shipping Ltd	09/08/06	11/08/06	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer/chief engineer licence (certificate of competency by Panama) not available onboard, MARPOL - ANNEX I: oil filtering equipment/the oily water separator found leaking
2	8909458	TIMBER TRADER VI	Taiwan, China	1989	5472	general cargo/multi-purpose ship	China Corporation Register of Shipping	Glory Navigation Co Ltd	10/08/06	11/08/06	FIRE SAFETY MEASURES: emergency fire pump/emergency fire pump casing found holed and seriously leaking
3	8208165	WEI YUAN	Panama	1983	37401	bulk carrier	Nippon Kaiji Kyokai	Wei Fong Shipping Co Ltd	12/08/06	12/08/06	LIFESAVING APPLIANCES: maintenance and inspection/the launching appliance (fwd and aft O ring) for hooking the port and stbd lifeboat found corroded, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room/the engine room bilge found oily
4	8817198	YONG FU STAR	Panama	1988	1598	general cargo/multi-purpose ship	Panama Maritime Surveyors Bureau Inc	Guangzhou Sunny Ocean International Shipping Management Co., Ltd	31/08/06	01/09/06	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer/the chief officer and 2nd officer did not have certificate of endorsement issued by Panama, certificates for master and officer/the chief engineer certificate of endorsement issued by Panama found expired on 19.8.2006, SAFETY OF NAVIGATION: lights, shapes, sound signals/the signalling lamp not working and no spare bulb found onboard, LIFESAVING APPLIANCES: lifeboat inventory/no bilge pump for lifeboat found, FIRE SAFETY MEASURES: fire-dampers/the fire dampers for engine room not working, personal equipment/one fireman outfit not found onboard, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches/four emergency lights in the engine room not working

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.