

## Ships detained in Hong Kong by PSC Section in January 2009

| No | IMO Number | Ship Name          | Flag     | YOB  | GRT   | Ship Type      | Class                                  | Related ROs   | Ship Company                      | Date of Detention | Date of Release | Nature of Deficiencies (responsible RO, if any)   |
|----|------------|--------------------|----------|------|-------|----------------|--|---|-----------------------------------|-------------------|-----------------|---|
| 1  | 7602467    | WELLY              | Panama   | 1976 | 22263 | Bulk Carrier   | China Corporation Register of Shipping | China Corporation Register of Shipping                  | Way-East Shipping Agency Co., Ltd | 02/01/2009        | 06/01/2009      | FIRE SAFETY MEASURES: emergency fire pump, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: other/7 medical certificates have been expired   |
| 2  | 9107057    | VAN LY             | Viet Nam | 1993 | 4879  | Container Ship | Viet Nam Register of Shipping          | Viet Nam Register of Shipping                           | Bien Dong Shipping Company        | 07/01/09          | 07/01/09        | SAFETY OF NAVIGATION: echo-sounding device/echo sounder found defective, FIRE SAFETY MEASURES: fire fighting equipment and appliances/fire isolating valve found seized   |
| 3  | 8100832    | PERMAI VI          | Panama   | 1981 | 18337 | Container Ship | American Bureau of Shipping            | Isthmus Bureau of Shipping; American Bureau of Shipping | Pt. Jayokusuma Perdana Lines      | 07/01/09          | 08/01/09        | RADIOCOMMUNICATIONS: satellite EPIRB 406MHz/1.6GHz, validity of hydrostatic release unit for EPIRB found expired (valid up to June 2008); MF/HF radio installation/function test of MF/HF DSC found not working in both main & emergency power supply condition, MARPOL - ANNEX I: oil filtering equipment/oily water separator (three-way valve) found not working |
| 4  | 8605662    | CALIFORNIA JUPITER | Liberia  | 1986 | 41668 | Container Ship | Nippon Kaiji Kyokai                    | Nippon Kaiji Kyokai                                     | NYK Shipmanagement Pte Ltd        | 16/01/09          | 16/01/09        | FIRE SAFETY MEASURES: emergency fire pump/emergency fire pump not able to pressurize the fire line  |

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.