

## Ships detained in Hong Kong by PSC Section in September 2010

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9332250	APL OAKLAND	Antigua and Barbuda	2007	43071	Container Ship	Germanischer Lloyd	Germanischer Lloyd	Hanseatic Lloyd Schiffahrt Gmbh & Co. KG	07/09/10	07/09/10	FIRE SAFETY MEASURES: fire-dampers, all four fire dampers for engine room blowers not closing as required. (Pneumatic rams for closing dampers rusty and stuck, and part of the louver type fire flaps not able to be closed tight.), WORKING SPACES (ILO 147): electrical, electric cable for e/r blower (stb'd aft) unsafe and not as required. (Cables not properly secured and cable through the junction box without tight gland or sealant)
2	7618296	SETUBAL CASTLE	Malta	1978	18455	Bulk carrier	Bureau Veritas	Bureau Veritas; Registro Italiano Navale	BNAVI Ship Management S.r.l.	08/09/10	09/09/10	FIRE SAFETY MEASURES: fire prevention, oxy-acetylene hoses passing through a hole (without closing) in e/r bulkhead impaired the fire construction, fire prevention, fire door between e/r & steering gear compartment (emergency fire pump room and fire exit) was kept open, other, many valves for glass level tubes for lube oil tanks not closed, other, many b-class cabin door louvers not able to be closed, other, a fuel quick closing valve for generators was kept open improperly and a q.c. valve for main engine was stuck by paint; ADDITIONAL MEASURES TO ENHANCE MARITIME SAFETY: access control to ship, agent and charterer's representatives had been onboard but no record found in visitor log. (note: a number of stevedores were on board but method of control unknown.); ISM RELATED DEFICIENCIES: emergency preparedness, deficient item #1 - 5 proved insufficient emergency preparedness.
3	8715261	VNL DYNAMIC	Viet Nam	1987	11977	Container Ship	Viet Nam Register of Shipping	Viet Nam Register of Shipping	Vinalines Container Shipping Co	10/09/10	12/09/10	STABILITY, STRUCTURE AND RELATED EQUIPMENT: hydraulic and other closing devices/watertight doors/underdeck spaces at for'd boson store, e.g. FP tank, chain lockers & bow thruster compartment not always closed, hydraulic and other closing devices/watertight doors/a section of the FP bulkhead valve linkage missing; SOLAS RELATED OPERATIONAL DEFICIENCIES: maintenance of fire protection systems/(i) method to prove operation of the cargo hold (no. 1 - 3) smoke detection system not known; (ii) type of smoke/heat fire detectors not identified by crew, operation of life saving appliances/immersion suits if need to be worn with lifejacket not known to crew. type approval certificate and service report not found; ISM RELATED DEFICIENCIES: emergency preparedness/deficient item no. 1 - 6 proved the insufficiency
4	9226920	MSC MARIANNA	Panama	2001	73819	Container Ship	Germanischer Lloyd	Germanischer Lloyd	Mediterranean Shipping Co. S.r.l.	28/09/10	29/09/10	SAFETY OF NAVIGATION: voyage data recorder (vdr), error found since new captain on board on 22.09.2010. There was not complete remedial actions taken including compensation of the equipment functions; FIRE SAFETY MEASURES: readily availability of fire fighting equipment, installation/system for f.o. quick closing valves and e/r dampers: (1) min. working pressure of the pneumatic system not known and (2) a big quantity of high viscosity liquid drained from the reserved air cylinder; ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, deficient item no. 1, 5 to 9 & 11 proved maintenance and emergency preparedness not sufficient.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.