

Ships detained in Hong Kong by PSC Section in November 2010

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7920792	SHUN HE	Sierra Leone	1979	1277	Refrigerated cargo carrier	Overseas Marine Certification Services (OMCS)	Overseas Marine Certification Services (OMCS)	Hongying Shipping Management Co., Ltd.	08/11/10	20/12/10	<p>CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: manning specified by the minimum safe manning document, ship undermanned by one deck officer, certificates for Master and officer, ship is carrying frozen chickens but flag state endorsement and CoC of master, c/o and engineer officer limit their service in ships carrying aquatic products, certificate for ratings for watchkeeping, (i) ship is carrying frozen chickens but watchkeeping certificate of a deck rating limits his service in ships carrying aquatic products; (ii) a deck rating without watchkeeping certificate, certificate for ship security officer, SSO without certificate of proficiency; ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: access control to ship, no implementation;</p> <p>STABILITY, STRUCTURE AND RELATED EQUIPMENT: other, repair of port shell plating below sheer strake at portside in way of no. 2 hold not verified by classification society if it was done properly;</p> <p>SAFETY OF NAVIGATION: other, communication of officers in English not sufficient, e.g. english in ship's certificates not understood by officers, other, nav. light panel: visual and audible alarms not working, voyage or passage plan, information required not provided, e.g. HK charts and charts for next port (Vietnam); SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of fire protection systems, operation of fire protection systems, responsible officers not know the proper procedures to operate the fixed CO₂ system for e/r fire fighting, maintenance of fire protection systems, coupling between e/r fire hoses and hydrants not matching and hoses without required nozzles, maintenance of fire protection systems, portable fire pump not delivering sufficient pressure; FIRE SAFETY MEASURES: division-main zones, gastightness of e/r bulkhead impaired: holed for passing through cables near port entrance (Overseas Marine Certification Services (OMCS));</p> <p>RADIOCOMMUNICATIONS: satellite EPIRB 406MHz/1.6GHz, EPIRB secured improperly by rope and the hydrostatic float-free securing device damage.</p>
2	9017032	SCI PRESTIGE	United Kingdom	1991	43213	Container	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Zodiac Maritime Agencies Limited	12/11/10	12/11/10	<p>FIRE SAFETY MEASURES: readily availability of fire fighting equipment, all connecting pipes of the pilot bottles for remotes operation of the cargo hold CO₂ fire fighting system were disconnected. (last service in Oct. 2010), means of control (opening, closure of skylights, pumps, etc. machinery spaces), more than 4 ltrs. of milky water drained from the air bottle for remote closing of fuel/lube oil quick closing valves.</p>

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.