

Ships detained in Hong Kong by PSC Section in January 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9546356	LIAO YUAN 7	Cambodia	2007	2983	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Liaoyuan Shipping (Hong Kong) Ltd.	11/01/13	15/01/13	LIFE SAVING APPLIANCES: on board training and instructions/ship's emergency manual written in chinese, c/o and c/e (bermese) cannot understand, lifeboats/both lifeboats rudders seized; SAFETY OF NAVIGATION: encho sounder/echo sounder failed; FIRE SAFETY: other (fire safety)/acetylene cylinders (full) stored in forecstle store room
2	8223804	HARVESTS	Panama	1982	1238	Refrigerated cargo	Panama Maritime Documentation Services	Panama Maritime Documentation Services	Ocean Grow International Shipmanagement Consultant Corp	14/01/13	18/01/13	CERTIFICATE AND DOCUMENTATION: ship certificates/continuous synopsis record/original CSR from no. 1 to no. 7 not available on board; FIRE SAFETY: ventilation/engine room port side ventilator can not be closed properly; SAFETY OF NAVIGATION: charts/BA charts for last and intended voyage: 937 outdated, 4127, 4118 not updated correction, nautical publications/lastest notice to mariner received on board was week 42/2012; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/excessive oily water found in engine room tanktop aft part
3	9259824	MELL SINGAPORE	Antigua and Barbuda	2002	9966	Container	Germanischer Lloyd	Germanischer Lloyd	W Bockstiegel Reederei GmbH & Co KG	19/01/13	22/01/13	SAFETY OF NAVIGATION: voyage data recorder (VDR)/simplified voyage data recorder (S-VDR)/VDR out of order from Nov. 2012, radar/port side radar out of order; FIRE SAFETY: fire-dampers/port side fire damper of e/r ventilator can not be closed; POLLUTION PREVENTION - MARPOL ANNEX VI: incinerator incl. operations and operating manual/the incinerator charging door can be opened when combustion chamber temperature more than 220 degree c

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.