

## Ships detained in Hong Kong by PSC Section in April 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9379583	JIN DA 27	Belize	2004	3869	General cargo/ multipurpose	Isthmus Bureau of Shipping, S.A.	Isthmus Bureau of Shipping, S.A.	He Full Shipping Management Inc.	10/04/13	16/04/13	WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/most of hatch cover cleats missing, covers (hatchway-, portable-, tarpaulins, etc.)/cargo hold no. 1 hatch cover could not be closed in proper position; FIRE SAFETY: fire fighting equipment and appliances/fire hydrant near the forecandle leaking during testing, fire fighting equipment and appliances/2 x fire hose found heavy leaking during testing; SAFETY OF NAVIGATION: charts/BA chart 937 old edition, 341 & 3026 not updated; RADIO COMMUNICATIONS: MF/HF radio installation/MF/HF radio DC power supply failure; EMERGENCY SYSTEMS: emergency steering position com./compass reading/emergency steering gear room communication to outside failure; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/e/r bottom about 20cm oily water accumulated
2	8518962	KUM SONG	Korea, Democratic People's Republic of	1985	1551	General cargo/ multipurpose	Korea Classification Society	Korea Classification Society	Yusong Shipping Co	15/04/13	16/04/13	WATER/WEATHERTIGHT CONDITIONS - VENTILATORS, AIR PIPES, CASINGS: no. 1 fot air vent pipe in cargo hold corroded/holed, cargo hold forward stbd side ventilator cannot be closed properly; LIFE SAVING APPLIANCES: lifebuoys incl. provision and disposition/2 lifebuoy lights expired & unlit, the other 2 lifebuoy lights expire date unknown; SAFETY OF NAVIGATION: echo sounder/echo sounder not working properly; FIRE SAFETY: oil accumulation in engine room/oil accumulated in e/r tanktop (about 15cm), other (fire safety)/e/r no. 2 fot sounding pipe self-closing cock hooked open, no. 1 fot sounding pipe self-closing cock disconnected
3	9348481	TS TAIPEI	Taiwan, China	2006	15487	Container	China Corporation Register of Shipping	China Corporation Register of Shipping	TS Lines Co Ltd	15/04/13	16/04/13	POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water separator not in working condition due to measuring cell out of order, oil and oily mixtures from machinery spaces/oil leaked to engine room floor due to sludge tank outlet valve leakage; FIRE SAFETY: fire detection and alarm system/smoke detector (zone 15) out of order and disconnected; SAFETY OF NAVIGATION: charts/BA charts 1962 and 937 for last and intend voyage expired; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage discharge connection/sewage directly discharge to sea at anchorage
4	9366586	ORIENTAL UNION	Panama	2004	6566	General cargo/ multipurpose	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai; China Corporation Register of Shipping	Fu Sheng Shipping Safety Management Consultant Co Ltd	22/04/13	26/04/13	POLLUTION PREVENTION - MARPOL ANNEX V: garbage management plan/garbage management plan not provided on board; LIFE SAVING APPLIANCES: lifeboats/both lifeboats engines fail to start by any means, lifejackets incl. provision and disposition/bridge lifejackets not of SOLAS type, but of type only for working use; FIRE SAFETY: other (fire safety)/acetylene stored in accommodation; ISM: safety and environment policy/deficiencies item no. 2 and no. 3 evidenced that SMS has not been properly implemented on board to comply with mandatory rules and regulations for environment protection

5	8649151	HAI CHI 3	Cambodia	2001	1159	Refrigerated cargo	Union Bureau of Shipping	Union Bureau of Shipping	For-Shine International Shipping (HK) Co Ltd	29/04/13	- - -	SAFETY OF NAVIGATION: automatic identification system (AIS)/AIS not working, voyage or passage plan/passage plans for last & intended voyage not available; ISM: certification, verification and control/according to above listed deficiencies, the international safety management system not implemented properly onboard; POLLUTION PREVENTION - MARPOL ANNEX VI: bunker delivery notes/bunkering delivery notes & oil samples not available; EMERGENCY SYSTEMS: emergency fire pump and its pipes/emergency fire pump not delivered sufficient pressure water during testing; FIRE SAFETY: fire doors/openings in fire-resisting divisions/one fire door for accommodation stairway missing, other fire doors not closed properly by self-closing device, oil accumulation in engine room/e/r bottom, oil accumulated about 20cm in depth, personal equipment for fire safety/short of one set of firefighter's outfit, one set of BA set pressure air leakage seriously found during testing; LIFE SAVING APPLIANCES: launching arrangements for rescue boats/rescue boat davit winch not working properly
6	8810384	KUM SONG 8	Korea, Democratic People's Republic of	1988	1485	Container	Korea Classification Society	Korea Classification Society	Korea Jamaedo Shipping Co	30/04/13	02/05/13	FIRE SAFETY: ready availability of fire fighting equipment/fire fighting equipment not ready for immediately using condition, fire hose & fire hydrant leaked during test, oil accumulation in engine room/e/r bottom, sludge oil accumulated about 10 cm in depth; SAFETY OF NAVIGATION: charts/navigation charts for last & intended voyage BA no 937, 1962 expired, BA no. 3062 small correction not done

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.