

Ships detained in Hong Kong by PSC Section in October 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8813582	GLOBAL MARINER	Belize	1988	6545	Refrigerated cargo	Panama Maritime Documentation Services	Panama Maritime Documentation Services	Greatsources Shipping Consultants Ltd	02/10/13	04/10/13	FIRE SAFETY: jacketed high pressure lines and oil leakage alarm/no. 3 m/e cylinder unit, jacketed f.o. high pressure pipe oil leaking at connection, ventilation/e/r skylight cover all bolts/nuts missing, fire fighting equipment and appliances/fire hose leaking seriously during testing; SAFETY OF NAVIGATION: nautical publications/6. navigation chart BA 4127 not available; ASD NP.60, NP33 old edition; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/second/third engineer assigned engineer duties without flag endorsement; LIFE SAVING APPLIANCES: lifeboats/p'side lifeboat seat belts hook corroded/broken; s'side lifeboat 3 window glasses broken; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS : cleanliness of engine room/oil/oil sludge accumulated in position : 1) EGR floor 2) F.O. purifier feed pump floor 3) air compressor bottom 4) camshaft pump bottom 5) G/E F.O. circ pump bottom 6) M/E case 7) G/E cases and 8) steer
2	8714085	FAVOR	Panama	1988	2426	General cargo/ multipurpose	Panama Maritime Documentation Services	Panama Maritime Documentation Services	Greatsources Shipping Consultants Ltd	02/10/13	07/10/13	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/master holds only chief officer's certificate of competency; SAFETY OF NAVIGATION: establishment of working language onboard/key engineers (C/E and 1st/E) not understanding any english, unable to read machineries manuals and instructions, echo sounder/echo sounder defective; RADIO COMMUNICATIONS: MF/HF radio installation /MF/HF radio telephony inoperative. MMSI not encoded correctly; FIRE SAFETY: fire detection and alarm system/all manual call points in accommodation and e/r inoperative, fire pumps and its pipes/emergency fire pump failed to start, jacketed high pressure lines and oil leakage alarm/M/E F.O. high pressure pipe leakage alarm tested failure; LIFE SAVING APPLIANCES: rescue boats/inflatable rescue boat failed to be inflated. launching davit seized; POLLUTION PREVENTION - MARPOL ANNEX IV: other (MARPOL annex IV)/sewage discharged to sea directly; PROPULSION AND AUXILIARY MACHINERY:operation of machinery/communication between engine side control and bridge/E.C.R. not operational
3	7625794	NEW IMPERIAL STAR	Saint Vincent and the Grenadines	1979	12586	Ro-Ro passenger ship	Registro Italiano Navale	Registro Italiano Navale	Skywill Management Ltd	17/10/13	31/10/13	LIFE SAVING APPLIANCES: lifejackets incl. provision and disposition/ infant lifejackets insufficient, 10 on board less than required 13; SAFETY OF NAVIGATION: rudder angle indicator/rudder angle indicator in bridge and steering gear room not working; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/E/R tanktop oily water accumulated 10cm in depth

4	8891297	DOUBLE HAPPINESS I	Panama	1994	2752	Container	Overseas Marine Certification Services	Overseas Marine Certification Services	Hong Chuan International Logistics Company Ltd	16/10/13	25/10/13	CERTIFICATE AND DOCUMENTATION: documents/SOPEP/SOPEP manual not available (only annex II o/b & not updated), crew certificates/manning specified by the minimum safe manning doc/lack of one 2/E as per MSMC requirement, SAFETY OF NAVIGATION: nautical publications/no notice to mariners provided on board since last edition 34/2012; ALRS NP286(6) and NP281(2) old edition, charts/voyage charts not properly corrected (including BA 4119, 4129, 4127), echo sounder/echo sounder not working, signalling lamp/bridge day light signalling lamp not working, FIRE SAFETY: fire detection and alarm system/fire detection system not properly working, fire fighting equipment and appliances/fire hoses leaking seriously during testing, EMERGENCY SYSTEMS: emergency, lighting, batteries and switches/all emergency lights not working, ISM/RESOURCES AND PERSONNEL: engineer not familiar with M/E local control operation, officer in charge not familiar with M/F DSC operation; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: cleanliness of engine room/oil accumulated in position : I) E/R tank top II) F.O./lub. oil purifier area III) D.O./F.O. serv. tank area IV) air compressor area V) steering gear room floor
5	8651219	KARO BRIGHT	Sierra Leone	2008	4503	General cargo/ multipurpose	Sing-Lloyd	Sing-Lloyd	Aoyang International Co Ltd	16/10/13	18/10/13	SAFETY OF NAVIGATION: charts/no any Hong Kong harbour chart onboard; FIRE SAFETY: fire doors/openings in fire-resisting divisions/fire doors to engine room self-close devices dismantled, numerous of fire doors self-close devices not working properly in accommodation, fire fighting equipment and appliances/main deck two (2) fire hydrants & one (1) fire hose found leaking seriously at testing
6	8107311	RAYNA	Comoros	1982	21551	Bulk carrier	Bulgarian Register of Shipping	Bulgarian Register of Shipping	Bulcom Ltd	27/10/13	20/11/13	SAFETY OF NAVIGATION: gyro compass/gyro compass not working properly, magnetic compass/magnetic compass damaged/broken, radar/s-band radar not working; LIFE SAVING APPLIANCES: inflatable liferafts/liferaft annual service expired in Aug 2013, no extension letter, distress flares/all hand flares onboard (in lifeboat and bridge) expired in Sept. 2013, all rocket parachute flares expired in Oct. 2013. No arrangement for replacement was found, lifebuoys incl. provision and disposition/bridge wing mob lifebuoy self-igniting light and smoke signal expired in May 2013, STRUCTURAL CONDITIONS: steering gear/emergency steering demonstrated failure; ALARMS : boiler alarm/boiler low water level alarm not functioning; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage treatment plant/sewage treating plant failed to be operated, other (MARPOL Annex IV)/sewage water discharged to sea directly; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water separator pump can not be started, 15 ppm alarm arrangements/only water separator 15 ppm alarm test failure; CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: cargo ship safety equipment (including exemption)/cargo ship safety equipment certificate. form e not available; FIRE SAFETY: fixed fire extinguishing installation/fix CO ₂ system, CO ₂ pipeline on main deck seriously rusted and broken at 2 locations (no. 2 & 4 cargo hold); LIVING AND WORKING CONDITIONS : winches & capstans/one mooring winch at aft not working; EMERGENCY SYSTEMS: emergency source of power - emergency generator/emergency generator damaged due to spare parts broken

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.