

## Ships detained in Hong Kong by PSC Section in December 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9709673	DIAN RADIANCE	Indonesia	2013	1558	Tugboat	Bureau Veritas	Bureau Veritas	PT DIAN BAHARI SEJATI	04/12/13	11/12/13	RADIO COMMUNICATIONS: maintenance/duplication of equipment/methods used to ensure availability of radio facilities is duplication of equipment only; CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: international air pollution prevention certificate (IAPP)/IAPP certificate supplement not indicate required information, international oil pollution prevention (IOPP)/IOPP certificate supplement not indicate required information, continuous synopsis record/CSR documents not available onboard during inspection; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/second engineer CoC expired on 11/03/2013, other (STCW)/medical certificates for all crew not available onboard during inspection; LIFE SAVING APPLIANCES: rescue boats/rescue boat fail to start
2	8608597	BELITA	Ship registration withdrawn	1986	4790	Refrigerated cargo	C.T.M. Inspection and Classification Company	C.T.M. Inspection and Classification Company	Corridor Overseas Co Ltd	23/12/13	- - -	<p>CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: other (certificates)/ship not holding certificate of registry issued by flag state, minimum safe manning document/ship not holding minimum safe manning certificate issued by flag state, continuous synopsis record/no valid CSR on board, civil liability for oil pollution damage cert./civil liability for bunker oil pollution damage certificate n/a; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/captain and c/o's CoC limitation under ship's tonnage, c/o's CoC expired, endorsement by flagstate/all officers CoC endorsement by flag state n/a; RADIO COMMUNICATIONS: reserve source of energy/GMDSS radio batteries power supply not operational, main installation/MMSI not encoded into radio station and EPIRB, facilities for reception of marine safety inform./NAVTEX</p> <p>not working; CERTIFICATE AND DOCUMENTATION - DOCUMENT: SOPEP/SOPEP n/a, survey report file/liferaft, EPIRB, AIS, S-VDR annual service n/a; LIFE SAVING APPLIANCES: emergency equipment for 2-way comm./two-way VHF primary batteries n/a, distress flares/all LSA signal equipment, including pyrotechnics, LTA, MOB sets expired, lifejackets incl. provision and disposition/lifejackets lights expired, lifeboats/stbd lifeboat rudder stock carrier broken, lifeboat inventory/most lifeboat inventories expired; SAFETY OF NAVIGATION: voyage data recorder (VDR)/simplified voyage data recorder (S-VDR)/S-VDR defective, speed and distance indicator/speed log defective, long-range identification and tracking system (LRIT)/LRIT not installed, bridge navigation watch alarm system</p> <p>(BNWAS)/BNWAS not installed, lights, shapes, sound-signals/all signal lights on main signal mast not working, charts/Hong Kong harbour chart n/a; FIRE SAFETY: fire detection and alarm system/fire detection system malfunction, fire pumps and its pipes/emergency fire pump not working, fire pumps and its pipes/deck firemain leakage at several holed positions, ventilation/port and stbd e/r ventilators hold on the trunks, fire detection and alarm system/manually operated call points not working; EMERGENCY SYSTEMS: emergency, lighting, batteries and switches/e/r emergency exit trunk no lighting; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage treatment plant/sewage treating plant not working; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/OWS not operational, retention of oil on board/oily water accumulated on e/r tank top about 35cm in dept</p>

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.