

## Ships detained in Hong Kong by PSC Section in March 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8714085	FAVOR	Panama	1988	2426	General cargo/ multipurpose	Panama Maritime Documentation Services	Panama Maritime Documentation Services	Greatsources Shipping Consultants Ltd	07/03/14	11/03/14	CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: other (certificates)/ship registry certificate and radio station licence expired on 4/Mar/2014. trading certificates (including ITC, LL, SE, SC, SR, IOPP, IAPP, ISPP) expired on 25/Feb/2014; no arrangement for renewal; EMERGENCY SYSTEMS: emergency, lighting, batteries and switches/all emergency lights unlit; POLLUTION PREVENTION - MARPOL ANNEX I/oil filtering equipment/oily water separator not working, POLLUTION PREVENTION - MARPOL ANNEX IV/sewage treatment plant/sewage treating plant not working; FIRE SAFETY: jacketed high pressure lines and oil leakage alarm/m/e jacketed high pressure f.o. leakage alarm defective, fixed fire extinguishing installation/CO <sub>2</sub> system unable to sound pre-discharge alarm to engine room; ISM/maintenance of the ship and equipment/above deficiencies give evidences that safety management system is not properly implemented onboard; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/master holds only chief officer's certificate of competency, manning specified by the minimum safe manning doc/insufficient manning. short of one ordinary seaman according to minimum safe manning certificate, endorsement by flagstate/no officers hold valid flag state endorsements for CoC; SAFETY OF NAVIGATION: echo sounder/echo sounder not working; RADIO COMMUNICATIONS: VHF radio installation/one of two VHF radio installations not working; LIFE SAVING APPLIANCES: rescue boats/inflatable rescue boat not usable, failed to be inflated
2	8627309	MIN TAI LENG	Kiribati	1984	2429	Refrigerated cargo	International Ship Classification	International Ship Classification	Hai Ling Shipping (Hong Kong) Limited	11/03/14	19/03/14	SAFETY OF NAVIGATION: nautical publications/NTM not available for BA charts, nautical publication NP32 expired, IAMSAR vol. III, NP30, NP79, NP286(6) not available onboard, echo sounder/echo sounder not working; ISM: certification, verification and control/item (11) not available, garbage record book showed dumping of category C garbage to sea since 12/09/2013; maintenance of the ship and equipment/according to the above listed items, shipboard ship safety management system maintenance of the ship and equipment not effective implemented, classification society additional SMC audit to carried out; FIRE SAFETY: fire doors/openings in fire-resisting divisions/engine room skylight hatch cover can't be closed properly, fire fighting equipment and appliances/fire hoses in poor condition, tested 3 fire hoses water leaking seriously, two fire hydrant valves corroded seriously seized; LIFE SAVING APPLIANCES: rescue boats/rescue boat fall chain and keel plate corroded seriously; EMERGENCY SYSTEMS: emergency source of power - emergency generator/emergency generator not working; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: cleanliness of engine room/engine room, oily dirty in place of purifier, steering gear flat, lubricate oil tank base; POLLUTION PREVENTION - MARPOL ANNEX I/oil and oily mixtures from machinery spaces/engine room bilge accumulated with 30cm in depth of oily bilge water

## Ships detained in Hong Kong by PSC Section in March 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
3	8747941	DONG TENG	Panama	1996	1413	General cargo/ multipurpose	Isthmus Bureau of Shipping, S.A.	Isthmus Bureau of Shipping, S.A.	East Harbour Navigation Co Ltd	07/03/14	10/03/14	FIRE SAFETY: fire detection and alarm system/fire detection and alarm system fault; EMERGENCY SYSTEMS: emergency fire pump and its pipes/emergency fire pump not working; POLLUTION PREVENTION - MARPOL ANNEX I/oil and oily mixtures from machinery spaces/engine room tank top oily water accumulated 10cm in depth
4	9174244	ORIENTAL BLESS	Taiwan, China	1997	5014	General cargo/ multipurpose	China Corporation Register of Shipping	China Corporation Register of Shipping	Len Chen Navigation Co Ltd	18/03/14	26/03/14	SAFETY OF NAVIGATION: echo sounder/echo sounder not function (no depth on paper/indicator), charts/charts BA4122 & amp; amp; BA4127 not corrected up-to-date and chart correction log is not available for inspection; LIFE SAVING APPLIANCES: radio life-saving appliances/failed EPRIB testing by crew members; FIRE SAFETY: ventilation/no 1 & 2 cargo hold ventilators unable to be closed fully; ISM: maintenance of the ship and equipment/from the evidences above, the implementation of SMS/ISM for shipboard maintenance and operations is not effective
5	8661903	CHUN YANG 17	Sierra Leone	2009	2994	General cargo/ multipurpose	Sing-Lloyd	Sing-Lloyd; International Register of Shipping	Aoyang International Co Ltd	21/03/14	24/03/14	EMERGENCY SYSTEMS: emergency source of power - emergency generator/emergency generator 2nd means start failure; FIRE SAFETY: remote means of control (opening, pumps, ventilation, etc.) machinery spaces/quick close valves for HFO port side and starboard side tanks not working; fire doors/openings in fire-resisting divisions/several fire doors not functioning properly; SAFETY OF NAVIGATION: charts/BA chart for present and next voyage: 937, 4127 not updated; pasted-up copy of 4122 and 4129 onboard

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.