

Ships detained in Hong Kong by PSC Section in November 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9245079	CENTURY SHINE	Panama	2000	4403	General cargo/ multipurpose	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Atlas Ship Management Co Ltd	10/11/14	11/11/14	WATER/WEATHERTIGHT CONDITIONS: scuppers, inlets and discharges/ one underwater overboard discharge valve is leaking seawater; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: electrical/the earth insulation for 100V feeder panel is 0 MOHM. (dangerous for electrical shock); POLLUTION PREVENTION - MARPOL ANNEX I/oil disch. monitoring and control system/the OWS alarm was out of order; POLLUTION PREVENTION - MARPOL ANNEX IV/sewage treatment plant/sewage treatment plant was out of order; FIRE SAFETY: operation of fire protection systems/emergency quick closing valve for no. 2 A.F.O. service TK not working
2	9151709	HAILI	Panama	1994	3541	Container	Overseas Marine Certification Services	Overseas Marine Certification Services	Beacon Marine Co Ltd	14/11/14	24/11/14	CERTIFICATE AND DOCUMENTATION - DOCUMENTS: tables of working hours/no hour of rest record for each crew member, stability information booklet/no SOPEP, cargo securing manual and stability booklet; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for medical care/no medical fitness certificates for all Myanmar, Indonesia crew member, one Chinese crew 3/O medical fitness certificate was out dated
3	9373175	RICH HONOR	Sierra Leone	2005	2396	General cargo/ multipurpose	Sing-Lloyd	Sing-Lloyd	Sanhe Marine Co Ltd	20/11/14	21/11/14	WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/cargo hold no. 1 manhole covers unable to be closed watertight, handle malfunction; FIRE SAFETY: ventilation/cargo hold no. 2 ventilation closing device flap missing, and some parts corroded holed, oil accumulation in engine room/engine room tank top oily water accumulated about 40cm in depth

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.