

Ships detained in Hong Kong by PSC Section in Nov 2015

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9163051	MIN FENG	Panama	1997	4697	General Cargo	NK	NK	Hai Ling Shipping (Hong Kong) Ltd	3.11.2015	11.11.2015	SAFETY OF NAVIGATION: NUC (FIXED NOT UNDER COMMAND, 2 ALL-ROUND RED LIGHTS) NOT AVAILABLE AND PORTABLE LIGHTS NOT HOSTED AS PER COLREGS, FIRE SAFETY: MAIN ENGINE FOUND LEAKING BLACK OIL AND OILY, FIRE RISK, FIRE SAFETY: E/R BILGE FOUND ABT. 5 CM DEPTH OF OILY WATER, ISM: EVIDENCES ABOVE (NO. 1 TO 24) INDICATED THAT SMS ON BOARD NOT IMPLEMENTED EFFECTIVELY.
2	7625794	NEW IMPERIAL STAR	Palau	1979	12586	Passenger RoRo	RINA	RINA	Skywill Management Ltd	5.11.2015	9.9.2016	SAFETY OF NAVIGATION: VOYAGE PLAN, NOT INCLUDED ESSENTIAL INFORMATION AS PER REQUIREMENT, RADIO COMMUNICATIONS: HF DSC RADIO, SHIP-SHORE TEST NOT AVAILABLE, TEST ON BOARD FAILED TO RECEIVE ACKNOWLEDGEMENT, ISM: SHIPS CREW NOT CONVERSANT WITH WEARING/TESTING SCBA AS PER REQUIREMENT FOR SAFE ENTRY OF DANGEROUS SPACE, FIRE SAFETY: E/R FIRE DAMPERS, UNABLE TO CLOSED BY REMOTELY ON BOAT DECK FOR FD3, FD4 AND FD5; AND, ISM: FORM THE EVIDENCES ABOVE (NO.1 TO 26), THE IMPLEMENTATION OF SHIPBOARD SAFETY MANAGEMENT SYSTEM NOT EFFECTIVE.
		NEW				Ro Ro Cargo	International Register of Shipping	International Register of Shipping	VR Maritime Services Private Ltd			
3	9398424	ZIM CHICAGO	Liberia	2009	91158	Container	LR	LR	Harmonia Reederei GmbH	26.11.2015	26.11.2015	EMERGENCY SYSTEMS: EMERGENCY GENERATOR NOT STARTED AUTOMATICALLY AND MANUALLY..
4	9372640	VINE 2	Malta	2005	9299	Bulk Carrier	RINA	RINA	Wallem Shipmanagement Ltd (WSM)	26.11.2015	2.12.2015	FIRE SAFETY: FIRE DETECTION ALARM SYSTEM, ZONE 3, 5, 10, 11 AND 12 WERE DISABLED, FIRE ALARM INDICATING IN ZONE 3, 5, AND 11 AFTER THE ZONES ENABLED, SYSTEM DEFECTIVE, FIRE SAFETY: FUNNEL FLAPS (LOUVERS) FIXED RUBBER SEALS AND UNABLE TO CLOSE IN EMERGENCY, FIRE SAFETY: ISOLATION VALVE FOR FIRE MAINS ON DECK-R/R DEFECTIVE/SEIZED IN OPEN POSITION, EMERGENCY SYSTEMS: CREW ASSIGNED TO WEAR SCBA NOT CECKED AND FOLLOW PROCEDURES TO ENSURE SAFE ENTERING TO DANGEROUS SPACE, EMERGENCY SYSTEMS: ENCLOSED SPACE CIC DRILL FOR ENTERING AND RESCUE OPERATION NOT PLANNED AND CONDUCTED AS PER REQUIREMENT INCLUDING COMMUNICATION, AWARE OF RISKS INSIDE, CHECKING ATMOSPHERE, FIRST AIDS, ETC.,

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.