

### 3. Ships detained in Hong Kong by PSC Section in July 2016

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9162320	AFFLUENT OCEAN	Panama	1997	6448	General cargo / multipurpose	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai, Overseas Marine Certification Services, Panama Maritime Documentation Services	Weihai Yunhao International Ship Management Co Ltd	06.07.2016	13.07.2016	<b>WATER/WEATHERTIGHT CONDITIONS:</b> POOP DECK HATCH TO STEERING GEAR ROOM HOLED, AND EDGES WASTED (UNABLE TO PROVIDE WEATHER-TIGHT), <b>WATER/WEATHERTIGHT CONDITIONS:</b> NO.1 AND NO.2 CARGO HATCH COVERS, SECURING CLEATS DAMAGED AND MISSING (6 PCS), <b>WATER/WEATHERTIGHT CONDITIONS:</b> FWD AND AFT AIR PIPES DAMAGED AND UNABLE TO BE CLOSED WEATHER-TIGHT (INCLUDING FPT, BOSUN STORE, AFT);, <b>WATER/WEATHERTIGHT CONDITIONS:</b> OPENING FOR UPPER DECK TO E/R, 16 BOLTS MISSING (UNABLE TO PROVIDE WATER-TIGHTNESS), <b>ISM:</b> SMS AS IMPLEMENTED, NOT ENSURE EFFECTIVE SAFETY MANAGEMENT ON BOARD THE VESSEL,
2	9642526	SEA RISING	Marshall Islaneds	2011	41684	Bulk Carrier	American Bureau of Shipping	American Bureau of Shipping, Det Norske Veritas	Wallem Shipmanagement Ltd (WSM)	08.07.2016	8.07.2016	<b>EMERGENCY SYSTEMS:</b> EMERGENCY FIRE PUMP, FAILED TO START FROM LOCAL AND REMOTE CONTROL (W/H AND FIRE CONTROL STATION), <b>LIFE SAVING APPLIANCES:</b> LIFEBOAT (FREEFALL) STEERING/RUDDER DEFECTIVE, <b>POLLUTION PREVENTION:</b> OWS, UNABLE TO DEMONSTRATE THE TEST AND OPERATION OF 15 PPM ALARM AND AUTO STOPPING AFTER MORE THAN 30 MINS,
3	9131010	PRUDENT	Mongolia	1996	4813	Container	Vietnam Register	Vietnam Register	VSICO Shipping JSC	25.07.2016	28.07.2016	<b>LIFE SAVING APPLIANCES:</b> PORT SIDE LIFE BOAT ENGINE COULD NOT STARTED DURING INSPECTION, NOT READY FOR USE., <b>CERTIFICATE &amp; DOCUMENTATION:</b> UNDER MANNING, ONE 2ND ENGINEER LESS THAN THE REQUIREMENT OF MINIMUM SAFE MANNING DOCUMENT.
4	8819691	QIAN YUAN	Micronesia	1988	1891	Refrigerated cargo	Union Bureau of Shipping	Union Bureau of Shipping	Greatsources Shipping Consultants Ltd	29.07.2016	18.08.2016	<b>FIRE SAFETY:</b> E/R SMOKE DETECTORS NOT WORK WHEN TESTED, <b>CERTIFICATE &amp; DOCUMENTATION:</b> ALL OFFICERS DON'T HAVE FLAG STATE ENDORSEMENT, <b>CERTIFICATE &amp; DOCUMENTATION:</b> MEDICAL CERTIFICATE NOT AVAILABLE FOR 10 CREWS (3/E, BOSUN, 3 X AB, FITTER, 2 X OILER, ELECTRICIAN, COOK),, <b>CERTIFICATE &amp; DOCUMENTATION:</b> NO STABILITY BOOKLET PRESENTED., <b>CARGO OPERATIONS INCLUDING EQUIPMENT:</b> NO CARGO SECURING MANUAL PRESENTED, <b>CERTIFICATE &amp; DOCUMENTATION:</b> NO GARBAGE MANAGEMENT PLAN AND RECORD BOOK PRESENTED., <b>CERTIFICATE &amp; DOCUMENTATION:</b> NO SOPEP MANUAL PRESENTED., <b>RADIO COMMUNICATIONS:</b> MF/HF DSC CAN NOT WORK AND NO RECORD., <b>EMERGENCY SYSTEMS:</b> EMERGENCY FIRE PUMP CAN NOT START., <b>WATER/WEATHERTIGHT CONDITIONS:</b> HATCH COVER CLEATS MISSED (CARGO HOLD #1: 4/16; #2: 7/16 AND #3: 8/16), REPEAT DEFICIENCY., <b>SAFETY OF NAVIGATION:</b> MAGNETIC COMPASS LIQUID LOSS., <b>ISM:</b> FROM THE ABOVE DEFICIENCY 1-31, SHOW ISM WAS NOT IMPLEMENTED PROPERLY..

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.