

Ships detained in Hong Kong by PSC Section in June 2003

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8921872	ORIENTAL GLORY	Belize	1990	2992	general cargo/multi-purpose ship	China Corporation Register of Shipping	Fu Sheng Shipping Safety Management Consultant Co., Ltd.	01/06/03	01/06/03	RADIOCOMMUNICATIONS: MF/HF radio installation
2	8313207	TIAN WEI	Malta	1983	6687	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Dalian Sea Carrier Co. Ltd.	02/06/03	05/06/03	ISM RELATED DEFICIENCIES: resources and personnel, maintenance of the ship and equipment, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, personal equipment, international shore connection, MARPOL - ANNEX I: oil filtering equipment, LIFESAVING APPLIANCES: stowage of lifeboats, lifeboats, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills
3	8403064	WEI LI NO. 2	Taiwan	1984	2847	general cargo/multi-purpose ship	China Corporation Register of Shipping	Tung Hai Navigation Co. Ltd.	02/06/03	03/06/03	FIRE FIGHTING MEASURES: fire fighting equipment and appliances, fire hose nozzles on deck was not dual purpose type, MARPOL - ANNEX I: oil filtering equipment, two solenoid valves cannot be tested, SHIP'S CERTIFICATES AND DOCUMENTS: document of Compliance (DOC/ISM Code), copy of DOC for ISM Code issued by the port authority was not found on board
4	9037214	OSG ALPHA	Saint Vincent and the Grenadines	1991	7167	container ship	China classification Society	Shanghai Adani Shipping Ltd.	03/06/03	03/06/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire dampers not able to be closed, RADIOCOMMUNICATIONS: MF/HF radio installation, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer
5	8705448	SHANGHAI EXPRESS	Malaysia	1988	18342	container ship	Germanischer Lloyd	Maritime Consortium Management Sdn. Bhd.	05/06/03	05/06/03	PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, ACCIDENT PREVENTION (ILO 147): pipes, wires (insulation), lagging for hot devices in E/R lack of maintenance and melted, FIRE FIGHTING MEASURES: fixed fire extinguishing installation, emergency gen. room protected by fixed CO2 system: vent. closing devices not gastight, STABILITY, STRUCTURE AND RELATED EQUIPMENT: steering gear, system oil leakage and deck oily
6	7360198	WASA QUEEN	Panama	1974	16546	Passenger ship	Det Norske Veritas	Star Cruise Administrative Services Sdn. Bhd.	05/06/03	06/06/03	LIFESAVING APPLIANCES: line throwing appliance
7	8713299	GREAT MARINER	Cambodia	1987	1894	general cargo/multi-purpose ship	Cambodia Ship Registry	Ever Maru Shipping S.A.	08/06/03	10/06/03	LIFESAVING APPLIANCES: on board training and instructions, ISM RELATED DEFICIENCIES: masters responsibility and authority, company verification, review and evaluation, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
8	8203854	SHENG LI	Panama	1982	3155	general cargo/multi-purpose ship	China Corporation Register of Shipping	Hansen Shipping Agencies Co. Ltd.	09/06/03	10/06/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, officer and motorman found holding fraudulent certificates, manning specified by the minimum safe manning document
9	8708555	VN SAPPHIRE	Viet Nam	1987	11977	container ship	Germanischer Lloyd	Vanlang Ship Management Company	09/06/03	10/06/03	RADIOCOMMUNICATIONS: other (radio), master and all officers were unable to carry out DSC coast station test with MF radio equipment, FIRE FIGHTING MEASURES: fire fighting equipment and appliances

10	7374888	XOH PAEK	North Korea	1978	3597	general cargo/multi-purpose ship	DPR Korea Register of Shipping	Pongsu Shipping Co.	09/06/03	13/06/03	ISM RELATED DEFICIENCIES: company verification, review and evaluation, emergency preparedness, maintenance of the ship and equipment, SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS: radar transponder, functional requirements, VHF EPIRB, LIFESAVING APPLIANCES: lifejackets, distress flares, lifeboat inventory, stowage of liferafts, lifeboats, FIRE FIGHTING MEASURES: personal equipment, readily availability of fire fighting equipment, MARPOL - ANNEX I: control of discharge of oil, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills
11	9016181	DONG HO	Viet Nam	1990	5518	general cargo/multi-purpose ship	Viet Nam Register of Shipping	Vietnam Sea and River Transport Corp.	10/06/03	12/06/03	SAFETY OF NAVIGATION: charts, LIFESAVING APPLIANCES: line throwing appliance, lifebuoys, ISM RELATED DEFICIENCIES: company verification, review and evaluation, internal audit has not carried out according to SMS requirement, emergency preparedness
12	8909458	TIMBER TRADER VI	Taiwan	1989	5472	general cargo/multi-purpose ship	China Corporation Register of Shipping	Glory Navigation Co. Ltd.	11/06/03	13/06/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: manning specified by the minimum safe manning document, STABILITY, STRUCTURE AND RELATED EQUIPMENT: stability/strength/loading information and instruments, SAFETY OF NAVIGATION: nautical publications, ISM RELATED DEFICIENCIES: masters responsibility and authority
13	9230270	MILLENNIUM DRAGON	Panama	2000	5007	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Eagle Maritime Co. Ltd.	15/06/03	15/06/03	SAFETY OF NAVIGATION: charts, charts 1917, 1918 & 3280 for hong kong waters were not the latest editions, LIFESAVING APPLIANCES: inflatable liferafts, the weaklink of the liferaft on board was missing
14	8201404	HUA YUE	Liberia	1983	1252	offshore service vessel	China classification Society	Shenzhen Huawei Offshore Shipping Transport Co. Ltd.	16/06/03	16/06/03	ISM RELATED DEFICIENCIES: resources and personnel, medical certificates for master, chief officer, chief engineer, bosun, sailors and cook expired
15	8714657	KAPITAN GRISHIN	Cyprus	1988	6030	general cargo/multi-purpose ship	Det Norske Veritas	Unicom Management Services (Cyprus) Ltd.	17/06/03	17/06/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, SAFETY OF NAVIGATION: lights, shapes, sound-signals
16	8119699	LAMON BAY	Liberia	1982	16910	container ship	Germanischer Lloyd	Norddeutsche Reederei H. Shuldt GmbH & Co. KG.	17/06/03	17/06/03	RADIOCOMMUNICATIONS: MF/HF radio installation, GMDSS MF/HF radio equipments were malfunction and failed to send DSC coast station test with 2, 4, 6, 8 mhz to hk MRCC
17	9134579	NINGBO STAR	Liberia	1998	17295	container ship	Germanischer Lloyd	Columbia Shipmanagement Ltd.	18/06/03	18/06/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, manning specified by the minimum safe manning document
18	8217324	HANDY FABIANA	Panama	1983	14286	Bulk carrier	Nippon Kaiji Kyokai	Tranasia Pool Pte. Ltd.	19/06/03	21/06/03	FIRE FIGHTING MEASURES: fire prevention, ventilation, fire-dampers, valves, quick closing devices, means of control, RADIOCOMMUNICATIONS: functional requirements
19	8506672	STENHEIM	Singapore	1985	10438	container ship	Nippon Kaiji Kyokai	Bauhinia Marine Pte. Ltd.	21/06/03	21/06/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, philippine 2nd Officer's flag state STCW endorsement application was not found on board, RADIOCOMMUNICATIONS: other(radio), master and all officers did not know how to operate and send a DSC coast station test with DSC MF/HF
20	7813834	YAN TONG	Panama	1979	6256	container ship	Germanischer Lloyd	Shandong Province Yantai International Marine Shipping Co.	22/06/03	24/06/03	ISM RELATED DEFICIENCIES: resources and personnel, company verification, review and evaluation, internal audit has not been carried out as per SMS requirement, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control

21	8106654	HO FENG NO.7	Panama	1981	5691	general cargo/multi-purpose ship	China Corporation Register of Shipping	Ho Feng Maritime Co., S.A.	24/06/03	26/06/03	ISM RELATED DEFICIENCIES: masters responsibility and authority, reports and analysis of non-conformities, accidents and hazardous occurrences, company verification, review and evaluation, STABILITY, STRUCTURE AND RELATED EQUIPMENT: stability/strength/loading information and instruments, SAFETY OF NAVIGATION: nautical publications, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, RADIOCOMMUNICATIONS: functional requirements, LIFESAVING APPLIANCES: lifeboats
22	9230220	WAN HAI 263	Singapore	2001	18872	container ship	Bureau Veritas	Wan Hai Lines Ltd.	24/06/03	24/06/03	RADIOCOMMUNICATIONS: MF/HF radio installation
23	7527239	MANILA STAR	Cambodia	1977	18632	Bulk carrier	China Corporation Register of Shipping	Dusung Shipping Co., Ltd.	24/06/03	28/06/03	SAFETY OF NAVIGATION: nautical publications, list of radio signals lists were 2000/01 edition and fog & lights list 2001/02 edition, FIRE FIGHTING MEASURES: fixed fire extinguishing installation, two foam nozzles for engine room fixed foam fire extinguishing installation were not found as shown on the fire plan, ISM RELATED DEFICIENCIES: company verification, review and evaluation, no evidence showed that internal audit was carried out in year 2002 as required by SMS manual "once every year" on ships, masters responsibility and authority, no evidence showed that master review was carried out in year 2002 as required by SMS manual "once a year", CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, master was holding flag endorsement certificate and its form was not complied with STCW 78 as amended
24	8225204	LADY JULIET	Cambodia	1982	12296	general cargo/multi-purpose ship	Russian Maritime Register of Shipping	Kaalbye Shipping International Limited	27/06/03	27/06/03	RADIOCOMMUNICATIONS: other (radio), ship's personnel unable to perform test on MF/HF radio using DSC, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, PROPULSION AND AUXILIARY MACHINERY: propulsion main engine, ISM RELATED DEFICIENCIES: emergency preparedness, emergency generator unable to be started for prolong period
25	8324012	HOSEI	Cambodia	1984	1200	general cargo/multi-purpose ship	Global Marine Bureau Inc.	Dalian Chun An Ship Management Co., Ltd.	27/06/03	30/06/03	FIRE FIGHTING MEASURES: fire fighting equipment and appliances, forward hydrant was not operable, ISM RELATED DEFICIENCIES: emergency preparedness, there was no evidence to show that schedule emergency drills between Jan. to June 2003 were carried out, masters responsibility and authority, there was no evidence that the master had carried out safety meeting from Feb. to June 2003 as required by SMS manual, resources and personnel, the training records including familiarization records of five crew members were not found

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.