

Ships detained in Hong Kong by PSC Section in September 2003

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8022494	RUNCHANG NO. 8	Belize	1980	1657	general cargo/multi-purpose ship	Korean Register of Shipping	Anqing Zhen Feng Shipping Co. Ltd.	02/09/03	04/09/03	FIRE FIGHTING MEASURES: fire pumps, emergency fire pump inoperable, SAFETY OF NAVIGATION: echo-sounding device, undefined, signalling lamp, undefined
2	7532997	GOOD SKY	Panama	1977	22398	bulk carrier	Korean Register of Shipping	ETA Ship Management Ltd.	03/09/03	16/09/03	STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, batteries were found with low specific gravity as shown by hydrometer, enhanced programme of inspection, there was no thickness measurement record maintained on board, hull-corrosion, No.3S TST bulkhead between 3/4 was found locally holed. Deck longitudinals were excessive diminished. Longitudinal IWO shear plate were excessive diminished. Web frames at 109&138 were found cracked & locally holed. No.3P TST - deck longitudinals were diminished. Wed frames IWO FR113 found badly corroded with hold, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, E/R fire door besides refrigeration room could not be shut, LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.), No.1 & 2 cargo hold hatch covers were not weathertight
3	8105478	NOOR	Qatar	1981	4644	oil tanker	International Register of Shipping	H.B.M. Shipping	09/09/03	under detention	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: manning specified by the minimum safe manning document, vessel undermanned by 3/O, certificates for master and officer, all officers no certificate of recognition, certificate for personnel on tankers, certificate of officers found no tanker safety endorsement, certificate for ratings for watchkeeping, ISM RELATED DEFICIENCIES: resources and personnel, no proper familiarization ashore given to master and no record of familiarization for officers and crew, company verification, review and evaluation, maintenance of the ship and equipment, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, manuals, instructions, etc., fire safety operational booklets not found, SAFETY OF NAVIGATION: nautical publications, speed and distance indicator, other (navigation), sextant not working, GYRO compass, CREW AND ACCOMMODATION (ILO 147): sanitary facilities, numerous cockroaches found and vessel was in poor hygiene condition, medical equipment, LIFESAVING APPLIANCES: operational readiness of lifesaving appliances, stowage of lifeboats, lifeboat inventory, lifeboats, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
4	9009176	ACX MARIGOLD	Singapore	1991	18487	container ship	Nippon Kaiji Kyokai	Pusaka Laut Pte. Ltd.	10/09/03	10/09/03	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, dangerous goods or harmful substances in packaged form, ISM RELATED DEFICIENCIES: emergency preparedness, LIFESAVING APPLIANCES: stowage of rescue boats, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, RADIOCOMMUNICATIONS: functional requirements
5	9170107	ASIAN QUEEN	Panama	1996	4769	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Toei Japan Ltd.	10/09/03	10/09/03	LIFESAVING APPLIANCES: lifeboats
6	8106800	SONG GWANG RYON	North Korea	1980	2393	general cargo/multi-purpose ship	Korea Classification Society	Visong Shipping Co.	18/09/03	23/09/03	ISM RELATED DEFICIENCIES: resources and personnel, nobody onboard has medical certificate, masters responsibility and authority, no master review, other (ISM), lifeboat not lowered into water - fail to comply with mandatory rules and regulations, emergency preparedness, no emergency procedure, emergency preparedness, no programme for drills, development of plans for shipboard operations, bunkering was not carried out under controlled conditions, MARPOL - ANNEX I : 15 PPM alarm arrangements, oil level sensors of ows cannot be proved functioning, LOAD LINES: ventilators, air pipes, casings, No.2 cargo hold port aft ventilator flap seized, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, funnel flap cannot be fully closed, SAFETY OF NAVIGATION: charts, nautical charts outdated, nautical publications, notice to mariners, sailing direction & supplement outdated, nautical publications, list of radio signals were not on board

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
7	8807674	DONG DU	Viet Nam	1988	6935	general cargo/multi-purpose ship	Viet Nam Register of Shipping	Vietnam Sea and River Transport	22/09/03	22/09/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS: functional requirements, ship officers not able to demonstrate to test the GMDSS equipment
8	9016167	LUCKY DIAMOND	Panama	1990	4405	general cargo/multi-purpose ship	China Corporation Register of Shipping	Hansen Shipping Agencies Co. Ltd.	23/09/03	23/09/03	LOAD LINES: ventilators, air pipes, casings, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, 2/E found without certificate of recognition from flag, LIFESAVING APPLIANCES: lifeboat inventory
9	7824015	PATARA	Saint Vincent and the Grenadines	1979	16281	general cargo/multi-purpose ship	Registro Italiano Navale	Convoy Maritime Ltd.	23/09/03	24/09/03	LIFESAVING APPLIANCES: lifeboats, both lifeboat engines not able to be started, lifeboats, stbd lifeboat propeller not in position, stowage of lifeboats, hooks release devices not function, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, officers' certificate of recognition not found, RADIOCOMMUNICATIONS: functional requirements, ship's officers not able to perform test on GMDSS equipment
10	7385734	JON JIN	North Korea	1973	12620	general cargo/multi-purpose ship	Korea Classification Society	Sohae Sonbak Co. Ltd.	24/09/03	30/09/03	SAFETY OF NAVIGATION: charts, nautical publications, LIFESAVING APPLIANCES: stowage of lifeboats, lifeboats, lifeboats, FIRE FIGHTING MEASURES: fire pumps, ventilation, fire-dampers, valves, quick closing devices, means of control, LOAD LINES: cargo and other hatchways, covers (hatchway-, portable-, tarpaulins, etc.), ISM RELATED DEFICIENCIES: company verification, review and evaluation, masters responsibility and authority, maintenance of the ship and equipment
11	7928744	HUB ACHIEVER	Malaysia	1980	5378	container ship	Germanischer Lloyd	HUB Shipping Sdn. Bhd., Malaysia	25/09/03	25/09/03	RADIOCOMMUNICATIONS: reserve source of energy, GMDSS batteries with low liquid level, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, CO2 release alarm not in ready operational condition, jacketed piping system for high pressure fuel lines
12	7900833	APOLLON I	Panama	1980	24804	container ship	Nippon Kaiji Kyokai	Technomar Shipping Inc.	29/09/03	29/09/03	LIFESAVING APPLIANCES: inflatable liferafts, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills
13	8418576	NEFTEGAZ-67	Ukraine	1989	2723	offshore service vessel	Russian Maritime Register of Shipping	National Stock Company "Chernomorнеftegaz", Ukraine	29/09/03	under detention	STABILITY, STRUCTURE AND RELATED EQUIPMENT: means of escape, emergency escape breathing apparatus not provided, ISM RELATED DEFICIENCIES: documentation, SOPEP: coastal state contact not update for years, development of plans for shipboard operations, passage plan not done regularly, resources and personnel, officers not familiar with the company safety system, e.g. periods of Internal Audit and master's review, MARPOL - ANNEX I: oil filtering equipment, oil sensor of IOPP equipment not functioning, LIFESAVING APPLIANCES: operational readiness of lifesaving appliances, rescue boat davit without periodical load test
14	8508412	THAILAND STAR 1	Cyprus	1985	10524	container ship	Germanischer Lloyd	MAR-CON GmbH, Germany	30/09/03	01/10/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, C/O, 3/O & 2/E without cyprus certificate, RADIOCOMMUNICATIONS: other (radio), GMDSS officers not familiar with the operation of GMDSS equip. e.g. test MF/HF radio, set navtex receiver & cancel the distress false alerts, MF/HF radio installation, MF/HF DSC radio cannot perform/test properly
15	9168403	UNICORN NO. 2	Panama	1997	5185	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Soki Kisen Co. Ltd.	30/09/03	30/09/03	LIFESAVING APPLIANCES: inflatable liferafts

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.