

Ships detained in Hong Kong by PSC Section in December 2003

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9208150	WAH HAI 231	Taiwan	1999	17751	Container ship	China Corporation Register of Shipping	Wan Hai Lines Ltd.	05/12/03	05/12/03	LIFESAVING APPLIANCES: lifeboats, starboard lifeboat engine failed starting up.
2	8610033	MOL ETERNITY	Japan	1986	35234	Container ship	Nippon Kaiji Kyokai	M. O. Shipmanagement Co. Ltd.	08/12/03	08/12/03	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills.
3	9260134	MAYFLOWER RESOLUTION	Isle of Man	2002	14085	Self-Elevation Unit (MODU)	Det Norske Veritas	Mayflower Energy Ltd	15/12/03	16/12/03	ISM RELATED DEFICIENCIES: certification, verification and control, RADIOCOMMUNICATIONS: functional requirements.
4	9158135	KENGTUNG	Myanmar	1998	9436	general cargo/multi-purpose ship	Lloyd's Register of Shipping	Myanma Five Star Line	16/12/03	16/12/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire fighting equipment and appliances, personal equipment.
5	8405103	TO SONG	North Korea	1984	1668	general cargo/multi-purpose ship	Korean Classification Society	Tosong Shipping Co., Ltd.	31/12/03	31/12/03	LIFESAVING APPLIANCES: lifeboats, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control.
6	8217685	PHA SUNG	Korea, Democratic People's Republic	1982	4113	general cargo/multi-purpose ship	Korean Classification Society	Pha Sung Shipping Co. Ltd	29/12/03	31/12/03	LIFESAVING APPLIANCES: line throwing appliance, RADIOCOMMUNICATIONS: radar transponder, FIRE FIGHTING MEASURES: fire fighting equipment and appliances, ventilation, fire-dampers, valves, quick closing devices, means of control, SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS: functional requirements.
7	7376288	MARIANA	Republic of Sierra Leone	1983	668	Oil Tanker	Sierra Leone Classification Corporation	Smart Wealth International Ltd.	17/12/03	23/12/03	SHIP'S CERTIFICATES AND DOCUMENTS: other (certificates), all convention certificates issued without IMO number, prevention of pollution by oil (IOPP), IOPP certificate found without Form B, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates of master and officer, all deck officers and C/E certificates of competency found valid for near coastal. However, according to minimum safe manning cert., the vessel is for world wide trade, MARPOL - ANNEX I: oil record book, oil record book and cargo record book not on board, ISM RELATED DEFICIENCIES: documentation, ISM manuals not found on board, LIFESAVING APPLIANCES: lifejackets, lifejackets found without light / whistle, inflatable, liferafts, one liferaft's service date found expired, two other liferafts found missing, other (life-saving), most of the LSA found expired and not ready for inspection, e.g. smoke signal, parachutes signals, line throwing apparatus etc., rescue boats, rescue boat found without engine and in very poor condition. In addition, rescue boat equipment not ready for inspection, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, partition between engine room and accommodation found with opening, LOAD LINES: railing, cat walks, ship side railings p/s detached, other (load lines), f'cle at starboard forward found holed, doors, f'cle watertight do (two) and access hatch on f'cle deck found holed / with opening, RADIOCOMMUNICATIONS: satellite EPIRB 406MHz/1.6 GHx, epirb battery found expired and its test certificate not available for inspection.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates