

## Ships detained in Hong Kong by PSC Section in March 2004

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8029600	MIKAELA II	Panama	1981	3316	general cargo/multi-purpose ship	International Register of Shipping	Seawind Maritime Company S.A.	03/03/04	11/03/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, ISM RELATED DEFICIENCIES: resources and personnel, LIFESAVING APPLIANCES: line throwing appliance, 2-way radiotelephone apparatus for survival craft, lifebuoys, inflatable liferafts, lifeboat inventory, operational readiness of lifesaving appliances, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, other (fire safety), 2 EEBD inside engine control room found without pressure, jacketed piping system for high pressure fuel lines, LOAD LINES: ventilators, air pipes, casings, MARPOL - ANNEX I: oil filtering equipment, SAFETY OF NAVIGATION: nautical publications, ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, company verification, review and evaluation, SHIP'S CERTIFICATES AND DOCUMENTS: safety management certificate (SMC/ISM Code)
2	8310803	YORK CASTLE	Cayman Islands	1984	29660	bulk carrier	Registro Italiano Navale	BNAVI S.p.A.	04/03/04	05/03/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, MARPOL - ANNEX I: oil discharge monitoring and control system, LOAD LINES: ventilators, air pipes, casings, cargo and other hatchways, LIFESAVING APPLIANCES: inflatable liferafts, lifeboats, SAFETY OF NAVIGATION: lights, shapes, sound-signals
3	8506672	STENHEIM	Singapore	1985	10438	container ship	Nippon Kaiji Kyokai	Bauhinia Marine Pte. Ltd.	05/03/04	05/03/04	MARPOL - ANNEX I: 15 ppm alarm arrangements, FIRE FIGHTING MEASURES: fire pumps, SAFETY OF NAVIGATION: other (navigation), passage plan not done/prepare for voyages
4	9111565	CSAV SANTOS	Germany	1994	16269	container ship	Germanischer Lloyd	Niederelbe Schiffahrtsgesellschaft Mbh & Co. Kg.	05/03/04	05/03/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, SHIP'S CERTIFICATES AND DOCUMENTS: cargo ship safety construction (including exemption), other (certificates), condition of class was not dealt with (class required final repair to be carried out before 29.2.2004), RADIOCOMMUNICATIONS: functional requirements
5	9134232	EVER DAINTY	Panama	1997	52090	container ship	American Bureau of Shipping	Evergreen Marine Corporation (Taiwan) Ltd	06/03/04	06/03/04	LIFESAVING APPLIANCES: lifeboats, STB lifeboat prolonged to start, FIRE FIGHTING MEASURES: fixed fire extinguishing installation, fire main isolation valve for engine room seized, fire pumps, emergency fire pump inoperative
6	8826046	GAN BAEK SAN	North Korea	1977	6399	general cargo/multi-purpose ship	Korea Classification Society	Korea Susan Shipping Company	07/03/04	10/03/04	ISM RELATED DEFICIENCIES: company verification, review and evaluation, emergency preparedness, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, FIRE FIGHTING MEASURES: personal, equipment, RADIOCOMMUNICATIONS, MF/HF radio installation, LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.)
7	8106800	SONG GWANG RYON	North Korea	1980	2393	general cargo/multi-purpose ship	Korea Classification Society DPR of Korea	Korea 56 Trading Co.(Jisong)	09/03/04	12/03/04	RADIOCOMMUNICATIONS: functional requirements, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, LIFESAVING APPLIANCES: lifeboats

8	8604474	GEORGE	Lebanon	1986	15872	bulk carrier	Nippon Kaiji Kyokai	Chekka Shipping S.A.	10/03/04	11/03/04	LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.), ventilators, air pipes, casings, FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, MARPOL - ANNEX I: oil filtering equipment, LIFESAVING APPLIANCES: inflatable liferafts, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificate for ratings for watchkeeping
9	9063146	JI SONG-5	North Korea	1992	1580	general cargo/multi-purpose ship	Korea Classification Society	Korea 56 Trading Co.(Ji Song), DPR Korea	12/03/04	13/03/04	STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, SAFETY OF NAVIGATION: charts, nautical publications
10	8804921	EVER SHINE	Cambodia	1988	1917	general cargo/multi-purpose ship	Global Marine Bureau Inc.	Ever Maru Shipping S.A.	13/03/04	16/03/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, LOAD LINES: ventilators, air pipes, casings, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, electric equipment in general, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, LIFESAVING APPLIANCES: inflatable liferafts
11	9255919	CORAL ISLANDER II	Panama	2002	17111	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Toda Ship Co. Ltd.	16/03/04	16/03/04	RADIOCOMMUNICATIONS: MF/HF radio installation, transmitter not working, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills
12	9124029	YAMAHARU	Panama	1995	4231	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Korea Shipmanagers Co., Ltd.	17/03/04	17/03/04	LIFESAVING APPLIANCES: lifebuoys, STB MOB smoke signal corroded and holed, lifeboats, STB lifeboat engine no astern motion, RADIOCOMMUNICATIONS: reserve source of energy
13	8508838	HEALTHY FALCON	Viet Nam	1984	2998	oil tanker	Viet Nam Register of Shipping	Falcon Shipping Company, Vietnam	18/03/04	19/03/04	MARPOL - ANNEX II: P & A manual, not approved procedures and arrangement manual required by MARPOL annex II onboard, RADIOCOMMUNICATIONS: other (radio), ITU publications not provided, LIFESAVING APPLIANCES: maintenance and inspection, port lifeboat: port of registry not marked at bow; air support system with no service; vent trunk handwheel missing; for'd sliding skate missing; engine throttle control wire detached; no top identification, stb'd lifeboat, top light detached, ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, deficient item no. 3, 6, 7 & 8, documentation, deficient item no. 1, 4, 5 & 10
14	8901743	MAGNA VISION	Malta	1989	17058	container ship	Nippon Kaiji Kyokai	Magna Shipholdings S.A.	18/03/04	19/03/04	FIRE FIGHTING MEASURES: fire fighting equipment and appliances, RADIOCOMMUNICATIONS: functional requirements
15	7377830	CARINA 1	Panama	1973	10538	other types of ship	Nippon Kaiji Kyokai	Cosmo Sealand Co., Ltd.	22/03/04	23/03/04	SAFETY OF NAVIGATION: charts, LIFESAVING APPLIANCES: lifeboat inventory, 2-way radiotelephone apparatus for survival craft
16	9158848	WAN HAI 163	Taiwan	1997	13246	container ship	China Corporation Register of Shipping	Wan Hai Lines Ltd.	24/03/04	24/03/04	LIFESAVING APPLIANCES: lifeboats, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, SAFETY OF NAVIGATION: other (navigation), voyage plan not done since jan 04
17	7374644	VAN DYCK	Saint Vincent and the Grenadines	1975	16166	general cargo/multi-purpose ship	Registro Italiano Navale	Convoy Maritime Ltd., Turkey	25/03/04	27/03/04	RADIOCOMMUNICATIONS: maintenance/duplication of equipment, GMDSS maintenance agreement issued on 27/11/03 without name & signature of owner/management company, other (radio), ITU publications outdate/not supplied: list of coast stations (1998), list of ship's stations (2001), list of radio determination & special service stations (2000), manual for use by the maritime mobile & maritime-mobile satellite service (1999), list of call signs & numerical identities not supplied, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and Officer, 2/E without flag state licence; 4/E cert. no. of national COC mentioned in flag state licence different,

											LIFESAVING APPLIANCES: maintenance and inspection, an EEBD at E/R platform outside workshop indicated empty, STB L/B: no POR marking at bow; crutches without chain connection, Port L/B: no POR marking at bow, an oar cracked, no spanner/tool to lock the mast securing clamp, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, air receiver for fuel oil quick closing valves near empty, ISM RELATED DEFICIENCIES: resources and personnel, def. item no. 3, 7 & 9, maintenance of the ship and equipment, def. item no. 5, 8, 11, 12, 13, 15 & 16, emergency preparedness, def. item no. 10 & 12, documentation, def. item no. 1, 2, 4, 6 & 14
18	7721835	TAO YUAN	Panama	1979	18644	container ship	China Corporation Register of Shipping	Taiwan Navigation Co., Ltd.	25/03/04	25/03/04	LOAD LINES: ventilators, air pipes, casings, covers (hatchway-, portable-, tarpaulins, etc.), cargo and other hatchways, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, jacketed piping system for high pressure fuel lines, LIFESAVING APPLIANCES: lifeboats
19	8025408	CHIN CHUN	Singapore	1981	8078	container ship	Nippon Kaiji Kyokai	Wan Hai Lines Ltd.	29/03/04	31/03/04	FIRE FIGHTING MEASURES: other (fire safety), E/R fire doors left open, lock damaged, handle missing, door frame unauthorized cut away, fire pumps, emergency fire pump not deliver pressure for long time, priming pump leak, ventilation, fire-dampers, valves, quick closing devices, means of control, LIFESAVING APPLIANCES: lifeboats, stbd lifeboat lifeline damaged, landing planks, seat planks detached, support frame bolts and nuts serious wasted, engine casing cover corroded, cover support frame seriously corroded and rusted, fire extinguisher casing wasted, propeller shaft rubbing with planks on test, port lifeboat in poor conditions, rudder tiller not able to be connected, inventory box cover seized, sail mast support mechanism stuck and plank detached, compass air bubble and light not working, crutches not in place, bowsing gear stuck, bilge pump detached
20	8029600	MIKAELA II	Panama	1981	3316	general cargo/multi-purpose ship	International Register of Shipping	Sea Wind Maritime S.A.	29/03/04	30/03/04	LOAD LINES: overloading, RADIOCOMMUNICATIONS: reserve source of energy, SAFETY OF NAVIGATION: other (navigation), voyage OKAB was not prepared before voyage, LIFESAVING APPLIANCES: lifebuoys
21	8616506	KAGA	Japan	1987	51047	container ship	Nippon Kaiji Kyokai	Hachiuma Steamship Co., Ltd.	31/03/04	31/03/04	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.