

Ships detained in Hong Kong by PSC Section in April 2004

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8605038	NEW LUCKY II	Panama	1986	3133	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Well Shipmanagement and Maritime consultant Co. Ltd.	01/04/04	01/04/04	ISM RELATED DEFICIENCIES: resources and personnel, SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS: reserve source of energy, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
2	9126481	SANTA GIULIANA	Liberia	1996	21531	container ship	Germanischer Lloyd	Reederei Claus-Peter Offen GmbH & Co.	06/04/04	06/04/04	LIFESAVING APPLIANCES: lifeboats
3	7617565	YANG BING	Panama	1976	4003	general cargo/multi-purpose ship	China Corporation Register of Shipping	Hua Ling (Thai) Co. Ltd.	13/04/04	19/04/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: manning specified by the minimum safe manning document, certificates for Master and officer, FIRE FIGHTING MEASURES: fixed fire extinguishing installation, LIFESAVING APPLIANCES: other (life-saving), there was no service record for 2 liferafts, lifeboat inventory
4	8417297	IMABARI GLORY	Cyprus	1984	14936	bulk carrier	Lloyd's Register of Shipping	Pacific & Atlantic Corporation	14/04/04	15/04/04	RADIOCOMMUNICATIONS: functional requirements, other (radio), distress signal was inadvertently sent to Australia MRCC; officers were not familiarised with the procedure of cancellation for distress signal, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
5	7810545	X-PRESS SINGAPORE	Panama	1978	7179	container ship	Panama Maritime Documentation Services, Inc.	Fuzhou Minlun Shipping Co., Ltd.	15/04/04	19/04/04	ISM RELATED DEFICIENCIES: resources and personnel, ship's officer not familiar with the operation of ship's equipment, maintenance of the ship and equipment, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, other (fire safety), many fire doors not able to be closed properly, jacketed piping system for high pressure fuel lines, protect piping damaged, personal equipment, most of B.A. not function, spare bottles empty, LIFESAVING APPLIANCES: stowage of lifeboats
6	8408193	HARVIA	Belize	1984	2514	general cargo/multi-purpose ship	Belize Maritime Bureau Inc.	Hua Wei Ocean Shipping Corporation	15/04/04	17/04/04	SAFETY OF NAVIGATION: charts, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, STABILITY, STRUCTURE AND RELATED EQUIPMENT: means of escape, emergency lighting, batteries and switches, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, LOAD LINES: ventilators, air pipes, casings
7	8113841	UNI-ONWARD	Panama	1982	19698	container ship	American Bureau of Shipping	Evergreen Marine Corporation (Taiwan) Ltd.	15/04/04	16/04/04	RADIOCOMMUNICATIONS: maintenance/duplication of equipment, radio battery liquid with low gravity, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, BA bottle attached to the breathing apparatus only half full, STABILITY, STRUCTURE AND RELATED EQUIPMENT: ballast, fuel and other tanks, air pipe flame arrestors for No. 1 & 2 F.O.tanks wasted

8	9021576	CHANG HONG	Panama	1990	4336	general cargo/multi-purpose ship	China Classification Society	Well Shipmanagement and Maritime consultant Co. Ltd.	19/04/04	20/04/04	SAFETY OF NAVIGATION: charts, STABILITY, STRUCTURE AND RELATED EQUIPMENT: other (stability/structure), forepeak valve not operable, sounding pipe cover not able to be closed, means of escape, escape door at deck level seriously corroded, insulation material damaged, FIRE FIGHTING MEASURES: other (fire safety), engine room escape trunk plating cut away, door corroded, insulation material cut away, jacketed piping system for high pressure fuel lines, emergency fuel oil stopping arrangement not ready, MARPOL - ANNEX I: oil filtering equipment, LIFESAVING APPLIANCES: lifeboat inventory, ISM RELATED DEFICIENCIES: resources and personnel, maintenance of the ship and equipment
9	9130509	EVER ABLE	Panama	1995	14807	container ship	Nippon Kaiji Kyokai	Evergreen Marine Corporation (Taiwan) Ltd.	19/04/04	19/04/04	LIFESAVING APPLIANCES: immersion suits, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills
10	7614317	KHUDOZHNIK ZHUKOV	Russia	1975	22369	container ship	Russian Maritime Register of Shipping	Far-Eastern Shipping Company	20/04/04	20/04/04	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire pumps, LIFESAVING APPLIANCES: buoyant apparatus, stowage of liferafts, ISM RELATED DEFICIENCIES: emergency preparedness
11	8113853	UNI-ORIENT	Panama	1982	19698	container ship	American Bureau of Shipping	Evergreen Marine Corporation (Taiwan) Ltd.	22/04/04	22/04/04	SAFETY OF NAVIGATION: charts, LIFESAVING APPLIANCES: lifeboat inventory, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, jacketed piping system for high pressure fuel lines, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches
12	8410366	THOR AMALIE	Isle of Man	1984	3120	general cargo/multi-purpose ship	Lloyd's Register of Shipping	CEC Shipmanagement	22/04/04	23/04/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
13	8518778	ORIENTAL PROFIT	Panama	1986	2838	general cargo/multi-purpose ship	China Corporation Register of Shipping	Fu Sheng Shipping Safety Management Consultant Co., Ltd., Taiwan	22/04/04	23/04/04	LIFESAVING APPLIANCES: on board training and instructions, launching of lifeboat (P) overdue (last 12/2003 to boat deck only), RADIOCOMMUNICATIONS: maintenance/duplication of equipment, date in the MF/HF DSC radio wrongly set to Jan. 03 and weekly ship/shore station test of DSC equipt overdue, ISM RELATED DEFICIENCIES: resources and personnel, def. item no. 2 & 5, emergency preparedness, def. item no. 2 & 4
14	9128099	CSAV ITAJAI	Marshall Islands	1996	24053	container ship	Germanischer Lloyd	Uniteam Marine Ltd.	26/04/04	27/04/04	RADIOCOMMUNICATIONS: functional requirements, ship's officer not familiar with the operation of MF/HF using DSC, MF/HF radio installation, MF/HF equipment not function

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.