## **Ships detained in Hong Kong by PSC Section in April 2005**

| No | IMO<br>Number | Ship Name     | Flag          | YOB  | GRT   | Ship Type                            | Class                                     | Ship Company  | Date of<br>Detention | Date of<br>Release | Nature of Deficiencies (responsible RO, if any)  |
|----|---------------|---------------|---------------|------|-------|--------------------------------------|---|---|----------------------|--------------------|--|
| 1  | 8113841       | EAGLE PIONEER | Panama        | 1982 | 19698 | container ship                       | American Bureau of<br>Shipping            | Ocean Eagle<br>Shipmanagement Company<br>Pte Ltd.           | 01/04/05             | 02/04/05           | LIFESAVING APPLIANCES: lifeboat inventory, FIRE SAFETY MEASURES<br>fire-dampers, emergency escape breathing device   |
| 2  | 8715261       | PHU MY        | Viet Nam      | 1987 | 11977 | container ship                       | Germanischer Lloyd                        | Van Lang Shipping<br>Company                                | 02/04/05             | 06/04/05           | LOAD LINES: ventilators, air pipes, casings, railing, cat walks, STABILITY,<br>STRUCTURE AND RELATED EQUIPMENT: means of escape, FIRE<br>SAFETY MEASURES: readily availability of fire fighting equipment, ISM<br>RELATED DEFICIENCIES: resources and personnel  |
| 3  | 9088213       | DONG PHONG    | Viet Nam      | 1993 | 5552  | general cargo/multi-<br>purpose ship | Viet Nam Register of<br>Shipping          | Dong Do Maritime<br>Corporation (Viseritrans)               | 06/04/05             | 06/04/05           | SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills,<br>SAFETY OF NAVIGATION: charts, LIFESAVING APPLIANCES: lifebuoys,<br>immersion suits, lifeboats, inflatable liferafts, STABILITY, STRUCTURE<br>AND RELATED EQUIPMENT: means of escape, FIRE SAFETY<br>MEASURES: fire-dampers, means of control (opening, closure of skylights,<br>pumps, etc. machinery spaces), fire prevention, PROPULSION AND<br>AUXILIARY MACHINERY: cleanliness of engine room  |
| 4  | 8314500       | EVER GOLDEN   | Taiwan, China | 1984 | 37023 | container ship                       | 1   | Evergreen Marine<br>Corporation (Taiwan) Ltd                | 07/04/05             | 07/04/05           | STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency<br>lighting, batteries and switches, FIRE SAFETY MEASURES: jacketed piping<br>system for high pressure fuel lines, fire prevention, readily availability of fire<br>fighting equipment, PROPULSION AND AUXILIARY MACHINERY:<br>cleanliness of engine room, LOAD LINES: cargo and other hatchways   |
| 5  | 9208186       | WAN HAI 235   | Taiwan, China | 1999 | 17751 | container ship                       | China Corporation<br>Register of Shipping | Wan Hai Lines Limited                                       | 07/04/05             | 07/04/05           | CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: manning specified by the minimum safe manning document   |
| 6  | 7533044       | WINONA        | Panama        | 1976 | 16126 | bulk carrier                         | China Corporation<br>Register of Shipping | Jacksoon Shipping Safety<br>Management Consultant<br>Co Ltd | 09/04/05             | 13/04/05           | SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills,<br>RADIOCOMMUNICATIONS: other (radio), ITU publication not onboard,<br>LIFESAVING APPLIANCES: emergency equipment for 2-way communication<br>lifeboat inventory, lifejackets, distress flares, FIRE SAFETY MEASURES:<br>ventilation, personal equipment, LOAD LINES: covers (hatchway-, portable-,<br>tarpaulins, etc.), machinery space openings, STABILITY, STRUCTURE AND<br>RELATED EQUIPMENT: steering gear, PROPULSION AND AUXILIARY<br>MACHINERY: cleanliness of engine room, MARPOL - ANNEX I: control of<br>discharge of oil, ISM RELATED DEFICIENCIES: resources and personnel |

| 7  | 7612034 | UCHUR              | Russia                           | 1976 | 4817  | general cargo/multi-<br>purpose ship | Russian Maritime<br>Register of Shipping | Azia Shipping Holdings<br>Ltd.                                     | 11/04/05 | 15/04/05 | ISM RELATED DEFICIENCIES: resources and personnel, SAFETY OF<br>NAVIGATION: charts, echo-sounding device, FIRE SAFETY MEASURES:<br>means of control (opening, closure of skylights, pumps, etc. machinery spaces),<br>fire prevention, jacketed piping system for high pressure fuel lines,<br>LIFESAVING APPLIANCES: stowage of liferafts, lifeboat inventory,<br>PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room   |
|----|---------|--------------------|----------------------------------|------|-------|--------------------------------------|--|--|----------|----------|---|
| 8  | 9279226 | VINASHIN NAVIGATOR | Viet Nam                         | 2002 | 9503  | container ship                       | Germanischer Lloyd                       | Bien Dong Shipping<br>Company                                      | 12/04/05 | 12/04/05 | FIRE SAFETY MEASURES: means of control (opening, closure of skylights,<br>pumps, etc. machinery spaces), LIFESAVING APPLIANCES: lifebuoys,<br>LOAD LINES: overloading   |
| 9  | 7626853 | SANDY CAPE         | Saint Vincent and the Grenadines | 1976 | 1819  | other types                          | American Bureau of<br>Shipping           | First Baltic<br>Shipmanagement AS                                  | 13/04/05 | 14/04/05 | SAFETY OF NAVIGATION: echo-sounding device, FIRE SAFETY<br>MEASURES: international shore connection, fire fighting equipment and<br>appliances, STABILITY, STRUCTURE AND RELATED EQUIPMENT:<br>bulkheads - operational damage, ISM RELATED DEFICIENCIES: resources<br>and personnel   |
| 10 | 8609797 | HIGH SEA           | Panama                           | 1986 | 1886  | general cargo/multi-<br>purpose ship | Panama Maritime<br>Surveyors Bureau Inc  | Wanzhou Shipping S.A.  | 13/04/05 | 14/04/05 | LIFESAVING APPLIANCES: lifejackets, SAFETY OF NAVIGATION:<br>signalling lamp, FIRE SAFETY MEASURES: emergency fire pump,<br>emergency escape breathing device   |
| 11 | 8505991 | ALAS               | Indonesia                        | 1985 | 6302  | general cargo/multi-<br>purpose ship | Nippon Kaiji Kyokai                      | Pt. Arpeni Dratama Ocean<br>Line                                   | 15/04/05 | 18/04/05 | FIRE SAFETY MEASURES: emergency fire pump, personal equipment,<br>division main zones, fire fighting equipment and appliances, LIFESAVING<br>APPLIANCES: emergency equipment for 2-way communication, lifejackets,<br>SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS: MF/HF<br>radio installation  |
| 12 | 7501273 | JINSHAN            | Panama                           | 1976 | 11729 | bulk carrier                         | Isthmus Bureau of<br>Shipping            | Ninbo Ftz Cosnavi<br>International Shipping<br>Management Co. Ltd. | 19/04/05 | 22/04/05 | SAFETY OF NAVIGATION: nautical publications, echo-sounding device,<br>LIFESAVING APPLIANCES: emergency equipment for 2-way communication,<br>lifeboat inventory, FIRE SAFETY MEASURES: fire-dampers, emergency fire<br>pump, LOAD LINES: doors, covers (hatchway-, portable-, tarpaulins, etc.)   |
| 13 | 7618521 | GLORY D            | Panama                           | 1978 | 11252 | container ship                       | Korean Register of<br>Shipping           | Goldenport<br>Shipmanagement Ltd.                                  | 29/04/05 | 29/04/05 | CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: endorsement<br>by flag states, FIRE SAFETY MEASURES: means of control (opening, closure<br>of skylights, pumps, etc. machinery spaces), fire prevention, LOAD LINES:<br>cargo and other hatchways, LIFESAVING APPLIANCES: lifebuoys,<br>PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room,<br>STABILITY, STRUCTURE AND RELATED EQUIPMENT: means of escape,<br>ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: other<br>(maritime security), the last 9 out of 10 ship/port records are not available,<br>declaration of security was not available for those ports that might not be in<br>compliance with ISPS, some ship's crew are not familiar with ISPS code (e.g.<br>requirement for completing of DOS etc.) |

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.