

## Ships detained in Hong Kong by PSC Section in May 2005

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7602467	WELLY	Panama	1976	22263	bulk carrier	China Corporation Register of Shipping	Jackson Shipping Safety Management Consultant Co. Ltd.	06/05/05	09/05/05	FIRE SAFETY MEASURES: doors within main vertical zone, LIFESAVING APPLIANCES: lifejackets, immersion suits, lifeboat inventory, SAFETY OF NAVIGATION: lights, shapes, sound-signals, nautical publications, RADIOCOMMUNICATIONS: MF/HF radio installation
2	7619604	BUANA	Panama	1976	9977	bulk carrier	Polski Rejestr Statkow	ATL Shipping Limited	09/05/05	13/05/05	SAFETY OF NAVIGATION: signalling lamp, LIFESAVING APPLIANCES: lifeboat inventory, FIRE SAFETY MEASURES: means of control (opening, closure of skylights, pumps, etc. machinery spaces), STABILITY, STRUCTURE AND RELATED EQUIPMENT: bulkheads - operational damage, ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: other (maritime security), no evidence on board that the ship had carried out ship security with entries of ten calls of port facilities, ISM RELATED DEFICIENCIES: resources and personnel
3	9112909	MASOVIA	Liberia	1994	17285	container ship	Germanischer Lloyd	Christian F. Ahrenkiel GmbH & Co. Kg	11/05/05	11/05/05	FIRE SAFETY MEASURES: fire prevention, jacketed piping system for high pressure fuel lines, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills
4	8508254	DERYOUNG SUNRISE	Panama	1985	4541	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	D.&S. CO., Ltd, Kaohsiung Office	11/05/05	12/05/05	SAFETY OF NAVIGATION: echo-sounding device, voyage or passage plan, nautical publications, FIRE SAFETY MEASURES: fire-dampers, jacketed piping system for high pressure fuel lines, LIFESAVING APPLIANCES: lifeboat inventory, LOAD LINES: doors
5	7374644	VAN DYCK	Saint Vincent and the Grenadines	1975	16166	general cargo/multi-purpose ship	Registro Italiano Navale	Convoy Maritime Ltd.	17/05/05	17/05/05	FIRE SAFETY MEASURES: jacketed piping system for high pressure fuel lines, SAFETY OF NAVIGATION: echo-sounding device
6	7929956	DONG FA	Panama	1980	1045	general cargo/multi-purpose ship	Isthmus Bureau of Shipping	East Harbour Navigation Co., Ltd.	23/05/05	24/05/05	SAFETY OF NAVIGATION: nautical publications, LOAD LINES: cargo and other hatchways, RADIOCOMMUNICATIONS: reserve source of energy, FIRE SAFETY MEASURES: personal equipment
7	9016167	LUCKY DIAMOND	Panama	1990	4405	general cargo/multi-purpose ship	China Corporation Register of Shipping	Hansen Shipmanagement Consultant Corp.	25/05/05	25/05/05	LIFESAVING APPLIANCES: line throwing appliance, lifebuoys, lifeboat inventory, lifeboats, immersion suits, FIRE SAFETY MEASURES: emergency fire pump, fire prevention, jacketed piping system for high pressure fuel lines, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room

8	7808413	RAGANO	Saint Vincent and the Grenadines	1978	9640	bulk carrier	Polski Rejestr Statkow	Treasure Target Limited	27/05/05	02/06/05	LOAD LINES: railing, cat walks, ISM RELATED DEFICIENCIES: resources and personnel, maintenance of the ship and equipment, SAFETY OF NAVIGATION: charts, nautical publications, voyage or passage plan, LIFESAVING APPLIANCES: lifebuoys, stowage of liferafts, immersion suits, lifeboat inventory, maintenance and inspection, FIRE SAFETY MEASURES: fire-dampers (Polski Rejestr Statkow), means of control (opening, closure of skylights, pumps, etc. machinery spaces)(Polski Rejestr Statkow), readily availability of fire fighting equipment, jacketed piping system for high pressure fuel lines (Polski Rejestr Statkow), fire prevention (Polski Rejestr Statkow), ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: security drills, other (maritime security), there was no control to restricted areas (e.g. funnel door & some accommodation door found held in open position etc.), access control to ship, records for ISPS event not complete (e.g. visitor log for several ports found missing e.g. Singapore, Haldia, Jingtang etc.), PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room
---	---------	--------	----------------------------------	------	------	--------------	------------------------	-------------------------	----------	----------	--

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.