

Ships detained in Hong Kong by PSC Section in February 2006

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9172117	FORTUNE TRADE 1	Panama	1997	9962	ro-ro cargo ship	Nippon Kaiji Kyokai	Janfield Shipping Ltd.	09/02/06	09/02/06	LOAD LINES: cargo ports and similar openings/Stern ramp door slightly deformed and watertightness affected
2	7236505	GOLDEN TAURUS	Bolivia	1972	280	other types of ship	Horizon International Naval Surveying & Inspection Board	Tosei Marine Company S.A.	13/02/06	not yet released	SAFETY OF NAVIGATION: nautical publications/ Nautical charts/Notice to Mariners, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: resources and personnel/MEDICAL CERTIFICATE/certificates for Master and officer, LIFESAVING APPLIANCES/lifejackets, LOAD LINES: ventilators/air pipes/casings, FIRE SAFETY MEASURES: Emergency Fire Pump, CREW AND ACCOMMODATION (ILO 147): Sanitary facilities
3	8403181	WING SANG 38	Honduras	1983	254	other types of ship	Honduras International Surveying and Inspection Bureau	Wing Sang Fisheries S.D.E.R.L.	13/02/06	07/03/06	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, certificates for radio personnel, LOAD LINES: doors (Honduras International Surveying and Inspection Bureau), MARPOL - ANNEX I: standard discharge connection (Honduras International Surveying and Inspection Bureau), suspected discharge violation
4	9020015	JUPITER ACE	Viet Nam	1991	5470	general cargo/multi-purpose ship	Viet Nam Register of Shipping	Eastern Dragon Shipping Company Ltd.	23/02/06	23/02/06	LIFESAVING APPLIANCES: lifeboats, FIRE SAFETY MEASURES: fire fighting equipment and appliances
5	7813602	ALTAIR	Panama	1978	16325	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Bnavi Ship Management S.R.L, Italy	24/02/06	25/02/06	SHIP'S CERTIFICATES AND DOCUMENTS: safety management certificate (SMC/ISM code)/original SMC/ISM certificate is not onboard, ADDITIONAL MEASURES TO ENHANCE MARITIME SAFETY: continuous synopsis record/original CSR certificate is not onboard, LIFESAVING APPLIANCES: lifebuoys/2 manoverboard signals expired, RADIOCOMMUNICATIONS: facilities for reception of marine safety information/Navtex test print not functioning, FIRE SAFETY MEASURES: fire-dampers/one engine room damper (port side) not able to be closed, fire fighting equipment and appliances/3 fire hoses/nozzles not found in fire boxes, fixed fire extinguishing installation/one fire hydrant found holed and leaking at port accommodation ladder, personal equipment/2 breathing apparatus pressure meters unreadable, ventilation/one galley ventilator found holed/wasted

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.