

Ships detained in Hong Kong by PSC Section in January 2007

IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
7721835	TAO YUAN	Panama	1979	18644	container ship	China Corporation Register of Shipping	China Corporation Register of Shipping, American Bureau of Shipping, Lloyd's Register	Taiwan Navigation Co., Ltd	05/01/07	05/01/07	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer/5 crew members' medical fitness certificate expired, SAFETY OF NAVIGATION: nautical publications/sailing direction NP30 & NP32 not corrected up-to-date, LIFESAVING APPLIANCES: lifeboats/port lifeboat lower part of vertical supporting frame connecting to boat keel found seriously corroded & wasted more than 50% of the steel thickness, lifeboat inventory/P & S boats items were in poor condition or not available. (e.g. water tanks damaged, morse signalling torches not available, awning stanchion wasted, harbour pin lashed, compass lights, search light, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room/engine room and generators/main engine casing found very oily and dirty may lead to serious fire risk
7709370	LONG TAI 1	Panama	1987	1792	container ship	Panama Maritime Surveyors Bureau Inc.	China Corporation Register of Shipping, Panama Maritime Surveyors Bureau Inc.	Guangzhou Sunny Ocean International Shipmanagement Co., Ltd.	11/01/07	Not yet released	SOLAS RELATED OPERATIONAL DEFICIENCIES: muster list, SAFETY OF NAVIGATION: charts, nautical publications, echo-sounding device (Panama Maritime Surveyors Bureau Inc.), signalling lamp (Panama Maritime Surveyors Bureau Inc.), FIRE SAFETY MEASURES: readily availability of fire fighting equipment, means of control (opening, closure of skylights, pumps etc. machinery spaces) (Panama Maritime Surveyor Bureau Inc.), emergency fire pump (Panama Maritime Surveyors Bureau Inc.), SHIP'S CERTIFICATES AND DOCUMENTS: logbooks/compulsory entries, RADIOCOMMUNICATIONS: radio log (daily), LIFESAVING APPLIANCES: lifeboats (Panama Maritime Surveyors Bureau Inc.), MARPOL - ANNEX I: oil record book, shipboard oil pollution emergency plan (SOPEP)
7715458	LE YU QUAN	Panama	1977	4036	container ship	China Classification Society	China Classification Society; Isthmus Bureau of Shipping	Qingdao Pan Ocean Shipping	17/01/07	19/01/07	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: other (STCW)/six crew members medical certificate found expired, LOAD LINES: ventilators, air pipes, casings/one ventilator on STBD forecandle deck found corroded/holed, covers (hatchway-, portable-, tarpaulins, etc.)/forecandle deck bosun store hatch cover all locking devices found missing, FIRE SAFETY MEASURES: emergency fire pump/emergency fire pump found not working (started to test the emergency fire pump on 10:45 and not working, until 13:15 the pump working

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.