## **Ships detained in Hong Kong by PSC Section in May 2008**

]	No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
	1	8705448	SINOTRANS KAOHSIUNG	Panama	1988	18342	container ship	Germanischer Lloyd	Germanischer Lloyd	Sea Star Ships Management Co Ltd	02/05/08	04/05/08	FIRE SAFETY MEASURES: Ventilation/no. 3 and no. 4 cargoholds ventilation closing devices damaged, LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.)
	2	8913136	MOL THAMES	Panama	1989	50628	container ship	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	New Asian Shipping Co Ltd	08/05/08		FIRE SAFETY MEASURES: emergency fire pump, the emergency fire pump room was flooded and the emergency fire pump was submerged and not working

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.