

## Ships detained in Hong Kong by PSC Section in April 2009

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8625741	ASIA HK 26	Cambodia	1985	1222	General cargo/multi-purpose ship	Union Bureau of Shipping	Union Bureau of Shipping	Liaoyuan Shipping (Hong Kong) Co. Ltd	01/04/09	04/04/09	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, 1. competent and endorsement certificate for 2nd engineer was not available; ISM RELATED DEFICIENCIES: masters responsibility and authority, no master review report was available onboard, resources and personnel, no safety management system (SMS) familiarisation record for new crew was available on board, emergency preparedness, no safety training schedule was established onboard, company verification, review and evaluation, no internal audit report was available onboard; masters responsibility and authority, the safety management was not properly implemented onboard; SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, no record showing lifeboat had been put into water after Oct-08; SAFETY OF NAVIGATION: voyage or passage plan, no voyage plan was prepared after Sep-2008; LIFESAVING APPLIANCES: lifeboat inventory, lifeboat light battery expired in Sep-1998, lifeboat inventory, lifeboat fire extinguisher found out of order; FIRE SAFETY MEASURES: emergency fire pump, emergency fire pump could not be started after 10min preparation work
2	9470038	YUSHO EIGHT	Panama	2007	2905	General cargo/multi-purpose ship	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Grow-will Inc.	15/04/09	16/04/09	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, the 2nd officer's certificate of competency and endorsement expired
3	9050084	BONNIE SMITHWICK	Bahamas	1993	45593	Combination carrier	Det Norske Veritas	Det Norske Veritas, American Bureau of Shipping	B + H Equimar Singapore Pte Ltd	16/04/09	17/04/09	LIFESAVING APPLIANCES: lifeboats, lifeboat (free-fall type) engine not working after recovery from water-borne testing
4	9167514	VINALINES PIONEER	Viet Nam	1997	6875	Container ship	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai, Viet Nam Register of Shipping	Vinalines Container Shipping Company	17/04/09	18/04/09	SAFETY OF NAVIGATION: charts, chart no. 4122 missing [2008] 6499, 6762 & [2009] 249 correction, no. 4129 missing [2008] 6254, [2009] 249 & 1470 correction, no. 4118 missing [2008] 6255 & 6762 correction, <b>ADDITIONAL MEASURES TO ENHANCE MARITIME SECURITY: access control to ship, pilot ladder lowered to water level all the time without gangway watch keeper around, various restricted area doors keep open</b> ; ISM RELATED DEFICIENCIES: development of plans for shipboard operations, with reference to the above, ISM system effectiveness not in evidence
5	9146780	MORNING VISHIP	Viet Nam	1996	6251	Container ship	Viet Nam Register of Shipping	Viet Nam Register of Shipping	Shikishima Kisen KK	25/04/09	27/04/09	STABILITY, STRUCTURE AND RELATED EQUIPMENT: stability/strength/loading information and instruments/the stability was done on a non-approved computer/software without periodical verification; SAFETY OF NAVIGATION: charts/chart corrections had not been made on HK charts due to lack of NMs; FIRE SAFETY MEASURES: doors within main vertical zone/the fire doors at engine room lowest level escape and galley cannot be closed

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.