

Ships detained in Hong Kong by PSC Section in November 2009

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9188817	MODERN DRIVE	Panama	1999	33831	Vehicles Carrier	Det Norske Veritas	Det Norske Veritas; Nippon Kaiji Kyokai	Fuyoh Shipping Co	06/11/09	06/11/09	LIFESAVING APPLIANCES: on board training and instructions, the crew could not describe an understanding of the on-load release, including interlocks; launching arrangements for survival craft, the crew could not describe the hooks and release arrangements, including any interlock are correctly set; stowage of liferafts, the hydrostatic releases of port and starboard liferafts were not properly installed; SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, the lifeboats were not launched and manoeuvred in the water at least once every three months during an abandon ship drill; STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, batteries were not in good order as indicated by hydrometer; FIRE SAFETY MEASURES: main vertical zone, engine room fire door, self closing device was detached
2	7929487	EAST SUNRISE 8	Panama	1980	37271	Bulk carrier	Overseas Marine Certification Services (OMCS)	Overseas Marine Certification Services (OMCS)	East Sunrise Ship Manage Ltd	09/11/09	12/11/09	FIRE SAFETY MEASURES: readily availability of fire fighting equipment; STABILITY, STRUCTURE AND RELATED EQUIPMENT: hydraulic and other closing devices/watertight doors; LIFESAVING APPLIANCES: lifeboat inventory, lifeboats
3	8806254	ASIA CEMENT NO. 3	Taiwan, China	1988	7608	Others	China Corporation Register of Shipping	China Corporation Register of Shipping	U-Ming Marine Transport Corp	18/11/09	19/11/09	FIRE SAFETY MEASURES: readily availability of fire fighting equipment, SAFETY OF NAVIGATION: nautical publications, LOAD LINES: machinery space openings, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room
4	8406418	ELEFThERIA K	Panama	1984	107915	Bulk carrier	Nippon Kaiji Kyokai	Det Norske Veritas; Nippon Kaiji Kyokai	European Navigation Inc	23/11/09	23/11/09	FIRE SAFETY MEASURES: main vertical zone, e/r upper decks entry door, one self closing device removed and one could not be fully closed; MARPOL - ANNEX I: 15 ppm alarm arrangements; ISM RELATED DEFICIENCIES: certification, verification and control
5	9176474	CHANG SHIN	Panama	1998	4737	General Cargo	China Classification Society	Nippon Kaiji Kyokai; China Classification Society	Ocean Grow International Shipmanagement Consultant Corp.	24/11/09	26/11/09	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer; SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills; LIFESAVING APPLIANCES: lifebuoys, lifeboats, on board training and instructions, launching arrangements for survival craft

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.