## Ships detained in Hong Kong by PSC Section in December 2009

N	[о	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
	I	7818511	SUN EXPRESS	Sierra Leone	1979	2975	Container ship	New United (Int'l) Marine Services Ltd	New United (Int'l) Marine Services Ltd	Ocean Grow International Shipmanagement Consultant Corp.	10/12/09		LIFESAVING APPLIANCES: lifeboat inventory, inventory of two lifeboats not found on board; SOLAS RELATED OPERATIONAL DEFICIENCIES: establishment of working language on board, instructions for releasing fixed CO <sub>2</sub> gas into engine room not in the working language and key personnel not familiar with the releasing procedures; FIRE SAFETY MEASURES: firedampers, ventilation trunk of engine room at port side for fire damper seriously wasted/holed
	2	8024521	AVRA	Panama	1981	39633	Bulk carrier	Russian Maritime Register of Shipping		Good Faith Shipping Co SA	17/12/09	17/12/09	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, RADIOCOMMUNICATIONS: functional requirements; LIFESAVING APPLIANCES: line throwing appliance, line throwing appliances, rockets were expired in 11/2009, lifeboats; STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.