

## Ships detained in Hong Kong by PSC Section in June 2010

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8109814	FLINT RIVER	Dominica	1981	682	Offshore service vessel	American Bureau of Shipping	American Bureau of Shipping	Shipping-China Oilfield Services Ltd	25/06/10	---	RADIOCOMMUNICATIONS: maintenance/duplication of equipment, valid GMDSS shore based maintenance agreement not found. (Note: name of owner or management company in existing agreement different from actual.), operation/maintenance, VHF DSC radio function test failed & MF/HF DSC radio not receiving acknowledgement from HKMRCC. (Note: There is not previous record of successful function test.)
2	8010025	WHITE RIVER	Dominica	1980	701	Offshore service vessel	American Bureau of Shipping	American Bureau of Shipping	Shipping-China Oilfield Services Ltd	25/06/10	---	SAFETY OF NAVIGATION: echo-sounding device, echo sounder out of order; RADIOCOMMUNICATIONS: operation/maintenance, MF/DSC testing for transmitting with HKMRCC but not capable of receiving reply acknowledge

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.