

## Ships detained in Hong Kong by PSC Section in January 2012

No.	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8223804	HARVESTS	Panama	1982	1238	Refrigerated cargo carrier	Panama Bureau of Shipping	Panama Bureau of Shipping	Harvests Shipping Co SA	05/01/12	11/01/12	SHIP'S CERTIFICATES AND DOCUMENTS: minimum safe manning document, lack of one Engineer Officer as per MSMC; LIFESAVING APPLIANCES: rescue boat engine failed to start during inspection, other, three 2-way portable GMDSS radios not working; RADIOCOMMUNICATIONS: facilities for reception of marine safety information, NAVTEX, no received information found on board, facilities for reception of marine safety information, EGC system not working, last message received on 14.10.2011; ISM RELATED DEFICIENCIES: master's responsibility and authority, items no. 8, 9, 10, 12, 13, 14, 15 revealed the safety management system not properly implemented on board.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.