

Ships detained in Hong Kong by PSC Section in April 2012

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9017032	SCI PRESTIGE	United Kingdom	1991	43213	Container	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Zodiac Maritime Agencies Ltd	19/04/12	19/04/12	FIRE SAFETY : International shore-connection/shipboard international shore connection is not correct type, fixed fire extinguishing installation/CO ₂ system storage room more than 8 light bulbs out of work, em'cy lighting not working, release station dark, no backup lighting, insufficient lighting for operation, fixed fire extinguishing installation/paint locker water sprinkler cannot deliver any water
2	9073177	CHU HONG	Panama	1994	7828	General cargo/ multipurpose	China Classification Society	China Classification Society	Shun Fa Shipping Co Ltd	23/04/12	25/04/12	FIRE SAFETY : fixed fire extinguishing installation/one fire hydrant at e/r tanktop floor seized, unable to open by crew; SAFETY OF NAVIGATION: nautical publications/BA chart 4121, NP 30 for current and next voyage expired; POLLUTION PREVENTION : MARPOL Annex V/garbage/poor garbage management, unclassified waste mixed together, only one entry in garbage record book since 22/Nov/2011, personnel not familiar with garbage disposal
3	9376141	TS PUSAN	Antigua and Barbuda	2007	26435	Container	Germanischer Lloyd	Germanischer Lloyd	Reederei Rudolf Schepers Gmbh & Co. Kg	24/04/12	24/04/12	EMERGENCY SYSTEMS: emergency source of power - emergency generator/emergency generator out work by manual; ISM : maintenance of the ship and equipment/SMS does not ensure the vessel can be effectively maintained as evidence by above relative deficiencies; LIVING AND WORKING CONDITIONS : working conditions/electrical/440V insulation low alarm found in E.G.R.
4	7709394	AN SHENG	Honduras	1978	1594	Container	Other	Other	Holy Success Investment Development Ltd.	27/04/12	04/05/12	SAFETY OF NAVIGATION: gyro compass/gyro compass not working, charts/HK0803, HK1501 not update to new edition, others no correction, echo sounder/echor sounder not working, radar/radar not working, voyage or passage plan/passage plan not available; LIFE SAVING APPLIANCES: lifeboats/life boat engine testing failure; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water seperator is not working; LIVING AND WORKING CONDITIONS : working conditions/cleanliness of engine room/e/r, large amount of oily water found in bottom; CERTIFICATE AND DOCUMENTATION: documents/oil record book/oil record book not available since year 2002; FIRE SAFETY : fire fighting equipment and appliances/3 fire hose broken, nuzzle seized

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.