

Ships detained in Hong Kong by PSC Section in May 2012

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8810401	FEN JIN 2	Panama	1989	2561	General cargo/ multi-purpose Ship	Panama Maritime Documentation Services	Panama Maritime Documentation Services	Ocean Grow International Shipmanagement Consultant Corp.	02/05/12	04/05/12	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: ship certificates/safety management certificate (SMC/ISM)SMC expired on 03/Nov/2011. Master cannot explain, crew certificates/manning specified by the minimum safe manning doc/not sufficient manning according to MSMC (chief off & one AB absent); FIRE SAFETY: ventilation/ E/R ventilators wire screens lost, closing device seized, international shore-connection/international shore connection n/a onboard, fire doors/openings in fire-resisting divisions/several fire doors inaccommodation missing: WATER/WEATHERTIGHT CONDITIONS: ventilators, air pipes, casing/2 ventilators of no. 2 cargo hold corroded & holed; ventilators, air pipes, casing/2 ventilators of f.p. holed; POLLUTION PREVENTION - MARPOL ANNEX IV/other (MARPOL Annex IV)/sewage directly discharged overboard through by-pass valve
2	7378250	ROYAL PEARL	Panama	1974	633	Tugboat	Registro Italiano Navale	Registro Italiano Navale	HMC Co., Ltd.	17/05/12	18/05/12	SAFETY OF NAVIGATION: charts/BA charts 937, 3026 old edition (voyage charts), no updated Hongkong port charts onboard, nautical publications/no updated notice to mariner onboard, last ntm was week 3 2012
3	9161443	LIAN FA	Kiribati	1996	4151	Container Ship	International Ship Classification	International Ship Classification	Ningbo Shanglun Ship Management Co Ltd	21/05/12	23/05/12	CERTIFICATE AND DOCUMENTION - DOCUMENTS: Oil record book/oil record book not available on board, ISM/Shipboard operations/officers not familiar with GMDSS reserved power operation, POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixture from machinery spaces/insufficient cleanliness of engine-room, excess amount of oily-water (50cm) mixture in main engine case and tank top
4	7920792	SHUN HE	Sierra Leone	1979	1277	Refrigerated Cargo Ship	Overses Marine Certification Services	Overses Marine Certification Services	Hongying Shipping Management Co., Ltd.	25/05/12	29/05/12	FIRE SAFETY: ready availabilty of fire fighting equipment/two (2) fire hose boxes and nozzles missing, another two (2) hoses leaking at test; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery space/ E/R large amount of oily water at bottom, E/R and steering gear room oily dirty; RADIO COMMUNICATIONS: facilities for reception of marine safety inform./NAVTEX not working; SAFETY OF NAVIGATION: charts/charts not update, ship has no chart correction management, no updated charts for intended voyage, a lot of photo copy charts found on board: WATER/WEATHER CONDITIONS: copy charts found on board; WATER/WEATHERTIGHT CONDITIONS: cargo & other hatchways/access hatch opening to E/R on poop deck cannot be closed watertightly, bolt missing, cargo & other hatchways/access hatch opening to bosun store at bow cannot be closed watertightly, bolt missing,dooe/two (2) water tight doors on deck cannot be closed watertightly

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.