

Ships detained in Hong Kong by PSC Section in August 2012

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9167461	KANWAY GLOBAL	Taiwan, China	1997	18502	Container	China Corporation Register of Shipping	China Corporation Register of Shipping	China Famous Co Ltd	14/08/12	15/08/12	POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/engine room, a large amount of oily water accumulated; RADIO COMMUNICATIONS: maintenance/duplication of equipment/MF/HF radio DC power supply not working
2	7702255	PFS VAMANA	India	1981	41671	Bulk carrier	Indian Register of Shipping	Indian Register of Shipping	PFS Shipping (India) Ltd	20/08/12	04/09/12	CERTIFICATE AND DOCUMENTATION: ship certificates/safety management certificate (SMC/ISM)/ship's SMC expired on 4/6/2012, ship certificates/international ship security certificate/ship's ISSC expired on 4/6/2012; ISM: shipboard operations/reserved power of GMDSS operation not familiar by all GMDSS operators; WATER/WEATHERTIGHT CONDITIONS: railing, gangway, walkway and means for safe passage/main deck, more than 8 sections of upmost handrail missing or broken; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage treatment plant/sewage treating plant, direct overboard discharging valve not closed blowing air gauge defective; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/e/r tank top about 15cm of oily water accumulated
3	9233600	PAX PHOENIX	Panama	2001	28021	Bulk carrier	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	MMS CO LTD	21/08/12	23/08/12	FIRE SAFETY : fixed fire extinguishing installation/CO2 pipe lines for cargo holds on main deck corroded seriously, some part broken
4	9167851	PACIFIC EXPRESS	Vietnam	1997	8333	Container	Vietnam Register of Shipping	Vietnam Register of Shipping	GEMADEPT Corp (Cong Ty Co Phan Dai Ly Lien Hiep Van Chuyen)	23/08/12	23/08/12	EMERGENCY SYSTEMS: emergency source of power - emergency generator/emergency generator not started by second mean; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/e/r tank top, 70cm oil water accumulated; FIRE SAFETY: fire doors/openings in fire-resisting divisions/e/r entrance fire doors kept open
5	9587946	WINPOSH RESOLVE	Indonesia	2009	2588	Offshore supply	American Bureau of Shipping	American Bureau of Shipping	PT Wintermar Offshore Marine	31/08/12	- - -	CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: other (certificates)/ship's radio station licence not available, continuous synopsis record/CSR not available; SAFETY OF NAVIGATION: long-range identification and tracking system (LRIT)/LRIT information (ship's name, call sign, MMSI, etc.) not updated after re-flag & renamed; POLLUTION PREVENTION - MARPOL ANNEX IV: other (MARPOL Annex IV)/sewage discharged into the sea directly; FIRE SAFETY: fire doors/openings in fire-resisting divisions/all fire-doors in accommodation and e/r kept open by hold back hooks

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.