

Ships detained in Hong Kong by PSC Section in August 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8223804	HARVESTS	Panama	1982	1238	Refrigerated cargo	Panama Maritime Documentation Services	Panama Maritime Documentation Services; Panama Bureau of Shipping	Ocean Grow International Shipmanagement Consultant Corp	07/08/13	21/08/13	SAFETY OF NAVIGATION: speed and distance indicator/speed and distance measuring device (through the water) was not available on board as required by form E of cargo ship safety equipment certificate; RADIO COMMUNICATIONS: MF/HF radio installation/MF/HF radio was not working; POLLUTION PREVENTION - MARPOL ANNEX I: oil and oily mixtures from machinery spaces/large amount of oil and oily mixture in bilges of machinery space (one meter in depth on tank top); FIRE SAFETY: fire doors/openings in fire-resisting divisions/fire door from e/r to steering gear room without lock/handle and self-closing device; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificates for master and officers/chief engineer was holding certificate with limitation for "near coastal voyage" which did not meet the requirement of minimum safe manning document for "worldwide trade" service
2	8223232	HUADA	Liberia	1983	1449	Offshore supply	Det Norske Veritas	Det Norske Veritas; Russian Maritime Register of Shipping	Hermes Maritime Services Pvt Ltd	19/08/13	23/08/13	CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: safety management certificate (SMC/ISM)/SMC not available, international ship security certificate/ISSC not available; FIRE SAFETY: remote means of control (opening, pumps, ventilation, etc.) machinery spaces/M/E D.O. service tank remote closing valve not working; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water separator, system inoperative
3	8617732	SINGMA TRADER	Mongolia	1987	1660	General cargo/ multipurpose	Singclass International	Singclass International	Singma Trader S.A	26/08/13	06/09/13	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: manning specified by the minimum safe manning doc/short of one navigational watching officer as per MSMC; FIRE SAFETY: fire pumps and its pipes/emergency fire pump connection not matching hose and failed to delivery water, fire doors/openings in fire-resisting divisions/E/R skylight cover packing damaged, deformed, fails to close tightly, ventilation/E/R funnel vent cover seized, unable to be closed by crew; fire detection and alarm system/bridge, fire detection system defective; LIVING AND WORKING CONDITIONS : working conditions/cleanliness of engine room/engine room oily and dirty found in following locations : M/E feeder oil system station, M/E water cooler, purifier station, fo transfer pump station, and E/R tank top, around 50cm in depth oily water; LIFE SAVING APPLIANCES: distress flares/bridge rocket parachute signals expired, lifebuoys incl. provision and disposition/bridge wing MOB smoke signal damaged and expired, rescue boats/rescue boatengine failed to start during inspection; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage treatment plants/sewage treating plant inoperative; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/oily water separator not working; SAFETY OF NAVIGATION: charts/Hong Kong port charts BA 4127,4121, 4119 and intended voyage chart 937 N/A, nautical publications/ notice to mariners 2013, IAMSAR vol III, updated NP286(6) N/A

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.