## **Ships detained in Hong Kong by PSC Section in November 2013**

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9279214	BIENDONG MARINER	Vietnam	2002	9503	Container	Vietnam Register of Shipping	Vietnam Register of Shipping; Germanischer Lloyd	Bien Dong Shipping Co Ltd (Bien Dong)	20/11/13	21/11/13	LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: cleanliness of engine room/oily dirty found in location of H.F.O. trans pump, m/e casing, e/r tank top, generarator & steering gear flat; FIRE SAFETY: fire doors/openings in fire-resisting divisions/numerous fire doors self-closing devices not working properly; RADIO COMMUNICATIONS: MF/HF radio installation/radio station, GMDSS MF/HF ac power supple not working
2	8974996	LI SHENG	Mongolia	1989	448	Refrigerated cargo	Sing-Lloyd	Sing-Lloyd	N/A	22/11/13		CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for rating for watchkeeping/short of one engine rating as required by MSMC; CERTIFICATE AND DOCUMENTATION - DOCUMENTS: SOPEP/SOPEP not available as required by IOPP certificate; WATER/WEATHERTIGHT CONDITIONS: railing, gangway, walkway and means for safe passage/main deck port side aft, hand rail damaged about 4 meters, doors/forward store room weather-tight door could not be properly closed

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.