

Ships detained in Hong Kong by PSC Section in April 2014

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8891297	DOUBLE HAPPINESS I	Panama	1994	2752	Container	Overseas Marine Certification Services	Overseas Marine Certification Services	Hong Chuan International Logistics Co Ltd	10/04/14	17/04/14	CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: document of compliance (DoC/ISM)/company DOC copy not available onboard; CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: endorsement by flagstate/2nd engineers CoC flag state endorsement n/a; LIFE SAVING APPLIANCES: line-throwing appliance/bridge 8 pcs rocket parachute flares and 2 line throwing apparatuses expired; WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/all hatch cover cleats missing, some snugs and crutches corroded and thinned, ventilators, air pipes, casings/forecastle port and sbd air-vent closure corroded with wide gap; ALARMS: boiler alarm/boiler ignited by naked fire manually, flame failure alarm test failure, safety valve corroded seriously
2	9499632	HOANG LONG 68	Vietnam	2007	2551	General cargo/multipurpose	Vietnam Register of Shipping	Vietnam Register of Shipping	Son Vinh Chung Shipping Company Limited	10/04/14	17/04/14	SAFETY OF NAVIGATION: voyage or passage plan/voyage plan from Zhanjiang to Hong Kong did not include BA chart 4122, 4121, 4119 and sufficient information as per IMO circular/guideline for safe navigation, echo sounder/echo sounder defective; EMERGENCY SYSTEMS: emergency, lighting, batteries and switches/two batteries in battery room defective; WATER/WEATHERTIGHT CONDITIONS: manholes/flush scuttles/apt, two manholes not secured by bolts/nuts; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/engineer unable to demonstrate the testing and operation of oily water separator
3	9081203	JADE	Sierra Leone	1995	53519	Container	International Register of Shipping	International Register of Shipping	Prayati Shipping Pvt Ltd	14/04/14	15/04/14	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: endorsement by flagstate/all officer and engineer without flag state CoC endorsement, manning specified by the minimum safe manning doc/short of one MSMC required engineer officer; CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: continuous synopsis record/no any ship CSR documents available onboard
4	9161443	QI DA HAO	Belize	1996	4151	Container	New United International Marine Services Ltd	New United International Marine Services Ltd; Panama Bureau of Shipping; Belize Maritime Bureau Inc.	Ocean Grow International Shipmanagement Consultant Corp	22/04/14	---	FIRE SAFETY: fire detection and alarm system/fire detection and alarm system not working properly, oil accumulation in engine room/engine room tank top oily water accumulated 20cm in depth; SAFETY OF NAVIGATION: charts/voyage charts BA4127 small correction not updated since year 2012, BA937, 1962 not available; WATER/WEATHERTIGHT CONDITIONS: cargo ports and other similar openings/cargo hold hatch cover locking cleats more than 5 ea malfunction; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: cleanliness of engine room/engine room serious oily dirty found at place of generator, main engine, purifier and all floor plat
5	8414221	SEA DRAGON	Thailand	1983	5463	General cargo/multipurpose	Thailand	Thailand; Nippon Kaiji Kyokai	Sinsimon Navigation Co Ltd	23/04/14	24/04/14	ISM: resources and personnel/from the evidences above, the SMS on board not implemented effectively as per ISM code requirement; EMERGENCY SYSTEMS: emergency, lighting, batteries and switches/all emergency batteries found S.G low (1.175-1.20)

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.