

Ships detained in Hong Kong by PSC Section in January 2015

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9161443	QI DA HAO	Belize	1996	4151	Container	New United International Marine Services Ltd.	New United International Marine Services Ltd.	Ocean Grow International Shipmanagement Consultant Corp	02/01/15	15/01/15	FIRE SAFETY: fire-dampers/fire damper, for e/r ventilator unable to close; LIFE SAVING APPLIANCES: lifeboats (starboard) engine unable to engage to propeller and steering/rudder failed to move; WATER/WEATHERTIGHT CONDITIONS: cargo ports and other similar openings/no. 1 cargo hold man hatch cover and forcle store mooring line hatch failed to close; EMERGENCY STSTEMS: emergency fire pump and its pipes/emergency fire pump failed to deliver water to fire main, fire hoses leaking seriously
2	9149988	CHUN SHING	Belize	1995	4265	Container	New United International Marine Services Ltd.	New United International Marine Services Ltd.	Ocean Grow International Shipmanagement Consultant Corp	02/01/15	17/01/15	LIFE SAVING APPLIANCES: lifeboats/s side lifeboat engine start by battery b failure, search light unlit, callsign and reflective tape deteriorated; STRUCTURAL CONDITIONS: closing devices/watertight doors/numerous weather tight doors unable to be closed properly; FIRE SAFETY: ventilation/numerous accommodation ventilation cover and b/f nuts seized, fire fighting equipment and appliances/2nd deck aft one fire hydrant valve seized; WATER/WEATHERTIGHT CONDITIONS: cargo & other hatchways/cargo hold no. 1 hatchway cover b/f nuts missing, bolts seized, ventilators, air pipes, casings/cargo hold no. 1 vent closing device close/open handle missing, all other vent closing devices malfunction due to mushroom head hit off or unapproved cover installed or handle seized, covers (hatchway-, portable-, tarpaulins, etc.)/rubber packing for all cargo hold hatch cover not available, some parts of hatch cover bent or damaged, unable to be weather tight
3	9265586	DOLPHIN STRAIT	Antigua and Barbuda	2002	9966	Container	Det Norske Veritas	Det Norske Veritas	Carsten Rehder Schiffsmakler und Reederei GmbH & Co KG	06/01/15	13/01/15	FIRE SAFETY: fire pumps and its pipes/emergency fire pump motor burnt, spare is ordered; LIFE SAVING APPLIANCES: rescue boats/rescue boat engine cannot start
4	9158783	FU YUN	Panama	1997	4165	Container	Panama Shipping Registrar Inc.	Panama Shipping Registrar Inc.; Overseas Marine Certification Services	Sun Rising Shipmanagement Co Ltd	09/01/15	13/01/15	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for rating for watchkeeping/MSM certificate required 3 duty AB, one AB CoC expired on 14/12/2014, manning specified by the minimum safe manning doc/M5 MSM certificate required master, c/o, 2/e, signed off before substitute onboard; FIRE SAFETY: fire detection and alarm system/fire detection and alarm system switched off, fault indicated for zone 3, DC power supply malfunction, some switch on control panel defective; RADIO COMMUNICATIONS: MF/HF radio installation/MF/HF DSC radio emergency power supply defective; LIFE SAVING APPLIANCES: lifeboats/free fall lifeboat engine start test by second battery failure; ISM: maintenance of the ship and equipment/6. according to the above listed items, shipboard ISM system not effective implemented, classification society additional audit to be carried out before departure

5	9302293	RICH OCEAN	Panama	2003	2499	General cargo/ multipurpose	Intermaritime Certification Services, ICS Class	Intermaritime Certification Services, ICS Class	Yantai Rich Marine International Shipping Management Co Ltd	15/01/15	16/01/15	CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATES: other (certificates)/ship radio station license expired on 22/12/2014, no valid license available; SAFETY OF NAVIGATION: charts/no valid voyage charts available onboard for previous and intended voyage; WATER/ WEATHERTIGHT CONDITIONS: windows, sidescuttles and deadlights/numerous sidescuttles in galley, mess room unable to be closed weathertight due to securing bolts missing or seized, and glass broken
6	8132835	TAE RYONG GANG	Korea, Democratic People's Republic of	1978	9145	General cargo/ multipurpose	Korea Classification Society	Korea Classification Society	Yongjin Ship Management Co Ltd	19/01/15	30/01/15	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for medical care/three crew members (d/rating, e/officer and purser) medical fitness certificates missing; SAFETY OF NAVIGATION: charts/no sufficient Hong Kong sea charts on board, signalling lamp/no spare lamp bulbs for portable signal light, lights, shapes, sound-signals/12-off hand flare (expiry 11.2014) was out dated; WATER/WEATHERTIGHT CONDITIONS: covers (hatchway-, portable-, tarpaulins, etc.)/several butterfly nuts for engine room skylight and roof top fire damper doors were missing, covers (hatchway-, portable-, tarpaulins, etc.)/all cleats for watertight hatch covers for all cargo hold missing; LIFE SAVING APPLIANCES: lifeboat inventory/all water bags in life boat (expiry 6.2014) was out dated; CERTIFICATE AND DOCUMENTATION - SHIP CERTIFICATE: document of compliance (DoC/ISM)/document of compliance (expiry 8.11.14) was out dated
7	9242613	STAR PLANET	Antigua and Barbuda	2000	6277	Container	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Coral Shipmanagement GmbH & Co KG	20/01/15	21/01/15	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: endorsement by flagstate/chief engineer, CoC flag endorsement expired on 18/10/2014, no evidence showing application made to extend the flag endorsement; SAFETY OF NAVIGATION: echo sounder/echo sounder large error (about 5 meters) found existed always
8	9203461	OTTO	Liberia	1999	20624	Container	Registro Italiano Navale	Registro Italiano Navale; Lloyd's Register	Naess Ship Management BV	21/01/15	23/01/15	SAFETY OF NAVIGATION: navigation bridge visibility/two sets of wiper (4 off) out of order; LIFE SAVING APPLIANCES: lifeboats/s/b side life boat no. 2 battery could not start the main engine; LIVING AND WORKING CONDITIONS - LIVING CONDITIONS: cold room/alarm of cold store in bridge out of order; FIRE SAFETY: operation of fire protection systems/heat and smoke detectors in engine room out of order; POLLUTION PREVENTION - MARPOL ANNEX I: 15 ppm alarm arrangements./oily water separator was defective and out of order; WATER/WEATHERTIGHT CONDITIONS: railing, gangway, walkway and means for safe passage/p & s side handrails for crew protection on life boat deck missing
9	9114517	UNIRICH	Belize	1994	5552	General cargo/ multipurpose	Intermaritime Certification Services, ICS Class	Intermaritime Certification Services, ICS Class	Sinounion Shipping Service Ltd	26/01/15	30/01/15	SAFETY OF NAVIGATION: voyage or passage plan/previous passage plan from Kaohsiung to Hong Kong not available; EMERGENCY STSTEMS: emergency fire pump and its pipes/emergency fire pump unable to delivery sufficient water to deck; LIVING AND WORKING CONDITIONS - WORKING CONDITIONS: protection machinery/boiler safety valve manual operation wire not installed; POLLUTION PREVENTION - MARPOL ANNEX IV: sewage treatment plant/sewage treatment plant malfunction; FIRE SAFETY: ventilation/cargo hold vent closing devices defective

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.