

Ships detained in Hong Kong by PSC Section in Oct 2015

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9363962	HANSE ENERGY	Antigua and Barbuda	2007	9610	Container	Germanischer Lloyd	Germanischer Lloyd	Johs Thode GmbH & Co KG	5/10/2015	9/10/2015	ISM: ENCLOSED SPACE DRILL, PREPARATION FOR ENTRANCE AND OPERATION AND RESCUE, NOT FAMILIARISED BY SHIPS CREW, FIRE SAFETY: TESTED THREE (3) VENTILATORS FOR E/R, FAILED TO CLOSE AFTER ONE HOUR AND REINSPECTED,
2	9350109	YUSHO LILY	Panama	2004	6004	General cargo/multipurpose	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Grow-Will Inc	28/10/2015	30/10/2015	EMERGENCY SYSTEMS: RESPONSIBLE OFFICER/CREW NOT FAMILIAR WITH THE USE OF GAS DETECTOR AND SCBA FOR ENTERING ENCLOSED SPACE AND EMERGENCY, RADIO COMMUNICATIONS: MF/HF RADIO, NO SUCCESSFUL SHIP-SHORE TEST/ DEFECTIVE, FIRE SAFETY: FIRE DETECTOR DEFECTIVE, AND TEST KIT NOT AVAILABLE, EMERGENCY SYSTEMS: ENCLOSED SPACE DRILL NOT PLANNED AND CONDUCTED AS PER REQUIREMENT, (I.E.VENTILATION, COMMUNICATION, CHECKING OF ATMOSPHERE, NOT AWARE OF RISK AND NO RESPONSE FOR VICTIM INSIDE ENCLOSED SPACE, EQUIPMEN.
3	9392913	LANTAU BREEZE	Antigua and Barbuda	2007	9610	Container	Nippon Kaiji Kyokai	Germanischer Lloyd	Kopping Reederei GmbH & Co KG	30/10/15	30/10/15	LIFE SAVING APPLIANCES: THE ENGINE OF S SIDE LIFEBOAT COULD NOT START..

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.