

### 3. Ships detained in Hong Kong by PSC Section in October 2016

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8622660	HOCKIN	Sierra Leone	1983	1923	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Chun Xin Shipping Co Ltd	07.10.2016	14.10.2016	<b>STRUCTURAL CONDITIONS:</b> PORT SIDE HULL (STERN, STEERING GEAR ROOM ABOVE LOADLINES) DAMAGED (ABOUT 1 M X 1 M) WITH A HOLE ABOUT 6 CM X 1 CM, AND ATTACHED FRAME MEMBERS DEFORMED, <b>SAFETY OF NAVIGATION:</b> ECHO SOUNDER MALFUNCTION, <b>SAFETY OF NAVIGATION:</b> ONE RADAR MALFUNCTION, <b>CERTIFICATE &amp; DOCUMENTATION:</b> NO FLAG ENDORSEMENTS FOR 2/O AND 3/E, <b>LIFE SAVING APPLIANCES:</b> RESCUE BOAT DAVIT, HOLDING CHAINS CORRODED, 1/2 SIZE OF THE CHAINS RUSTED OFF,

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.