Ships Detained in Hong Kong Due to PSC Inspection in December 2024

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
586	8743531	BROTHER 36	Panama	22.10.2007	2,930	General cargo / multipurpose	Panama Maritime Documentation Service (PMDS)	I I IOCI IMANTATION	CGW LOGISTICS CO LIMITED	13.12.2024	20.12.2024	1.Current voyage use of photocopy chart BA 1716 for navigation and lack of nautical charts for entering Hong Kong, at least short of BA 4127, 4129. 2.All two-way VHF radiotelephone were found battery expired and low battery at test. 3.Both sides lifeboat engines were not working properly, cannot engage in ahead and astern propulsion by the engine control lever, in addition, the starboard lifeboat battery failed. 4. Ship ISM implementation was failure to ensure safe operation and proper maintenance of the ship with objective evidence as detected deficiencies.