SHIPS UNDER PORT STATE CONTROL DETENTION IN HONG KONG IN JULY 2002

No.	IMO Number	Ship Name	Flag	Year of Build	Gross Tonnage	Ship Type	Classification Society	Ship Company	Port of Detention	Date of Detention	Date of Release	Nature of Major Deficiencies (responsible RO, if any)
1	9010022	THAI JASMINE	Thailand	1991	5551	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Toko Kaiun Kaisha Ltd.	Hong Kong, China	4-Jul-02	5-Jul-02	ISM RELATED DEFICIENCIES - maintanance of ship and equipment; emergency preparedness.
2	9165059	SUN FRONTIER	Panama	1997	6870	General Cargo	Nippon Kaiji Kyokai	Noma Shipping Co. Ltd.	Hong Kong, China	5-Jul-02	6-Jul-02	ISM RELATED DEFICIENCIES - resources and personnel; company responsibility and authority; masters resposibility and authority.
3	9227041	DERYOUNG SUNSHINE	Panama	1999	6354	General Cargo	Nippon Kaiji Kyokai	D. & S. Co. Ltd. Kaohsiung Office	Hong Kong, China	5-Jul-02	5-Jul-02	ISM RELATED DEFICIENCIES - company verification, review and evaluation. SOLAS RELATED OPERATIONAL DEFICIENCIES - lifeboat drill.
4	9159098	ERAWAN BRIDGE	Panama	1997	11810	Container Ship	Nippon Kaiji Kyokai	Ehime Kaiun Co. Ltd.	Hong Kong, China	8-Jul-02	8-Jul-02	LIFESAVING APPLIANCES - lifeboat inventory. MARPOL ANNEX I - oily water separator. ISM RELATED DEFICIENCIES - emergency preparedness.
5	8417912	MMM HOUSTON	Malaysia	1985	4509	chemical tanke	Det Norske Veritas	Malaysia Merchant Marine Berhad	Hong Kong, China	9-Jul-02	10-Jul-02	FIRE FIGHTING MEASURES - fire fighting equipment and appliances, fire pumps, ventilation, fire-dampers, valves, quick closing devices, means of control. ISM RELATED DEFICIENCIES - emergency preparedness.
6	8812887	UNICORN JOY	Panama	1990	2854	general cargo/multi- purpose ship	Lloyd's Register of Shipping	Well Ship Management and Maritime Co. Ltd	Hong Kong, China	12-Jul-02	12-Jul-02	ISM RELATED DEFICIENCIES, emergency preparedness, company verification, review and evaluation, masters resposibility and authority.
7	8125650	GUAN HORNG	Taiwan, China	1981	2998	General Cargo	China Corporation Register of Shipping	Len Chen Navigation Co. Ltd.	Hong Kong, China	12-Jul-02	12-Jul-02	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS - absence of radio personnel. SOLAS RELATED OPERATIONAL DEFICIENCIES - fire control plan. FIRE FIGHTING MEASURES, fire fighting equipment and appliances, ventilation, fire-dampers, valves, quick closing devices, means of control, engine room quick closing valves.
8	9016179	HORNED OWL	Panama	1991	4382	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Maki Shokai Co. Ltd	Hong Kong, China	16-Jul-02	17-Jul-02	LIFESAVING APPLIANCES - lifeboat engine; boat hook. ISM RELATED DEFICIENCIES - emergency preparedness
9	7928744	HUB ARCHIVER	Malaysia	1980	5378	general cargo/multi- purpose ship	Germanischer Lloyd	Hub Marine PTE. Ltd	Hong Kong, China	17-Jul-02	18-Jul-02	LIFESAVING APPLIANCES - lifeboat engine; fuel oil tank pv vent valve (RO); lifebuoy self-ignition light. FIRE FIGHTING MEASURES - fire fighting equipment and appliances. RADIOCOMMUNICATIONS - reserve battery.
10	8202501	WOOYANG IVORY	Korea, Republic of	1981	3892	general cargo/multi- purpose ship	Korean Register of Shipping	Korea Ship Managers Co., Ltd	Hong Kong, China	17-Jul-02	18-Jul-02	LIFESAVING APPLIANCES, embarkation arrangements for survival craft; lifeboat inventory. FIRE FIGHTING MEASURES - fixed fire extinguishing installation
11	9074444	WAN HAI 222	Singapore	1994	16911	container ship	American Bureau of Shipping	Wan Hai Lines Ltd	Hong Kong, China	17-Jul-02	18-Jul-02	LIFESAVING APPLIANCES - line throwing appliance.
12	9197636	ULSWATER	Panama	1997	4769	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	B&S Enterprise Co., Ltd	Hong Kong, China	22-Jul-02	24-Jul-02	FIRE FIGHTING MEASURES - ventilation, fire-dampers, valves, quick closing devices, means of contro, fire pumps. ISM RELATED DEFICIENCIES - masters resposibility and authority, emergency preparedness, maintanance of ship and equipment

No.	IMO Number	Ship Name	Flag	Year of Build	Gross Tonnage	Ship Type	Classification Society	Ship Company	Port of Detention	Date of Detention	Date of Release	Nature of Major Deficiencies (responsible RO, if any)
13	9182019	ACE CONTAINER	Singapore	1998	17609	container ship	American Bureau of Shipping	Kien Hung Shipping Co. Ltd	Hong Kong, China	24-Jul-02		ISM RELATED DEFICIENCIES - emergency preparedness, masters responsibility and authority, company verification, review and evaluation.
14	9127540	WESTEREMS	Liberia	1997	23896	container ship	Germanischer Lloyd	Hans Peterson & Sohne GmbH & Co KG	Hong Kong, China	24-Jul-02		ISM RELATED DEFICIENCIES - emergency preparedness. SOLAS RELATED OPERATIONAL DEFICIENCIES - operation of machinery
15	8309426	BENARITA	Norway	1984	23594	bulk carrier	Det Norske Veritas	Ugland Marine Se	Hong Kong, China	29-Jul-02	2-Aug-02	PROPULSION AND AUXILIARY MACHINERY - boilers. LIFESAVING APPLIANCES - lifeboats. SAFETY OF NAVIGATION - charts
16	8312435	KITTY	Panama	1984	2669	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Shin Wei Navigation Co., Ltd.	Hong Kong, China	29-Jul-02	1-Aug-02	ISM RELATED DEFICIENCIES - masters resposibility and authority, emergency preparedness, maintanance of ship and equipment. LIFESAVING APPLIANCES - embarkation arrangements for survival craft
17	8025393	FU CHUN	Taiwan, China	1981	8078	container ship	China Corporation Register of Shipping	Wan Hai Lines Ltd	Hong Kong, China	29-Jul-02	30-Jul-02	RADIO COMMUNICATIONS - back-up power for radio installation. STABILITY, STRUCTURE AND RELATED EQUIPMENT - skylights casing. FIRE FIGHTING APPLIANCES - fire fighting equipment damaged, fuel oil remote control. ISM RELATED DEFICIENCIES - resources and personnel, documentation
18	7435060	ZOMING 1	Korea, Democratic People's Republic	1976	1233	general cargo/multi- purpose ship	Others	KOREA Zoming Shipping Company	Hong Kong, China	31-Jul-02	5-Aug-02	SAFETY OF NAVIGATION - charts. LOAD LINES - doors, hatch covers, ventilator covers, hatchway cover securing lugs. LIFESAVING APPLIANCES - lifeboat engine, lifeboat inventory, embarkation arrangements for survival craft, stowage of lifeboats, lifejackets. lifebuoy self-ignition light. RADIOCOMMUNICATIONS - main installation.

N.B. The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.

[PSC/Dentention]2002-07 Web]