

## Ships detained in Hong Kong by PSC Section in May 2003

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8200149	EVER GENTRY	Taiwan	1983	37023	container ship	China Corporation Register of Shipping	Evergreen Marine Corporation (Taiwan) Ltd.	03/05/03	03/05/03	LIFESAVING APPLIANCES: stowage of liferafts, RADIOCOMMUNICATIONS: functional requirements
2	9005259	P&O NEDLLOYD XIAMEN	Liberia	1990	36627	container ship	Det Norske Veritas	Zodiac Maritime Agencies	03/05/03	03/05/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and Officer
3	7426100	FANG GANG 8	Belize	1975	2453	Cement carrier	Panama Maritime Documentation Service Inc.	Guang Xi Fanggang Marine Co. Ltd.	04/05/03	05/05/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for radio personnel, RADIOCOMMUNICATIONS: functional requirements, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
4	8919001	ALBERTA	Cyprus	1991	21053	container ship	Germanischer Lloyd	Peter Dohle Schiffahrts-KG	09/05/03	09/05/03	SAFETY OF NAVIGATION: other (navigation), emergency steering gear test overdue, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and Officer
5	9196917	APL MALAYSIA	Liberia	2000	54415	container ship	Germanischer Lloyd	N.R.H.S. Gmbh & Co. KG	10/05/03	10/05/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS : certificates for Master and Officer
6	8503747	DONG YA NO. 8	Cambodia	1985	1123	general cargo/multi-purpose ship	Cosmos Bureau of Shipping Inc.	Jusheng Shipping Agency Ltd.	13/05/03	20/05/03	RADIOCOMMUNICATIONS: MF/HF radio installation, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and Officer, LIFESAVING APPLIANCES: lifebuoys, FIRE FIGHTING MEASURES : personal equipment, emergency escape breathing apparatus, international shore connection, ventilation, fire-dampers, valves, quick closing devices, means of control, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, LOAD LINES : other (load lines), ship side shell plate holed and stiffener buckle, ISM RELATED DEFICIENCIES : maintenance of the ship and equipment
7	7706770	FCC GLORY	Saint Vincent and the Grenadines	1977	6168	general cargo/multi-purpose ship	Bureau Veritas	Shenzhen Shun Xin Yuan Shipping Co. Ltd.	13/05/03	13/05/03	ISM RELATED DEFICIENCIES: company verification, review and evaluation, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, LIFESAVING APPLIANCES : lifeboats

8	8967436	FORERUNNER	Bolivia	1985	2958	general cargo/multi-purpose ship	Honduras/Horizon International Naval Surveying Inspection Bureau/Board	Heng Yuan International Shipping Co. Ltd.	15/05/03	21/05/03	LIFESAVING APPLIANCES: immersion suits, all immersion suit lights expired or no batteries, lifeboat inventory, port non-propelled lifeboat mast and sail were not found, FIRE FIGHTING MEASURES: personal equipment, all fire proved lights had no power or batteries, fire fighting equipment and appliances, fire nozzles on deck were stuck, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS : certificates for master and officer, stcw flag endorsement of C/E & 2/O were not on board, RADIOCOMMUNICATIONS: MF/HF radio installation, master and all officers failed to carry out dsc coast station test with MF/HF radio equipment
9	9202481	YM HAKATA	Singapore	1999	17167	container ship	Germanischer Lloyd	Navalloyd A.G. Reederei	15/05/03	16/05/03	RADIOCOMMUNICATIONS, MF/HF radio installation
10	9012836	UNI-CROWN	Taiwan	1991	12404	container ship	China Corporation Register of Shipping	Evergreen Marine Corporation (Taiwan) Ltd.	19/05/03	20/05/03	LIFESAVING APPLIANCES: on board training and instructions, rescue boat drill not carried out, operational readiness of lifesaving appliances, stb'd l/b : compass with bubbles, safety belt lock corroded, inventory not located properly, steering wheel hard to turn, operational readiness of lifesaving appliances, port L/B, steering wheel hard to turn, FIRE FIGHTING MEASURES: personal equipment, main & spare air bottles in rusty condition; personal equipment not in ready condition; torch missing; mask in dirty condition, international shore connection, bolts missing, RADIOCOMMUNICATIONS: functional requirements, DSC radio installation cannot be tested
11	8012889	VAN PHONG	Viet Nam	1983	8678	container ship	Viet Nam Register of Shipping	Vanlang Ship Management Company	19/05/03	19/05/03	LIFESAVING APPLIANCES: Inflatable liferafts, lifejackets, RADIOCOMMUNICATIONS : functional requirements, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, ISM RELATED DEFICIENCIES: maintainance of the ship and equipment
12	8602543	THIEN QUANG	Viet Nam	1985	4096	general cargo/multi-purpose ship	Viet Nam Register of Shipping	Northern Shipping Company	22/05/03	24/05/03	ISM RELATED DEFICIENCIES: Masters responsibility and authority, emergency preparedness, documentation, maintainance of the ship and equipment, company verification, review and evaluation, LIFESAVING APPLIANCES: on board training and instructions, MARPOL - ANNEX I : shipboard oil pollution emergency plan (SOPEP), no oil pollution drill, SAFETY OF NAVIGATION: lights, shapes, sound-signals, nautical publications, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, RADIOCOMMUNICATIONS: functional requirements
13	8311431	THOR SKIPPER	Thailand	1985	10572	general cargo/multi-purpose ship	Lloyd's Register of Shipping	Thoresen & Co. (Bangkok) Ltd.	22/05/03	22/05/03	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, LIFESAVING APPLIANCES: lifebuoys, inflatable liferafts, stowage of liferafts
14	8511328	HYUNDAI PIONEER	Bahamas	1986	39892	container ship	Det Norske Veritas	Jahre Malle AS	23/05/03	23/05/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control

15	7810894	OCEAN STARLIGHT	Liberia	1979	29873	container ship	American Bureau of Shipping	Yang Ming Marine Transport Corporation	25/05/03	25/05/03	LIFESAVING APPLIANCES: operational readiness of lifesaving appliances, STB lifeboat engine not run, FIRE FIGHTING MEASURES: fixed fire extinguishing installation, a door entrance from accommodation not gastight
16	8203854	SHENG LI	Panama	1982	3155	general cargo/multi-purpose ship	China Corporation Register of Shipping	Hansen Shipping Agencies Co. Ltd.	26/05/03	26/05/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and Officer, ISM RELATED DEFICIENCIES: Masters responsibility and authority, STABILITY, STRUCTURE AND RELATED EQUIPMENT: stability/strength/loading information and instruments, SAFETY OF NAVIGATION: nautical publications
17	7377830	CARINA 1	Panama	1973	10538	Cement carrier	Nippon Kaiji Kyokai	Cosmo Sealand Co. Ltd.	27/05/03	29/05/03	ISM RELATED DEFICIENCIES: emergency preparedness, FIRE FIGHTING MEASURES : ventilation, fire-dampers, valves, quick closing devices, means of control, fixed fire extinguishing installation
18	9070046	CONTI SINGAPORE	Germany	1993	16259	container ship	Germanischer Lloyd	Niederelbe Schifffahrtsgesellschaft mbH & Co. KG.	27/05/03	27/05/03	LIFESAVING APPLIANCES : on board training and instructions, rescue boat drill and emergency steering test overdue
19	8303927	SOLAR MARINER	Panama	1983	1735	Refrigerated cargo carrier	Nippon Kaiji Kyokai	Global Star (Asia) Ship Management	27/05/03	29/05/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and Officer, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, engine room fire dampers not able to close, pull cable broken, RADIOCOMMUNICATIONS: maintenance/duplication of equipment
20	9128489	EVER MIGHTY	Panama	1995	39376	Bulk carrier	Bureau Veritas	First Steamship Co. Ltd.	28/05/03	30/05/03	RADIOCOMMUNICATIONS : MF/HF radio installation
21	7718345	SAN FONG	Panama	1977	10489	general cargo/multi-purpose ship	China Corporation Register of Shipping	Unison Marine Corp.	28/05/03	28/05/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, LIFESAVING APPLIANCES: on board training and instructions

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.