

Ships detained in Hong Kong by PSC Section in November 2003

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7600225	ALLY II	Panama	1976	20594	bulk carrier	China Corporation Register of Shipping	Jackson Shipping Safety Management Consultant Co., Ltd.	01/11/03	01/11/03	FIRE FIGHTING MEASURES: fire prevention, fixed fire extinguishing installation, LOAD LINES: ventilators, air pipes, casings, STABILITY STRUCTURE AND RELATED EQUIPMENT: electric equipment in general.
2	8406793	SAGAING	Myanmar	1984	9990	general cargo/multi-purpose ship	Lloyd's Register of Shipping	Myanmar Five Star Line	01/11/03	03/11/03	LOAD LINES: other (load lines), steel plating next to stbd lifeboat holed, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, FIRE FIGHTING MEASURES: fire pumps, fire hoses and fire lines significantly leaking, readily availability of fire fighting equipment, CO ₂ room boundary plating holed, ISM RELATED DEFICIENCIES: Masters responsibility and authority, no evidence on board Master did Master review, resources and personnel.
3	8210900	GREAT PRIDE	Panama	1982	8062	Container ship	Korean Register of Shipping	SITC Ships Management Co., Ltd.	02/11/03	02/11/03	STABILITY, STRUCTURE AND RELATED EQUIPMENT: electric equipment in general, paint locker explosive proof light support found detached and the light held in position by its power supply cable, LOAD LINES: ventilators, air pipes, casings.
4	8821577	BAO HE	Panama	1989	4717	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	First Marine Service Co., Ltd.	05/11/03	05/11/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, LIFESAVING APPLIANCES: lifeboat inventory, searchlight not working, STABILITY, STRUCTURE AND RELATED EQUIPMENT: means of escape.
5	8404393	SOUTHERN ARROW	Cambodia	1984	3951	general cargo/multi-purpose ship	International Register of Shipping	Representative Office of Pamela Corporation in Viadivostok	07/11/03	08/11/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire fighting equipment and appliances, RADIOCOMMUNICATIONS: functional requireemnts.
6	8005020	SUNRISE I	Panama	1980	76104	bulk carrier	China Classification Society	Good Faith Shipping Co., Greece	09/11/03	10/11/03	BULK CARRIERS - ADDITIONAL SAFETY MEASURES: loading instrument, all ship loading computers (2 nos.) not approved.
7	8125650	GUAN HORNG	Taiwan	1981	2998	general cargo/multi-purpose ship	China Corporation Register of Shipping	Len Chen Navigation Co. Ltd.	09/11/03	12/11/03	SAFETY OF NAVIGATION: lights, shapes, sound-signals, both side lights casing badly corroded and not able to be mounted, LIFESAVING APPLIANCES: lifeboats, lifeboat engine not starting, stowage of lifeboats, stowage of liferafts, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, readily availability of fire fighting equipment, fixed fire extinguishing installation, cargohold CO ₂ line damaged; LOAD LINES: cargo and other hatchways; STABILITY, STRUCTURE AND RELATED EQUIPMENT: other (stability/structure), forepeak valve inoperable, all manhole bolts removed; PROPULSION AND AUXILIARY MACHINERY: other (machinery), aft mooring winch foundation excessively wasted; ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, the ship failed to be maintained in conformity with the provisions of rules and regulations, resources and personnel, development of plans for shipboard operations.
8	8921872	ORIENTAL GLORY	Belize	1990	2992	general cargo/multi-purpose ship	China Corporation Register of Shipping	Fu Sheng Shipping Safety Management Consultant Co., Ltd.	15/11/03	15/11/03	FIRE FIGHTING MEASURES: other (fire safety), both galley door not able to be closed. Jacketed pipng system for high pressure fuel lines.
9	8518778	ORIENTAL PROFIT	Panama	1986	2838	general cargo/multi-purpose ship	China Corporation Register of Shipping	Fu Sheng Shipping Safety Management Consultant Co., Ltd.	20/11/03	20/11/03	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer.

10	7709526	RUBIES	Saint Vincent and the Grenadines	1977	11036	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Treasure Target Ltd.	25/11/03	28/11/03	STABILITY, STRUCTURE AND RELATED EQUIPMENT: electric equipment in general, MARPOL: ANNEX I, oil filtering equipment, LIFESAVING APPLIANCES: lifeboats.
11	7708754	TIGER STAR	Cyprus	1977	14953	Container ship	Korean Register of Shipping	Varship Shipping Co. Ltd.	22/11/03	23/11/03	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, cargo hold ventilator closing devices seized.
12	8708555	VN SAPPHIRE	Vietnam	1987	11977	Container ship	Germanischer Lloyd	Vanlang Shipping Management Company	27/11/03	28/11/03	RADIOCOMMUNICATIONS: functional requirements, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, LIFESAVING APPLIANCES: stowage of liferafts.
13	9020015	JUPITER ACE	Panama	1991	5470	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Shinwa Marine Corporation, Japan	27/11/03	28/11/03	ISM RELATED DEFICIENCIES: documentation, filing system poor, e.g. Form R of SR Cert. missing, various service rpt./record related to ship's safety equipment not properly filed at relevant location, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, GMDSS officers not familiar with setting of AVTEX receiver, procedures to cancel false distress alert sent, and function tests on GMDSS equipment, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, oil tank air pipes wire mesh missing.
14	8631374	GOOD LUCK	Belize	1987	1101	general cargo/multi-purpose ship	BMBI	Good Luck Shipping S.A.	08/11/03		SOLAS RELATED OPERATIONAL DEFICIENCIES: fire control plan, manuals, instructions, muster list, etc., FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, RADIOCOMMUNICATIONS: MF/HF radio installation, SAFETY OF NAVIGATION: emergency steering position communications/compass reading, ISM RELATED DEFICIENCIES: certification, verification and control.
15	8805107	HUNG SHUN	Panama	1988	535	oil tanker	IRS	Kam Bao Shipping (HK) Co. Ltd.	13/11/03		FIRE FIGHTING MEASURES: personal equipment, fixed fire extinguishing installation, other (fire safety), aft pump room bulkhead, electrical wire penetration was not properly fitted, ventilation, fire-dampers, valves, quick closing devices, means of control, international shore connection, RADIOCOMMUNICATIONS: radar transponder, VHF EPIRB, other (radio), language of all gmdss equipment manual unknown to crew and procedures to cancel gmdss equipment false distress alert unknown to gmdss officers, MARPOL - ANNEX I: shipboard oil pollution emergency plan (SOPEP), LIFESAVING APPLIANCES: rescue boat inventory, maintenance and inspection, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, SOLAS RELATED OPERATIONAL DEFICIENCIES: fire control plan, LOAD LINES: ventilators, air pipes, casing.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.