Ships detained in Hong Kong by PSC Section in January 2004

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7512741	MARIBOR	Saint Vincent and the Grenadines	1976	12117	general cargo/multi- purpose ship	Croatian Register of Shipping	Splosna Plovba	06/01/04	06/01/04	RADIOCOMMUNCATIONS: reserve source of energy, LIFESAVING APPLIANCES: lifeboat inventory
2	8118669	INTER DAVID	Cambodia	1981	6686	bulk carrier	Nippon Kaiji Kyokai	Inter Shipping Co. Ltd.	08/01/04	08/01/04	FIRE FIGHTING MEASURES: fire fighting equipment and appliances, fire fighting equipment and appliances, ventilation, fire-dampers, valves, quick closing devices, means of control, LIFESAVING APPLIANCES: lifejackets
3	8808587	YM PEARL RIVER I	Marshall Islands	1989	18000	container ship	Germanischer Lloyd	NSB Niederelbe, Schiffahrtsges, mbH & CO. KG.	14/01/04	14/01/04	MARPOL - ANNEX I : oil/water interface detector, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer
4	9036868	JOLLY FALCON	Viet Nam	1991	3207	oil tanker	Viet Nam Register of Shipping	FALCON Shipping Company	15/01/04	19/01/04	LIFESAVING APPLIANCES: operational readiness of lifesaving appliances, 2 lifebuoys on poop deck (P&S) missing, on board training and instructions, responsible crew not familiar with lifeboat equipemnt operation, ISM RELATED DEFICIENCIES: documentation, nautical publications, certs, etc. not properly filed, controlled, updated, etc., reports and analysis of non- conformities, accidents and hazardous occurrences, no master review record on accidental cargo oil discharge on 4.1.2004, resources and personnel, crew generally not familiar with operation of emergency equipment onboard, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, radio officer not test the GMDSS equipment regularly, operation of GMDSS equipment, procedures to cancel false GMDSS distress alerts unknown to radio officer, SAFETY OF NAVIGATION: nautical publications, STABILITY, STRUCTURE AND RELATED EQUIPMENT: hydraulic and other closing devices/watertight doors, 3 fire doors for E/R no closed, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, air receiver for activating quick closing valve device not fully charged
5	7902922	YONGTONG	Panama	1979	1831	oil tanker	Isthmus Bureau of Shipping	East Harbour Navigation Co., Ltd.	15/01/04	29/01/04	FIRE FIGHTING MEASURES: personal equipment, fire fighting equipment and appliances, ventilation, fire-dampers, valves, quick closing devices, means of control, SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS functional requirements, LIFESAVING APPLIANCES: lifeboats, lifeboats
6	9149665	SIGRUN BOLTEN	Liberia	1997	19354	general cargo/multi- purpose ship	American Bureau of Shipping	Aug. Bolten/Wm. Miller's Nachf. (GmbH & Co.)	16/01/04	17/01/04	CERTFICICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, ISM RELATED DEFICIENCIES: company verification, review and evaluation
7	8323692	HILDA	Panama	1983	15045	bulk carrier	Nippon Kaiji Kyokai	Eternity Shipping Agencies Ltd.	17/01/04	17/01/04	LIFESAVING APPLIANCES: stowage of liferafts, ISM RELATED DEFICIENCIES: emergency preparedness, FIRE FIGHTING MEASURES: fire fighting equipment and appliances
8	8921482	VIHAN 05	Viet Nam	1989	5552	general cargo/multi- purpose ship	Viet Nam Register of Shipping	Viet Nam Shipping and Trading Co. Ltd.	19/01/04	19/01/04	FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, RADIOCOMMUNICATIONS: functional requirements

Ships detained in Hong Kong by PSC Section in January 2004

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
9	8708555	VN SAPPHIRE	Viet Nam	1987	11977	container ship	Germanischer Lloyd	Vanlang Ship Management Company	19/01/04	19/01/04	RADIOCOMMUNICATIONS: MF/HF radio installation
10	7912367	ZIM KEELUNG	Malta	1980	36263	container ship	Lloyd's Register of Shipping	OFER (Ships Holding) Ltd.	20/01/04	20/01/04	CERTFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for master and officer
11	8316273	SUPERIOR LEADER	Panama	1984	22009	bulk carrier	Det Norske Veritas	Serway Shipping Limited	26/01/04		FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire pumps, LIFESAVING APPLIANCES: lifeboat inventory, lifeboats
12	8631013	YE DA	Cambodia	1987	1994	general cargo/multi- purpose ship	Global Marine Bureau Inc.	Yantai Development Zone Fengyuan Shipping Co., Ltd.	26/01/04	02/02/04	ISM RELATED DEFICIENCIES: emergency preparedness, rescue boat manning not in muster list, maintanance of the ship and equipment, manual alarms not working, GMDSS officers not know emergency operation adn functional test of all GMDSS equipt., safety & job familiarization record not found, emergency preparedness, emergency drills not carried out, FIRE FIGHTING MEASURES: fire detection, heat/smoke detectors not installed according to approved fire control plan, readily availability of fire fighting equipment, portable foam bottles empty and foam nozzle couples not matching with fire hose couple, STABILITY, STRUCTURE AND RELATED EQUIPMENT: electric equipment in general, air vent for battery room blanked by insulation and closing flap without gasket & screw seized, hydraulic and other closing devices/watertight doors, fire door self-closing devices for bridge deck and E/R not working
13	9144158	HELENE RICKMERS	Marshall Islands	1997	16801	container ship	Germanischer Lloyd	Columbus Shipmanagement GmbH	29/01/04		RADIOCOMMUNICATIONS: reserve source of energy, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire fighting equipment and appliances

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.