Ships detained in Hong Kong by PSC Section in May 2004

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9237400	HARUKAZE	Cyprus	2000	4764	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Bell Shipmanagement Co., Ltd	04/05/04	04/05/04	SAFETY OF NAVIGATION: charts, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, STABILITY, STRUCTURE AND RELATED EQUIPMENT: ballast, fuel and other tanks
2	9134622	WEHR ALTONA	Marshall Islands	1997	16801	container ship	Germanischer Lloyd	Oskar Wehr Kg Gmbh & Co. Germany	05/05/04	05/05/04	RADIOCOMMUNICATIONS: maintenance/duplication of equipment, MF radio not working properly
3	8115332	ARABELLA	Cyprus	1981	14160	general cargo/multi- purpose ship	Lloyd's Register of Shipping	Pacific and Atlantic Corporation	06/05/04	07/05/04	SAFETY OF NAVIGATION: charts, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, readily availability of fire fighting equipment, LIFESAVING APPLIANCES: lifeboat inventory
4	9254757	WINNING RUN	Panama	2001	6381	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Chofuku Kisen Co., Ltd.	06/05/04	07/05/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, SAFETY OF NAVIGATION: charts, LOAD LINES: ventilators, air pipes, casings
5	8905957	VILLE DE MARS	Panama	1990	37235	container ship	Bureau Veritas	CMA-CGM, FRANCE	07/05/04	07/05/04	SAFETY OF NAVIGATION: charts, HK charts required for voyage not supplied, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, Master & new C/O without Panama licences, ISM RELATED DEFICIENCIES: resources and personnel, def. item no. 3, maintenance of the ship and equipment, def. item no. 2 & 4
6	7907116	TONG HO	Taiwan, China	1980	5890	other types of ship		Ta Ho Maritime Corporation	10/05/04	12/05/04	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, LIFESAVING APPLIANCES: inflatable liferafts, 2-way radiotelephone apparatus for survival craft, lifeboats, lifeboat inventory, SAFETY OF NAVIGATION: charts, signalling lamp, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, electric equipment in general, means of escape, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire pumps, LOAD LINES: ventilators, air pipes, casings, cargo and other hatchways, railing, cat walks, MARPOL - ANNEX I: oil discharge monitoring and control system, ALL OTHER DEFICIENCIES: deficiencies clearly hazardous to safety, health or environment, specified in clear text, 3 motor cycle with petroleum fuel found on board, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, ISM RELATED DEFICIENCIES: maintenance of the ship and equipment

7	8010764	BRILLIANT ZHEJIANG	Panama	1982	40796	bulk carrier	Lloyd's Register of Shipping	Zhejiang Ocean Shipping Co. Ltd.	11/05/04	11/05/04	SAFETY OF NAVIGATION: charts, LIFESAVING APPLIANCES: lifejackets lifeboats, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
8	8312435	NEW LUCKY III	Panama	1983	2669	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Shanghai Marukichi Shipmanagement Co. Ltd.	12/05/04	13/05/04	RADIOCOMMUNICATIONS: reserve source of energy, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, personal equipment, LIFESAVING APPLIANCES: lifeboat inventory
9	9137557	IMARI	Singapore	1996	18602	container ship	Nippon Kaiji Kyokai	Sandigan Ship Services, Incorporated	13/05/04	13/05/04	SAFETY OF NAVIGATION: charts, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, fire fighting equipment and appliances
10	8605117	CHUN HE	Saint Vincent and the Grenadines	1986	1215	general cargo/multi- purpose ship		Dalian Chun An Ship Management Co. Ltd.	13/05/04	14/05/04	ISM RELATED DEFICIENCIES: resources and personnel, FIRE FIGHTING MEASURES: personal equipment
11	7640378	RYONG GANG 2	North Korea	1980	9027	general cargo/multi- purpose ship	Korea Classification Society DPR	Taedong Sonbak Company Ltd.	20/05/04	24/05/04	ISM RELATED DEFICIENCIES: resources and personnel, SAFETY OF NAVIGATION: nautical publications, LIFESAVING APPLIANCES: lifeboat inventory, RADIOCOMMUNICATIONS: reserve source of energy, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, personal equipment
12	9232981	ARTUS	Antigua and Barbuda	2000	6385	container ship	Germanischer Lloyd	Kapitan Manfred Draxl Schiffahrts GMBH & Co. Kg, Germany	21/05/04	21/05/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, 2/E without flag state licence since 9/2003
13	8301292	WIN BRIGHT	Malta	1983	5464	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Winland Shipping Co., Ltd., Dalian, PRC	24/05/04	28/05/04	FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, system not inspected/certified for compliance, readily availability of fire fighting equipment, air receiver for shutting F.O. quick closing valves not charged to working pressure, LIFESAVING APPLIANCES: maintenance and inspection, lifeboat davits/winches without dynamic load test, STB'D lifeboat propulsion system not reliable for ahead and astern motions; engine running very smoky, ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, pressure test of CO ₂ bottles overdue, resources and peronnel, all crew without medical certs certified fit for work as seafarer, operation and risk to operate the CO ₂ system not familiar/identified by responsible crew, def. item no. 1, 2, 3, 7, 9, 10, 13, 15, 16 & 17, def. item no. 11 & 12, RADIOCOMMUNICATIONS: maintenance/duplication of equipment, no routine test to GMDSS equipt, reserve batteries not maintained, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, GMDSS officers not familiar with test of equipt, cancellation of false distress alerts not known to GMDSS officers

14	7408940	PELA 1	Malta	1975	8647	container ship		PT Pelayaran Tirtamas Express	28/05/04	29/05/04	LIFESAVING APPLIANCES: lifejackets, FIRE FIGHTING MEASURES: personal equipment, other (fire safety), engine room was dirty and was fire risk in way of main engine leakage and fuel oil transfer pump leakage, fire fighting equipment and appliances
----	---------	--------	-------	------	------	----------------	--	----------------------------------	----------	----------	---

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.