## **Ships detained in Hong Kong by PSC Section in June 2004**

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8627763	MIDAS-1	Belize	1985	1300	general cargo/multi- purpose ship	Inclamar	Dalian Chun An Ship Management Co., Ltd.	03/06/04	03/06/04	FIRE FIGHTING MEASURES: personal equipment, ventilation, fire-dampers, valves, quick closing devices, means of control, LOAD LINES: ventilators, air pipes, casings
2	8714657	KAPITAN GRISHIN	Cyprus	1988	6030	general cargo/multi- purpose ship	Det Norske Veritas	Unicom Management Services (Cyprus) Ltd.	07/06/04	07/06/04	SAFETY OF NAVIGATION: other (navigation), containers loaded on board disturbed/affected ship's visibility, LIFESAVING APPLIANCES: lifebuoys
3	9133575	BENNY	Panama	1995	4667	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Hansen Shipping Agencies Co., Ltd.	07/06/04	07/06/04	RADIOCOMMUNICATIONS: reserve source of energy, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
4	7810894	OCEAN STARLIGHT	Liberia	1979	29873	container ship		Yangming Marine Transport Corporation	07/06/04	07/06/04	FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, ventilation, fire-dampers, valves, quick closing devices, means of control, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, ALL OTHER DEFICIENCIES: deficiencies clearly hazardous to safety, health or environment, specified in clear text, oil found attached on the funnel, LIFESAVING APPLIANCES: inflatable liferafts
5	7909164	BU GANG	North Korea	1979	2982	general cargo/multi- purpose ship		Korea Rungrado Shipping Co Ltd, Korea	08/06/04	10/06/04	SAFETY OF NAVIGATION: charts, using obsolet charts, nautical publications, no tide table, list of lights, LIFESAVING APPLIANCES: lifebuoys, bridge, P&S lifebuoys and smoke signal was not connected, emergency equipment for 2-way communication, portable GMDSS VHF 3 spare batteries were expired, lifeboat inventory, P'side lifeboat has no sail, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, P' E/R fan vent flapper cannot be closed, STABILITY, STRUCTURE AND RELATED EQUIPMENT: means of escape, steering room emergency escape was blocked by steel pipes, MOORING ARRANGEMENTS (ILO 147): anchoring devices, P&S anchor chains were not properly secured
6	9114787	MEKONG PIONEER	Antigua and Barbuda	1995	3833	container ship	Germanischer Lloyd	Jungerhans Maritime Services GmbH & Co KG	08/06/04	08/06/04	LIFESAVING APPLIANCES: line throwing appliance, distress flares

7	8403076	AI PU SHUN	Belize	1984	6116	general cargo/multi- purpose ship	China Corporation Register of Shipping	Dalian Tongyuan Shipping Agency Co., Ltd., Dalian, China	09/06/04	09/06/04	ISM RELATED DEFICIENCIES: resources and personnel, crew medical certificates, RADIOCOMMUNICATIONS: other (radio), ITU publications outdate/not supplied, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, GMDSS officers not familiar with operation of GMDSS equipment
8	8303329	MALAYSIA STAR 1	Antigua and Barbuda	1983	9678	container ship	Germanischer Lloyd	BBC Burger Bereederungs Contor GmbH & Co. KG	09/06/04	09/06/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, SAFETY OF NAVIGATION: charts, FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, ventilation, fire-dampers, valves, quick closing devices, means of control, MARPOL - ANNEX I: oil filtering equipment, SHIP'S CERTIFICATES AND DOCUMENTS: document of compliance (DOC/ISM Code)
9	7906930	ATHANASSIA	Cyprus	1980	16260	general cargo/multi- purpose ship	Registro Italiano Navale	Technomar Shipping Inc	10/06/04	10/06/04	SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, lifeboat drills overdue, FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, one drain pipe missing
10	8017695	SANG THAI RADIUM	Thailand	1980	2974	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	Sinsimon Navigation Co. Ltd.	14/06/04	15/06/04	LIFESAVING APPLIANCES: lifeboat inventory, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, personal equipment
11	8811106	XIANG HE	Belize	1988	1311	general cargo/multi- purpose ship	Isthmus Bureau of Shipping	Dalian Chun An Ship Management Co., Ltd.	16/06/04	16/06/04	STABILITY, STRUCTURE AND RELATED EQUIPMENT: means of escape
12	8909082	YM QINGDAO I	Panama	1989	15122	container ship	Nippon Kaiji Kyokai	Eurobulk Ltd.	16/06/04	16/06/04	FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, emergency fire pump was opened up in port, PROPULSION AND AUXILIARY MACHINERY: bilge pumping arrangements, emergency filge suction in engine room seized
13	8976190	QI SHUN	Cambodia	1983	3355	general cargo/multi- purpose ship	Globe Marine Bureau	Dalian Tongyuan Shipping Agency Co., Ltd	17/06/04	22/06/04	FIRE FIGHTING MEASURES: fire pumps, personal equipment, LIFESAVING APPLIANCES: lifeboat inventory, SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, ISM RELATED DEFICIENCIES: maintenance of the ship and equipment
14	8510738	BOW MARINO	Singapore	1986	8003	chemical tanker	Lloyd's Register of Shipping	Odfjell Asa, Bergen, Norway	21/06/04	21/06/04	LOAD LINES: freeboard marks, RADIOCOMMUNICATIONS: other (radio), ITU publication outdate/missing, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, pump room halon release alarm not working

15	8921872	ORIENTAL GLORY	Belize	1990	2992	general cargo/multi- purpose ship	China Corporation Register of Shipping	Fu Sheng Shipping Safety Management Consultant Co., Ltd., Taiwan	21/06/04	21/06/04	SAFETY OF NAVIGATION: charts, using obsolete chart, BA chart not corrected up-to-date
16	7507241	KAMNIK	Singapore	1976	12117	general cargo/multi- purpose ship	Lloyd's Register of Shipping	Splosna Plovba Ltd	21/06/04	23/06/04	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: other (STCW), chief engineer cannot speak and read english, he cannot communicate with Master of the ship, STABILITY, STRUCTURE AND RELATED EQUIPMENT: bulkheads - cracking, FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control
17	7712640	GOLDEN WEALTH	Panama	1978	12137	bulk carrier	China Corporation Register of Shipping	Fuh Feng Lines Co. Ltd	23/06/04	26/06/04	SAFETY OF NAVIGATION: charts, using obsolete charts, SOLAS RELATED OPERATIONAL DEFICIENCIES: bridge operation, no passage plans for 2 recent voyages, abandon ship drills, both P' & S' lifeboats were found not lower into water and manoeuvring within last 3 months, RADIOCOMMUNICATIONS: MF/HF radio installation, MF/HF set is out of order
18	7823621	MARRIOTT INTERNATIONAL	Cambodia	1979	3310	oil tanker	Global Marine Bureau Inc.	Prime Cosmos Limited, Hong Kong	23/06/04		LIFESAVING APPLIANCES: maintenance and inspection, P&S lifeboats, STABILITY, STRUCTURE AND RELATED EQUIPMENT: damage to hull due to weather or ship operation, stern shell structures crushed and indented, P. shell plating I.W.O. emergency fire pump room holed and drain hole open, bulkheads - corrosion, boat deck house casing wasted & holed, enhanced programme of inspection, no program established, CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: certificates for Master and officer, 2/E temp. Cambodia licence expired, RADIOCOMMUNICATIONS: other (radio), ITU publications outdate, MARPOL - ANNEX I: control of discharge of oil, saveall for L.O./settling tank air pipes wasted & holded, OIL, CHEMICAL TANKERS AND GAS CARRIERS: cargo vent system, vent valve hand wheel for S. aft slop tank broken, FIRE FIGHTING MEASURES: readily availability of fire fighting equipment, suction valve for emerg. fire pump seized, air bottle for a B.A. set emply, MARPOL - ANNEX II: P & A manual, not approved, SOLAS RELATED OPERATIONAL DEFICIENCIES: operation of GMDSS equipment, operation of GMDSS equipt. not known to responsible crew, ISM RELATED DEFICIENCIES: documentation, no record of safety and duty familiarization for crew, no record of Master review, int. & ext. audit since change of management in 01.2004, resources and personnel, Master not conversant to the SMS manual
19	7632852	DUCKY SINCERE	Panama	1976	14294	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	TMT Co. Ltd.	23/06/04	30/06/04	FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, ventilation, fire dampers, valves, quick closing devices, means of control, MARPOL - ANNEX I: oil filtering equipment, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room
20	8909587	LONG BIEN	Vietnam	1989	5506	general cargo/multi- purpose ship	Viet Nam Register of Shipping	Northern Shipping Company	28/06/04	30/06/04	SAFETY OF NAVIGATION: charts, LIFESAVING APPLIANCES: distress flares, lifeboat inventory, FIRE FIGHTING MEASURES: jacketed piping system for high pressure fuel lines, personal equipment

21	7519426	VALERIA	Liberia	1976	14003	general cargo/multi- purpose ship	Nippon Kaiji Kyokai	NYK Shipmanagement Pte Ltd.	28/06/04	29/06/04	LIFESAVING APPLIANCES: lifeboat inventory, LOAD LINES: ventilators, air pipes, casings, covers (hatchway-, portable-, tarpaulins, etc.), FIRE FIGHTING MEASURES: ventilation, fire-dampers, valves, quick closing devices, means of control, jacketed piping system for high pressure fuel lines
----	---------	---------	---------	------	-------	--------------------------------------	---------------------	--------------------------------	----------	----------	---

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.