

Ships detained in Hong Kong by PSC Section in October 2006

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8713380	SEA TAXI -1	Panama	1988	1250	general cargo/multi-purpose ship	Isthmus Bureau of Shipping	Isthmus Bureau of Shipping	Dalian Chun An Ship Management Co, Ltd.	03/10/06	04/10/06	RADIOCOMMUNICATIONS: facilities for reception of marine safety information/navtex printout unreadable
2	8014203	OIL AMBASSADOR	Panama	1980	12758	oil tanker	International Register of Shipping	Isthmus Bureau of Shipping, International Register of Shipping	China Chance Shipping Ltd	16/10/06	19/10/06	SAFETY OF NAVIGATION: nautical publications, LIFESAVING APPLIANCES: lifebuoys, FIRE SAFETY MEASURES: fire-dampers, emergency fire pump
3	8922436	KANG NAM-1	Korea, Democratic People's Republic	1989	702	general cargo/multi-purpose ship	Korea Classification Society (former Joson CS)	Korea Classification Society (former Joson CS)	Korea Kumrung Trading Co Ltd	23/10/06	03/11/06	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: other (STCW)/all crew's medical fitness examination certificate were not available, LIFESAVING APPLIANCES: rescue boats, lifebuoys, distress flares, line throwing appliance, emergency equipment, SHIP'S CERTIFICATES AND DOCUMENTS: logbooks/compulsory entries, SAFETY OF NAVIGATION: magnetic compass, lights, shapes, sound-signals, charts, nautical publications, echo-sounding device
4	7913127	YANG YUAN	Panama	1980	7188	general cargo/multi-purpose ship	Isthmus Bureau of Shipping	Isthmus Bureau of Shipping	Yang Chun (HK) Ocean Shipping Company Limited (Shandong Branch Office)	24/10/06	24/10/06	SAFETY OF NAVIGATION: nautical publications/list of lights and fog signals, NP 79, volume F was not found on board, nautical publications/sailing direction, NP 32 China sea pilot, vol. III, was not found on board, charts/only 2 charts (no. 4129 and 4121) for Hong Kong were found on board, FIRE SAFETY MEASURES: emergency fire pump/emergency fire pump was not working, fixed fire extinguishing installation/certificate/report for maintenance of fixed CO cylinders/system was not available, SOLAS RELATED OPERATIONAL DEFICIENCIES: maintenance of life saving appliances/certificate for inspection and maintenance of liferafts were not available
5	8005886	PACIFIC LEADER NO. 1	Panama	1980	12923	bulk carrier	Panama Maritime Documentation Services	Panama Maritime Documentation Services; Panama Shipping Registrar Inc.	Kangjin Ship Management Co., Ltd. Room 404, Songnam Bldg., 76-1, 4Ka Chungang-dong, Chung-ku, Busan, Korea	26/10/06	31/10/06	SAFETY OF NAVIGATION: charts, RADIOCOMMUNICATIONS: MF/HF radio installation, LIFESAVING APPLIANCES: launching arrangements for survival craft (Panama Maritime Documentation Services), FIRE SAFETY MEASURES: fire prevention
6	8626006	KANG NAM 5	Korea, Democratic People's Republic	1984	1135	general cargo/multi-purpose ship	Korea Classification Society (former Joson CS)	Korea Classification Society (former Joson CS)	Korea Kumrung Trading Co Ltd	26/10/06	Not yet release	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: other (STCW)/all crew's medical examination certificates were not available, LIFESAVING APPLIANCES: maintenance and inspection/inflatable liferafts inspection/maintenance certificates/reports were not available, emergency equipment for 2-way communication/2 sets of 2-way radiotelephone apparatus (VHF) were not working, 3 sets of batteries were not available, SAFETY OF NAVIGATION: nautical publications/nautical publications were not available, e.g. ITU publications, IAMSAR manual vol. III, radio signals, sailing direction, list of lights and fog signals, notice to mariners, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches/emergency light system was not working (light bulbs of emergency lights were missing, battery was not available)

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.